

Sept. 1909

C.E. Roberts

✓ $\frac{1}{4}$ Cor. Bet. Secs. 28 & 33 (F.B. No. 10 Page 51)

✓ No tree in Sec. 28

✓ W. Fir 32 in N. $20\frac{1}{4}^{\circ}$ W. 168 lks.

R. " 30 " N. $15\frac{1}{4}^{\circ}$ E. 144 $\frac{1}{2}$ "

C.E. Roberts

✓ Cor. Secs. 28-29-32-33 T. 31 S. R. 3 W. (F.B. No. 10 Page 51)

✓ Fir 12" S. $76\frac{3}{4}^{\circ}$ E. 31 lks.

✓ " 12" S. $32\frac{1}{2}^{\circ}$ W. 59 "

G.J. Wenduth

August 1942

✓ Cor. Secs. 32-33-4-5 T. 31 S. R. 3 W. + T. 32 S. R. 3 W.

✓ found one B.T. standing 34" Fir S. 34° W. 34 ft.

also found scrib mark "T" on old rotted Laurel stump
N. 45° E. 39 ft. Set two new B.T.

28" Fir N. $72^{\circ}04'$ E. 30 ft.

15" Fir N. $31^{\circ}36'$ W. 63 ft. Set a 1" x 33" Bolt.

G.J. Wenduth

Aug. 1942

✓ $\frac{1}{4}$ Cor. bet. Sec. 31 + 32

found Cedar B.T. S. 48° W. 29 ft. still standing and
Pine stump in place but rotted no marks showing.
Set $\frac{3}{4}$ " I.P. for Corner and mark new tree for B.T.

12" Cedar N. $79^{\circ}15'$ E. 38 ft.

G.J. Wenduth

Aug. 1942

✓ Cor. Secs. 31-32-5-6, T. 31 S. R. 3 W. + T. 32 S. R. 3 W.

found B.T. S. 22° E. 59 ft. standing also Pine stump
marked B.T. N. 80° E. 47 lks instead of 117 lks. also Pine
stump S. 30° W. approx. 30 lks had been uprooted no marks.

Set 1" Iron rod 2 ft. long for Cor. also new B.T.

14" Fir N. $57^{\circ}10'$ W. 140 ft.

31-3

W. W. W. W. W.
August 1942

✓
 ✓ 1/4 Cor. South side Sec. 32 T. 31 S. R. 3 W.
 No B.T. found So run line bet. S.W. & S.E. Cor. and
 set 1/4 Cor. equal dist. from each.
 Set 1" Iron Pipe 30" long and 2 New B.T.
 7" Chinquapin S. 47° 24' E. 92 ft.
 10" Fir. N. 47° 40' W. 339 ft.