

Buss Survey  
W.S. Clear  
Geo. Montgomery } witnesses

Witness Corner to 1/4 Sec. Cor. 15-16 True corner falls in Elk Creek. Set boulder 6"x8"x12" marked with X and 1/2" x 24" pipe driven alongside for witness corner

Scribed 18" fir 524°45'E 60 lks WC 1/4 S 15 CS BT  
36" " 578°15'W 216 " " 516 "

This W.C. is 156 lks <sup>50°22'E</sup> south of true corner and on the west line of Sec. 15.

1/4 Sec. Corner between Secs. 12 & 13

Identified by a 4" cedar post as set by Surveyor Thiel and the O.B.T. a 36" leaning Fir N14°E 33 lks. I did not chop out this B.T. as there was no doubt as to its being the O.B.T. Remarked this tree in bark and 1/4 S 12 - CS - BT Also marked a 16" W. Oak for a BT South 94<sup>8</sup> ft. 1/4 S 13 - CS - BT.

April 16-17-1928  
Buss Survey Deputy Co Surveyor  
P. Irving  
Jesse Widely } witnesses

1/4 Sec. Corner between Secs 13+14

Identified by a plain sandstone rock set by Thiel and an O.B.T. a 32" B. Oak. This oak had been chopped out and John Clayton the owner of adjoining property testified that when Thiel chopped out the tree scribe marks were visible. Fir bearing tree gone but found old stump burned off level with ground which checked both bearing and distance. Rechecked the rock 6'x10'x15" with a X and 1/4 Scribed New BT's a 15" fir N81°E 55° ft. 1/4 S 13 - CS - BT.  
a 36" " 560°12'W 266 ft. 1/4 S 14 - CS - BT.

1/4 Sec. Cor. between Secs. 13+24.

I identified the location of this corner by the remains of an O.B.T. now a rotted snag. 8' high. Marks B.T. reverse visible where it had grown into original scribe marks.

drove a 3/4" x 36" pipe for this corner at proper location from this tree. Surrounding pipe with a mound of stone.

Scribed new BTs. a 15" Fir N47°30'W 92<sup>8</sup>ft. 44513CSBT  
20" " S16°E 145<sup>9</sup>ft 44524CSB<sub>2</sub>

S.W. Cor. Thos. Stillwell D.L.C. #45

I identified this corner by a fir post set by surveyor Thiel also on. Orig. BT S10°W 15 lks. Scribe marks visible in the bark. A ~~tree~~ snag bears S15°E 30 lks. This snag has been so badly burned that all marks are obliterated. It appears from location however to be the other DBT. Set a 3/4" x 36" pipe 30" in the ground for the corner. Remarkd DBT S10°W 15 lks Also a 30" Fir N18°E 5 lks which had been previously marked by someone unknown.

NW Exter. Corner. Thos Stillwell DLC #45

I identified this location from an original BT. bearing proper scribe marks. This ~~tree~~ is a 50" fir which I chopped down to find the scribe marks. I set a 3/4" x 36" pipe 34" in ground for corner. N80°E 26 lks. from this orig. BT.

Scribed a 14" Fir S80°W 73 lks 7225R6W C145CSBT. as a new BT. Also remarkd a 14" fir S84°E 82 lks. CS. This tree had been scribed about 30 years ago by someone but not recorded.

N.W. Inter. Cor Thos Stillwell DLC #45

I identified the location of this corner by both Original BTs alive and standing. Scribe marks visible  
(see p 190)

April 16-19 incl  
Bentley Deputy County Surveyor  
R L Irving }  
Jas Waddy }  
Witnesses