

T 29 S. R. 6 W.

Jan. 10-1913

Frank Cairn

1/4 Sec. Bet. Secs. 17 & 20 F. Book 33
 W. Oak post 4" x 4" x 3 1/2' marked 1/4 S. CS.
 ✓
 ✓
 #52
 Fir 12" S. 2° 30' E. 28 lks
 " 24" N. 26 1/4 W. 45 "

Mench

1/4 Cor. Bet. Secs. 19-20 F. Book 33
 ✓
 #53
 A Fir 4" marked 1/4 S From which
 A Chincapine 10" N. 50 1/2° W. 27 lks
 Fir 8" S. 52 1/2° E. 56 1/2 "

#54

1/4 Cor. Bet. Secs. 4-9 F. Book 37
 Set pointed rock 7x8x14
 Both original trees in place

#55

1/4 Cor. Bet. Secs. 8 & 17 F. Book 33
 ✓
 See Pg. 199
 Feb-Mar-1940
 Trees do not fit notes. Set post N. 30° E 25 lks
 (from) 18" Oak and remark same. Find Oak
 N. 72° E. 66 feet. I mark a Fir 40" N. 3° W. 75 lks.

June 3-1915

N.E. Cor. Stephen D. Willis DLC. 41 (F.B. 37 Page 46)
 ✓
 #56
 Oak post marked C. 41 - CS.
 W. Oak 7" S. 10° W. 8 lks.
 " 7" N. 37° E 13 "

~~1/4 Cor. Bet. Secs. 26-27 F.B.~~

Mar. 9-1917

1/4 Cor. Bet. Secs. 19-20 (F.B. 44-P. 27)
 ✓
 #57
 A 4" Fir marked by New Govt. Survey From which
 Chinkapin 8" N. 47 3/4° W. 27 lks.
 Fir 8" S. 51 1/2° E. 37 "

F.C. Frear

Cor. Secs. 19-20-29-30
 ✓
 #58
 Large Rock set by New Govt. Survey from which
 Madrone 18" N. 76 1/2° W. 58 lks.
 Fir 18" S. 31° E. 62 1/2 "

Fir 12" S. 20 3/4° W. 49 Lks

" 24" N. 19 1/2° E. 17 "

✓ 1/4 Cor. Bet. Secs. 19-30

Large Rock set by New Govt. Survey from which

✓ A Madrone 30" S. 4° E. 32 Lks.

" " 12" N. 72 1/4° E. 25 1/2 "

#59

✓ Sec. Cor. 1-2-11-12 Reestablished.

Found B.O. stump marked B.T. facing N.E.

✓ Recognized as B.T. described S 65° W 62 links

Other Trees obliterated. measured N 65° E

62 links set stake marked C.S. Buried

1 1/4" x 6" x 8" iron plate. Marked

W. Oak. 14" Dia. N. 71° 15' W 182

W. Oak. 32" Dia. S. 53° 30' W 454

B. Oak. 32" Dia. S. 6° E 375

B. Oak. 22" Dia. N. 18° 30' E 342

Feet
Links

F.B. 57
P 75

#60

✓ 1/4 Cor. bet. Sec's. 15 & 22. re establishd. from orig. (2) B.T.'s which are badly decayed & hollow. Set 5/8" Iron Bolt 36" lg., nut on top,

beside a 15" W. Fir which is blazed. Marked following 2 Trees,

24" Fir (bark blaze) N. 44 1/2° W. 18.0'

8" " S. 4 1/2° E. 25.5'

✓ S.E. Cor. D.L.C. 41, (Stephen Willis) re established from stump of orig. Oak B.T.

Set Ford rear axle shaft, pinion gear attached, from which,

24" Cedar, S. 35° W., 43.2' near R. bank creek

22 W. Fir, S. 5° E., 47.3'

✓ #63 NE. Cor. Lot 3, which is also NW Cor. Lot 2, Sec. 15 as agreed to in signed statement by the two (all) interested propty. owners

set 1x30" Auto axle fr. which 8" Fir; brs. N. 54° W. 16.0' - 9/11 6" Myrtle
Mkd C.S. B.T. on side hill abt 100' W. of County Road

Arthur Boyer, D.C.S. }
Hub set Mar 10, 1937 }
Auto Axle set July 13 " }
At point where hub was prev. set }
Witnesses
N.E. Richardson, Victor Phipps }
Ruben L. Moore 9/11 Geo. F. Stephens. }
Wits.

Mar 10, 1937

Mar 8, 1937

#61

#62

Victor Phipps }
Jim Nichols }
N.E. Richardson }
by Arthur Boyer, D.C.S. }
Wits.
July 13, 1937