

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 1 E R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

E. C. Grant
D. W. P. & J. C. Transit.
8/12/57
C. S. File #42/328

Renewal of Corner to Sections 26, 27, 34, & 35, T25S., R1E.

From reference points set by Art Evans.

Set $\frac{3}{4}$ " Steel Rod below surface of Road, from which:

Marked 40" Fir T25S, R1E., S34 2807. S 83° 10' W 200.0 ft *
Marked 8" Fir T25S, R1E, S27. N 87° 30' W 235.5 ft

No other trees suitable for marking.

Note: See Sketch in C.S. File.

* Added 11-17-97 DCSO JC

1

D. G. Heuschkel
For Forrest Alberti
Nov. 24, 1958
C. S. File No. 42/405

Section Corner to Sections 15, 16, 21, & 22.

This corner was a 12" Hemlock which had been tied to a cutting unit boundary by Forest Service surveyors. Although marked to be saved, the tree was destroyed during logging. The Forest Service admin. present then placed a temporary metal pipe in the stump hole. The logger, Mr. Alberti confirmed the location. Blazes still exist intercepting the stump hole from all directions.

A Wild Theodolite was used in reestablishing the corner.

A Pipe 2" in diam. & 42" long marks the corner. From it:

A Pipe 2" by 25" bears N 32° 7' W. a distance of 13' 7"

A Pipe 1 $\frac{1}{2}$ " by 28" bears N 57° 32' E a distance of 13' 1";

A Pipe 1 $\frac{1}{2}$ " by 24" bears S 66° 6' E a distance of 14' 2";

a Pipe 2" by 28" bears S 58° 16' W a distance of 18' 5".

2

Closing Corner

T 25 S R 1 W

S 36

T26-R1W S 1/S 31 T25 $\frac{1}{2}$ -1E

Found - 2" I. Pipe & 1928 GLO Brass Cap attached, properly mkd.

18", now 26" Fir S. 38° E. 71.9 ft., shows very good scar,

Tree alive, we do not open

Orig. 36", now 48" badly rotted Fir Stump, S. 31° W. 48.2 ft.,

shows frag. scribe marks "T2" on shattered blaze.

New BT: 15" Pine S. 64° W. 23.6 ft. mkd. T26S R1W S 1 CC CS BT.

Note - Corner lies on steep, south, slope, approx. 140 ft. East of shallow ravine, course SE.

3

Closing Corner to Secs. 19 & 30, T25-R1E.

Found - 1927 GLO Brass Cap, properly mkd., slightly bent over.

16" Fir, now 24" Stump, 5' high, N. 64° E. 84.5 ft., shows good scar. Do not open.

10", now 14" Fir, S. 62° E. 7.3 ft. Alive, shows good scar.

New BT: 20" W. Fir N. 45° E. 8.4 ft. mkd. T25S R1E S19 CC CS BT.

Note - This corner lies approx. 164 ft. S. of the Sec. Cor. of Secs. 24 and 25, T25-1W. on moderate S. slope.

4

Vernone "Ray" Tracy
Jack Heritage & E. West
October, 1966
C. S. File No. 52/30

Sec. Cor. to Sections 24 and 25 only, T25-1W.

Found - 1927 GLO Brass Cap, properly mkd.

Orig. 28", now 36" W. Fir, S. 14° W. 71.9 ft. (not S. 18° W.) shows scribe marks on unhealed blaze. Alive.

Orig. 48", now 53" Fir, dead & shattered, N. 18° W. 23.8 ft., scribe marks visible on face & reverse on overgrowth.

New BT's: 8" W. Fir S. 56° W. 11.2 ft. mkd. T25S R1W S25 CS BT.

8" D. Fir N. 12° W. 46.4 ft. mkd. T25S R1W S24 CS BT.

Note - This corner lies on southerly slope, approx. 360 ft. S. of top of spur & approx. 164 ft. N. of C.C. of Secs. 19 & 30, T25-1E.

5

$\frac{1}{4}$ Corner to Section 25 only, T25-1W.

Found - 1927 GLO Brass Cap, properly mkd., badly bent & nearly out of the ground. We straighten and Reset.

Orig. 36", now 40" Fir Snag, S. 60° W. 20.5 ft., very good scar. Do not open.

6", now 10" Fir N. 65° W. 34.3 ft., Alive, shows good scar. Do not open.

Orig. Basalt Stone, showing " $\frac{1}{4}$ " chisel marks.

New BT: 9" D. Fir S. 10 $\frac{1}{2}$ ° W. 23.7 ft. mkd. $\frac{1}{4}$ S25 CS BT.

Note - This cor. lies on moderate, changing to steep, W. Slope and approx. 125 ft. N. of the $\frac{1}{4}$ corner of Sec. 30, T25-1E.

6