

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 1 E. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

18

1/4 Corner to Section 6 only, T25S-R1E.

Found - 1927 GLO Brass Cap set in mound of stone & properly mkd.  
16", now 18" Fir N. 29° E. 19.8 ft., prev. opened &  
scribe visible, Alive. Rescribe above old blaze:

" 1/4 S 6 CS BT".

24", now 28" Fir, S. 42° E. 23.8 ft., shows good scar,  
we do not open. This BT. is directly behind a 36" D. Fir  
from Brass Cap.

New BT: 18" D. Fir S. 9° E. 12.0 ft. mkd. 1/4 S 6 CS BT.

Note - This corner lies approx. 125 ft. S. of new logging road &  
approx. 180 ft. S. of 1/4 Cor., Sec. 1, T25-1W.

19

1/4 Corner to Section 7 only, T25-1E.

Found - 1927 GLO Brass Cap mkd. "1/4 S7", firmly set.

24", now 26" Fir with top broken out, N. 46° E. 46.9 ft.  
Alive, shows good scar. We do not open.

50", now 52" Fir, uprooted & out of position, S. 51° E. 42.9 ft.

New BT's: 51" D. Fir Stump S. 78° E. 27.2 ft. mkd. 1/4 S7 CS BT.

44" D. Fir Stump N. 2° E. 14.0 ft. mkd. 1/4 S7 CS BT.

Note - This corner lies approx. 60 ft. S. of cutting corner in  
clear cut unit & approx. 146 ft. S. of 1/4 Cor. S12, T25-1W.

20

1/4 Corner to Sections 12 only T25-RLW.

Found - Stone mkd. "1/4 S12" on W. face.

Orig. 16", now 21" Fir Stump, N. 40° W. 35.8 ft., shows  
good scar. We do not open.

30", now 36" Fir Stump, S. 21° W. 44.2 ft. (not 39.6 ft.)

Open & find reverse scribing.

Orig. 36", now 42" Fir, N. 63° E. 11.9 ft., shows scar,

recorded as marks obliterated. Alive, we use as reference only.

Set - Brass Cap at Cor. Mkd: County Surveyor's T25S RLW 1/4 S12 R1E  
Office, 1966

New BT: 23" D. Fir N. 78° E. 24.9 ft. mkd. 1/4 S CS BT.

No trees available to W. of line due to logging.

1/2" Steel Pin with 1" Alumin. Cap mkd. "Prop. Cor",

See Ren. #57, bears S. 48° E. 1.5 ft.

(T25-1W)

21

Sec. Corner to Sections 17 - 18 - 19 - 20.

Found - Orig. Corner Tree, 10", now 11" Fir with scars on  
appropriate side, Now Snag.

Orig. 8", now 14" Fir, Alive, N. 65° W. 5.3 ft., shows good scar.

Orig. 10", now 13" Fir, shattered Stump, S. 53° W. 58.7 ft.,  
reverse scribe.

Orig. 10", now 14" Fir Snag, N. 35° E. 16.5 ft., shows good scar.

No trace of S.E. BT.

Set - Brass Cap on S. Side of Corner Tree 1 ft. from center mkd:

County Surveyor's	T 25 S	R 1 E
Office	S 18	S 17
1967	S 19	S 20

New BT's: 10" Fir S. 76° W. 57.7 ft. mkd. T25S R1E S19 CS BT.

6" Fir S. 77° E. 30.8 ft. mkd. T25S R1E S20 CS BT.

8" Fir N. 66° E. 15.8 ft. mkd. T25S R1E S17 CS BT.

Note - This corner lies on very steep, SW slope, 50 ft. S. of logging road.

April 6, 1967

22

1/4 Corner to Section 31 and 32.

Found - 1927 GLO Brass Cap, properly mkd, but almost out of ground.

Reset - Brass Cap in mound of Stone from one Orig. BT:

12"?, now 50" Pine, N. 14 1/2° E. 304.3 ft., Alive, shows  
very good scar. Do not open. No trace SW BT.

New BT: 12" D. Fir S. 34° W. 74.2 ft. mkd. 1/4 S31 CS BT.

Note - This corner on precip. SE. rock slope approx. 300 ft. S. of timberline.

March 24, 1967

Vernon "Ray" Tracy  
Jack Heritage & E. West  
November, 1966  
C. S. File No. 52/30

RE-RENEWED CORNER NO. 57

RE-RENEWED CORNER NO. 58