

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 25 T. S. R 1 E E
R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 97101

Dennis Gaylord
U. Forest Service
April 1, 1979
C 60/24

Glenn Baughman
For: U.S. Forest Service
Sept. 1980
C.S. 58/229

Glenn Baughman, LS 536
For: U.S. Forest Service
Sept. 1980
C.S. 58/229

40

Closing corner for SEcs. 2 and 1 only.

Found - 2" Iron pipe firmly set & protruding 14" above ground. A 2 1/2" brass cap attached to the pipe is marked: U.S.G.L.O. survey R1E T24S S35 C C S2 S1 T25S R1E 1928.
A 37" D. Fir bears S.63°E., 36.3 ft. & has a single healed blaze.
A 28" D. Fir bears S.26°30'W., 29.7 ft. & has a single healed blaze.

U.S.F.S. bearing tree signs were placed on both BT's and they were painted with a band of red paint. No new Accessories. The corner 35 S36 bears N.89°30'E., 57.3 ft. (Rec. N.89°02'E., 0.86 chs.) S 1
Corner lies 5 ft. north of F.S. Road #2512.

4/19/79

41

Closing Corner for Secs. 6 and 7 only.

Found - 1927 U.S. GLO brass cap, properly marked, on a 2" iron post firmly set, 10" above the ground. (C.S. Vol. 21 Pg. 9120)
21" D. Fir, orig. with healed blaze, bears N.6°E., 6.6 ft.
24" wind fallen D. Fir, orig., with healed blaze bears S.17°E., 49.5 ft.

New BT - a 11" D. Fir bears S.7°E., 42.7 ft. marked "T25S., R1E S7 CC BT" on a double blaze with a brass washer stamped "LS 536" nailed into lower blaze.

9/80

42

Section corner for Sec. 31; and Sec. 36 of T.25-1W. (Twsp. corner)

Found - 18"x12"x8" basalt stone with 6 notches in the north, south, east and west faces. Stone was laying on top of the ground.
A 62" D. Fir, orig. bearing tree, with healed blaze bears S.36°E., 47.5 ft. (Scribe marks destroyed in 1927 resurvey).
A 28" D. Fir, orig. BT, with healed blaze bears S.11 1/2°E., 30.0 ft. (Rec. 33.0 ft.) (Scribe marks destroyed in 1927 resurvey)
A 45" D. Fir, orig. BT, with healed blaze bears N.54 1/2°W., 52.8 ft.
A 22" D. Fir, orig. BT with healed blaze bears N.67 1/2°E., 56.8 ft.
A 24" Cedar (not of record) with healed blaze bears N.32°E., 30.1 ft.
Set - At the corner point A 2 1/2" x 30" iron pipe, 6" in the ground on bedrock in concrete, and in a 3 ft. diam. mound of stone, 3 ft. high with a 3" brass cap projecting 12" above the mound of stone and marked: "T25S R1W S 36 R1E S 31 T25 1/2S R1E S31 1980"

9/80

43

1/4 Corner for SEc. 36 only of T.25-1W

Found - A 1966 County brass cap properly marked. Ren. #7
A 50" D. Fir stump, Orig. BT, with scribe mark "4" visible, bears N.80 1/2°W.- 28.4 ft.
A 8" D. Fir snag, with scribe marks "1/4 S36 CS BT" visible on an unhealed blaze bears S.89°W., 12.9 ft.
A 24" Hemlock snag, with scribe marks "1/4 S36 CS Bt" visible on an unhealed blaze bears S.18°W., 18.6 ft. (Rec. 16°W.)
New BT's- A 10" Cedar, bears S.52°W., 33.8 ft. marked: "1/4 S36 BT" on a double blaze with a brass washer "LS 536" nailed into lower blaze.
A 16" D. Fir, bears N.38°W., 61.3 ft. marked "1/4 S36 BT" on a doubleblaze with a brass washer "LS 536" nailed into lower blaze

9/80

44

1/4 Corner for Sec. 31 only. (West)

Found - A 1927 US GLO brass cap properly marked, on a 1" x 36" I.P. laying on top of the ground. The monument was disturbed by See two windthrown trees which pulled it out of the ground. Ren. 8
A 20" D. Fir, orig., with healed blaze bears S.28°E., 29.0 ft.
A 12" Windthrown D. Fir, with healed blaze bears N.41°E., 4.0 ft.
Set - RESET the monument in its orig. position, 15" in the ground in a 3 ft. diam. mound of stone, 2 ft. high.
New BT - A 26" D. Fir, bears N.62°E., 104.5 ft. marked: "1/4 S31 BT" on a double blaze with a brass washer stamped "LS 536" nailed into lower blaze.

9/80