

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 1 E R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

E. C. Grant
D. W. P. & J. C. Transit.
8/12/57
C. S. File #42/328

Renewal of Corner to Sections 26, 27, 34, & 35, T25S., R1E.

From reference points set by Art Evans.

Set $\frac{3}{4}$ " Steel Rod below surface of Road, from which:

Marked 40" Fir T25S, R1E., S34 2807. S 83° 10' W 200.0 ft *
Marked 8" Fir T25S, R1E, S27. N 87° 30' W 235.5 ft

No other trees suitable for marking.

Note: See Sketch in C.S. File.

* Added 11-17-97 DCSO JC

D. G. Heuschkel
For Forrest Alberti
Nov. 24, 1958
C. S. File No. 42/405

Section Corner to Sections 15, 16, 21, & 22.

This corner was a 12" Hemlock which had been tied to a cutting unit boundary by Forest Service surveyors. Although marked to be saved, the tree was destroyed during logging. The Forest Service admin. present then placed a temporary metal pipe in the stump hole. The logger, Mr. Alberti confirmed the location. Blazes still exist intercepting the stump hole from all directions.

A Wild Theodolite was used in reestablishing the corner.

A Pipe 2" in diam. & 42" long marks the corner. From it:

A Pipe 2" by 25" bears N 32° 7' W. a distance of 13' 7"

A Pipe $1\frac{1}{2}$ " by 28" bears N 57° 32' E a distance of 13' 1";

A Pipe $1\frac{1}{2}$ " by 24" bears S 66° 6' E a distance of 14' 2";

a Pipe 2" by 28" bears S 58° 16' W a distance of 18' 5".

Closing Corner

T 25 S R 1 W
S 36

T26-R1W S 1/S 31 T25 $\frac{1}{2}$ -1E

Found - 2" I. Pipe & 1928 GLO Brass Cap attached, properly mkd.

18", now 26" Fir S. 38° E. 71.9 ft., shows very good scar,

Tree alive, we do not open

Orig. 36", now 48" badly rotted Fir Stump, S. 31° W. 48.2 ft.,

shows frag. scribe marks "T2" on shattered blaze.

New BT: 15" Pine S. 64° W. 23.6 ft. mkd. T26S R1W S 1 CC CS BT.

Note - Corner lies on steep, south, slope, approx. 140 ft. East of shallow ravine, course SE.

Closing Corner to Secs. 19 & 30, T25-R1E.

Found - 1927 GLO Brass Cap, properly mkd., slightly bent over.

16" Fir, now 24" Stump, 5' high, N. 64° E. 84.5 ft., shows good scar. Do not open.

10", now 14" Fir, S. 62° E. 7.3 ft. Alive, shows good scar.

New BT: 20" W. Fir N. 45° E. 8.4 ft. mkd. T25S R1E S19 CC CS BT.

Note - This corner lies approx. 164 ft. S. of the Sec. Cor. of Secs. 24 and 25, T25-1W. on moderate S. slope.

Sec. Cor. to Sections 24 and 25 only, T25-1W.

Found - 1927 GLO Brass Cap, properly mkd.

Orig. 28", now 36" W. Fir, S. 14° W. 71.9 ft. (not S. 18° W.) shows scribe marks on unhealed blaze. Alive.

Orig. 48", now 53" Fir, dead & shattered, N. 18° W. 23.8 ft., scribe marks visible on face & reverse on overgrowth.

New BT's: 8" W. Fir S. 56° W. 11.2 ft. mkd. T25S R1W S25 CS BT.

8" D. Fir N. 12° W. 46.4 ft. mkd. T25S R1W S24 CS BT.

Note - This corner lies on southerly slope, approx. 360 ft. S. of top of spur & approx. 164 ft. N. of C.C. of Secs. 19 & 30, T25-1E.

$\frac{1}{4}$ Corner to Section 25 only, T25-1W.

Found - 1927 GLO Brass Cap, properly mkd., badly bent & nearly out of the ground. We straighten and Reset.

Orig. 36", now 40" Fir Snag, S. 60° W. 20.5 ft., very good scar. Do not open.

6", now 10" Fir N. 65° W. 34.3 ft., Alive, shows good scar. Do not open.

Orig. Basalt Stone, showing $\frac{1}{4}$ " chisel marks.

New BT: 9" D. Fir S. 10 $\frac{1}{2}$ ° W. 23.7 ft. mkd. $\frac{1}{4}$ S25 CS BT.

Note - This cor. lies on moderate, changing to steep, W. Slope and approx. 125 ft. N. of the $\frac{1}{4}$ corner of Sec. 30, T25-1E.

Vernone "Ray" Tracy
Jack Heritage & E. West
October, 1966
C. S. File No. 52/30

1

2

3

4

5

6

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 1 E. R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

7

1/4 Cor. to Section 36 only, T25-1W.
Found - Orig. 50" Fir, now stump, N. 80 1/2° W. 28.4 ft., shows "T".
8" Fir, now down, S. 37° W. 30.4 ft., shows "S36" & unhealed blaze. No trace of Rock called for.
Set - Brass Cap at Cor. Mkd: Doug. Co. Surv. Office, 1966 R1W 1/4 S 36 R1E
(14" in ground & mnd of 1927)
New BT's: 8" Fir S. 39° W. 12.9 ft. mkd. 1/4 S36 CS BT.
12" Hemlock S. 16° W. 18.6 ft. mkd. 1/4 S36 CS BT.
Note - This corner lies on right bank of Canton Creek.

RE-RENEWED, SEE CORNER NO. #43

8

1/4 Corner to Section 31 only, T25-1E.
Found - 1927 GLO Brass Cap mkd. "1/4 S31", nearly on of rock mound.
Reset Brass Cap in new mound of approx. 2' high.
Both 1927 BT's. alive & show scar. 14", now 18" D. Fir S. 37° E. 14.6 ft. rescribed "1/4 S31 CS BT".
8" Pine N. 44° E. 11.7 ft. rescribed "1/4 S31 CS BT".
Note - Corner lies 50 ft. W. of Canton Creek, course S. on right high bank & approx. 40 ft. S. of the 1/4 Cor. Sec. 36 only, T25-1W.

RE-RENEWED, SEE CORNER NO. #44

9

Closing Corner to Sections 30 and 31, T25-1E.
Found - 1927 GLO Brass cap, properly mkd.
10", now 14" Fir, S. 64° E. 41.6 ft. (face) prev. opened, scribe marks visible. Alive. N.E. BT. lying face down.
New BT's: 8" D. Fir S. 37° E. 14.6 ft. mkd. CC S31 CS BT.
8" Pine N. 44° E. 11.7 ft. mkd. CC S30 CS BT.
Note - This cor. lies in logged off unit 150' N. of small ravine, course SW.

Vernon "Ray" Tracy
Jack Heritage & E. West
October, 1966
C. S. File No. 52/30

10

Sec. Cor. to Sections 25 and 36 only, T25-1W.
Found - 1927 GLO Brass cap, properly mkd.
Orig. 36", now 57" Pine Stump (not Fir) N. 25° W. 33.7 ft., shows fair scar. We rescribe "T25S R1W S25 CS BT".
Orig. 30", now 30" Fir Stump, 10 ft. high, S. 14° W. 43.6 ft.
14", now 20" Pine Shattered Stump, S. 70° W. 46.2 ft.
Also find stumps of obliterated BT's. to E. of line.
New BT's: 14" D. Fir N. 39° W. 42.0 ft. mkd. T25S R1W S25 CS BT.
12" Pine S. 60° W. 108.3 ft. mkd. T25S R1W S36 CS BT.
Note - This corner lies approx. 85 ft. north of closing corner of secs. 30 & 31, T25-1E.

RE-RENEWED, SEE CORNER NO. #59

11

Township Corner, T24S-T25S- R.1W. & R.1E.
Found - Orig. 18", now 28" Cedar N. 64° E. 11.2 ft., prev. opened many years ago "S E S3" scribe visible on nearly rehealed blaze. We rescribe "T24S R1E S31 DCS BT".
Orig. 28", now 36" Fir S. 37° E. 43.6 ft. Alive, good condtn., shows very good scar.
Orig. 30", now 36" Fir S. 86° W. 33.0 ft. Alive, good cond., shows very good scar.
Orig. 18", now 21" Fir N. 25° W. 31.0 ft. Alive, good cond., shows very good scar.
Set - Brass Cap at Cor. Mkd: Doug. Co. Surv. Office, 1966 T24S R1W S 36 | S 31 R1E
T25S R1W S 1 | S 6 R1E
New BT: 10" Hemlock N. 60° W. 34.8 ft. mkd. T24S R1W S36 DCS BT.
No smaller trees close to S.E. or S. W.
Note - This corner is on Douglas-Lane County Line.

Nov. 3, 1966

12

Closing Corner Sections 18 and 19, T25S-R1E.
Found - 1927 GLO Brass Cap, properly marked & BT's. allows:
8", now 11" Fir, N. 61° E. 30.4 ft., now small, shows scar, we do not open.
8" now 10" Fir Snag, S. 40° E. 27.7 ft., shows scar, Don't open.
New BT's: 36" Cedar S. 48° E. 7.4 ft. mkd. T25S R1E S19 CCOCS BT.
12" D. Fir N. 1° E. 31.6 ft. mkd. T25S R1E S18 CC CS BT.
Note - This corner lies on S.W. slope approx. 150 ft. south of corner to Secs. 13 & 24, T25-1W, Ren. #22 which is O. K.

RE-RENEWED, SEE CORNER NO. #34

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 1 E. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Witness Corner(South) T25S RLW $\frac{S 12}{S 13}$ RLE 13
 Found - Rock mkd. "WC S12" on N.E. & "S13" on S.W., firmly set
 1.3' north of cl. corner of Secs. 7 & 18, T25-1E which is
 a 1927 GLO Brass Cap firmly set in mound of stone.
 Orig. 40", now 40" Fir Snag, N. 89° W. 13.2 ft. (slope), shows good
 scar, we do not open.
 30", now 34" Fir S. 24° W. 31.7 ft., now stump, shows good scar,
 we do not open.
 Orig. 20", now 20" Fir Snag, N. 58° E. 13.2 ft., recorded as
 being obliterated, frag. scribe marks visible on chopped face.
 New BT's: 12" Cedar S. 71° W. 40.3 ft. mkd. W.C. T25S RLW S13 CS BT.
 12" Pine N. 14° W. 106.3 ft. mkd. W.C. T25S RLW S12 CS BT.
 Note - This corner lies on precip. west slope on N.-S. cutting line,
 cut off to west.

Wit. Cor. (North) $\frac{S 12}{RLW S 13}$ T25S RLE 14
 Found - Steel tube & Alum. Cap & Rock face mkd. S12 B.O. N. 16° W. 17.7 ft.,
 as recorded in Ren. #24 (T25-1W)
 Orig. Rock with "WC" only.
 Set - Brass Cap 482.5 ft. N. of True Corner, note dist. to true cor.
 not on Brass Cap.
 Set Steel Tube along Ren. #24 (T25-1W) B.C. Wit. Cor. $\frac{S 12}{S 13}$ RLE
 There are no live trees west of line. Mark New BT's. to East.
 9" Fir S. 26° E. 39.0 ft. mkd. W.C. CS BT.
 1" Fir N. 85° E. 24.9 ft. mkd. W.C. CS BT.
 Note - This corner lies on top of verticle rock bluff 60' high above
 N. fork of H1 Power Creek.

$\frac{1}{2}$ Corner to Section 24 only, T25-RLW. 15
 Found - Basalt Stone mkd. "1/2 W on W. face.
 No trace of 1927 GLO Brass Cap.
 26", now 30" Fir Stump, N. 45° W. 66.0 ft., shows good scar. Don't open
 8", now 11" Madrone N. 64° W. 4.6 ft., prev. opened & shows fragments
 of scribe. (Recorded as S. 64° W.)
 Also obliterated 16" Madrone N. 53° E. 7.9 ft.
 Set - Brass Cap Mkd: County Surveyor's T25S RLW $\frac{1}{2}$ S24 RLE
 New BT's: Office, 1966
 6" Madrone N. 39° E. 6.0 ft. mkd. "1/2 S CS BT".
 5" Madrone N. 21° W. 5.5 ft. Mkd: "1/2 S24 CS BT.
 11" Madrone N. 64° W. 4.6 ft. remarked: "1/2 S24 CS BT.
 Note - This corner lies at foot of 30 ft. bluff on top of 100' high bluff.

Sec. Corner to Sections 1 & 12 only, T25S-RLW. 16
 Found - 1927 GLO Brass Cap, properly mkd. & nearly out of ground.
 Reset - Brass Cap 12" in ground & buried mound of stone 15" high around
 Orig. 60", now 60" Fir Stump, cut low, S. 48° W. 19.1 ft., no scribe.
 Orig. 30", now 31" Fir N. 71° W. 26.4 ft. (recorded as 4 lks., should
 be 40 lks.) scribe marks visible on nearly healed blaze. Alive.
 Obliterated BT's. to N.E. & S. E., now turned out.
 New BT's: 31" Fir S. 74° W. 61.6 ft. mkd. T25S RLW S12 CS BT.
 5" Hemlock N. 59° W. 29.4 ft. mkd. S 1 CS BT.
 Note - This corner lies at N.E. corner of cut off unit on top of round spur.

$\frac{1}{2}$ Corner to Section 1 only, T25-1W. 17
 Found - GLO 1927 Brass cap, firmly set & properly marked.
 Orig. 30" Fir, now Snag, S. 50° E. 63.4 ft. This BT. was obliterated
 in 1927, rehealed blaze. Use as ref. since bear. to fallen BT.
 does not check.
 8", now 14" Pine, N. 76° W. (not N. 62° W.) 14.5 ft., partial scribe
 marks visible on nearly healed blaze. Alive.
 Rescribe: "1/2 S 1 CS BT".
 8", now 14" Chinq., S. 35° W. 15.2 ft., frag. scribe marks visible
 on badly decayed & unhealed blaze. Alive.
 New BT: 12" D. Fir S. 6° W. 22.5 ft. mkd. $\frac{1}{2}$ S 1 CS BT.
 Note - This corner lies 25' E. of new logging Rd., course N.&S., curving S.E.

Vernon "Ray" Tracy
 Jack Heritage & E. West
 November, 1966
 C. S. File No. 52/30

RE-RENEWED SEE CORNER NO #33

RE-RENEWED SEE CORNER NO #60

RE-RENEWED SEE CORNER NO #61

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 1 E. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

18

1/4 Corner to Section 6 only, T25S-R1E.

Found - 1927 GLO Brass Cap set in mound of stone & properly mkd.
16", now 18" Fir N. 29° E. 19.8 ft., prev. opened &
scribe visible, Alive. Rescribe above old blaze:

" 1/4 S 6 CS BT".

24", now 28" Fir, S. 42° E. 23.8 ft., shows good scar,
we do not open. This BT. is directly behind a 36" D. Fir
from Brass Cap.

New BT: 18" D. Fir S. 9° E. 12.0 ft. mkd. 1/4 S 6 CS BT.

Note - This corner lies approx. 125 ft. S. of new logging road &
approx. 180 ft. S. of 1/4 Cor., Sec. 1, T25-1W.

19

1/4 Corner to Section 7 only, T25-1E.

Found - 1927 GLO Brass Cap mkd. "1/4 S7", firmly set.

24", now 26" Fir with top broken out, N. 46° E. 46.9 ft. ^{#57}

Alive, shows good scar. We do not open.

50", now 52" Fir, uprooted & out of position, S. 51° E. 42.9 ft.

New BT's: 51" D. Fir Stump S. 78° E. 27.2 ft. mkd. 1/4 S7 CS BT.

44" D. Fir Stump N. 2° E. 14.0 ft. mkd. 1/4 S7 CS BT.

Note - This corner lies approx. 60 ft. S. of cutting corner in
clear cut unit & approx. 146 ft. S. of 1/4 Cor. S12, T25-1W.

20

1/4 Corner to Sections 12 only T25-RLW.

Found - Stone mkd. "1/4 S12" on W. face.

Orig. 16", now 21" Fir Stump, N. 40° W. 35.8 ft., shows
good scar. We do not open.

30", now 36" Fir Stump, S. 21° W. 44.2 ft. (not 39.6 ft.)

Open & find reverse scribing.

Orig. 36", now 42" Fir, N. 63° E. 11.9 ft., shows scar,

recorded as marks obliterated. Alive, we use as reference only.

Set - Brass Cap at Cor. Mkd: County Surveyor's T25S RLW 1/4 S12 R1E
Office, 1966

New BT: 23" D. Fir N. 78° E. 24.9 ft. mkd. 1/4 S CS BT.

No trees available to W. of line due to logging.

1/2" Steel Pin with 1" Alumin. Cap mkd. "Prop. Cor",

See Ren. #57, bears S. 48° E. 1.5 ft.

T25-1W

21

Sec. Corner to Sections 17 - 18 - 19 - 20.

Found - Orig. Corner Tree, 10", now 11" Fir with scars on
appropriate side, Now Snag.

Orig. 8", now 14" Fir, Alive, N. 65° W. 5.3 ft., shows good scar.

Orig. 10", now 13" Fir, shattered Stump, S. 53° W. 58.7 ft.,
reverse scribe.

Orig. 10", now 14" Fir Snag, N. 35° E. 16.5 ft., shows good scar.

No trace of S.E. BT.

Set - Brass Cap on S. Side of Corner Tree 1 ft. from center mkd:

County Surveyor's T 25 S R 1 E
Office S 18 | S 17
1967 S 19 | S 20

New BT's: 10" Fir S. 76° W. 57.7 ft. mkd. T25S R1E S19 CS BT.

6" Fir S. 77° E. 30.8 ft. mkd. T25S R1E S20 CS BT.

8" Fir N. 66° E. 15.8 ft. mkd. T25S R1E S17 CS BT.

Note - This corner lies on very steep, SW slope, 50 ft. S. of logging road.

April 6, 1967

22

1/4 Corner to Section 31 and 32.

Found - 1927 GLO Brass Cap, properly mkd, but almost out of ground.

Reset - Brass Cap in mound of Stone from one Orig. BT:

12"?, now 50" Pine, N. 14 1/2° E. 304.3 ft., Alive, shows
very good scar. Do not open. No trace SW BT.

New BT: 12" D. Fir S. 34° W. 74.2 ft. mkd. 1/4 S31 CS BT.

Note - This corner on precip. SE. rock slope approx. 300 ft. S. of timberline.

March 24, 1967

Vernon "Ray" Tracy
Jack Heritage & E. West
November, 1966
C. S. File No. 52/30

RE-RENEWED CORNER NO. #57
RE-RENEWED CORNER NO. #58

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 1 E. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

23

1/4 Corner to Sections 30 and 31.
Found - 1927 GLO Brass Cap properly marked, but far around. #52
Reset - in proper position from the following BT's:
Orig. 18" now 16" Fir, alive, S 48° W. 23.8 ft., shows good
scar. We do not open.
Orig. 10" now 16" Hemlock sawed Stump, N. 10 1/2° W. 33.0 ft., shows
"BT" scribe on unhealed blaze.
New BT: 6" Chinq. N. 26° E. 68.7 ft. mkd. 1/4 S31 CS BT.
Note - Corner lies on N. edge of Cat. fire trail on S. edge of logged unit.

1/4 Corner to Section 31 only, T25-1E. 24
Found - 1927 US GLO Brass Cap properly marked & BT's. as follows:
8", now 9" Fir Stump, N. 25° E. 63.4 ft., shows "BT" scribe on
unhealed blaze.
6", now 9" Fir, Alive, N. 75° W. 13.9 ft., shows good scar. Don't opn.
New BT: 7" D.Fir N. 58° E. 16.9 ft. mkd. 1/4 S31 CS BT.
Note - This corner lies 100 ft. N. of Canton Creek Access Road.

MICROFILM TO HERE -10/67

25

Corner #1 Mineral Survey # 501
Found: Rotted Remains of 4" square wood post, no marks remaining, near a small
mound of stone.
From which: An orig 40" fir, now an 8 ft tall rotten snag bears north 6.0ft.,
with scribing "BT" visible on wood fragments.
An orig. 18" now 24" D.Fir bears S 7 1/2° W., 21.0ft., alive and well-healed.
At the corner point, we set a 1"x30" I. pipe 10" in the ground to the bedrock
and supported in a mound of rock 3 ft. at the base and 1 ft. high, with
Brass cap attached, Mkd: T 25 S R1E
DOUGLAS CO. SURVEYOR
1975
M.S.
Cor. 1 501
Note: This nonument is set leaning to the west.
We mark a new bearing tree:
A 14" D.Fir bears N 20° W., 15.4ft., scribed "1 MS 501 CS BT" on a double blaze.
Note: This corner lies approx 40 ft. west of Steamboat Creek. Magnetic
Declination : 20° E. 9/10/75

Corner #2 Mineral Survey #501 26
Found: Orig 24" now 34" D.Fir, alive and well-healed, bears N 40° E., 24.0ft.
A Down and rotten ceder bears N31 1/2° W., 25.5ft., with illegible reverse
scribe marks visible on healed wood.
At the corner point, we set a 1"x30" I. pipe, with brass cap attached. MKD
DOUGLAS CO SURVEYOR T25S R1E
1975
Cor. 2 M.S. 501
We mark the following bearing tree for this cor.
A 7" Grand Fir bears S22° E., 3.4 ft., scribed: "2 MS 501 CS BT" on a double
blaze. Dompass Declination setting: 20° East
9/8/75

Corner #3 Mineral Survey #501 27
Found: No remains of original corner. Corner and accessories destroyed by
camp ground construction.
New: We set a 5/8" iron rod at the corner as it falls in the road.
An 11" maple scribed "3 MS 501 CS BT" in a double blaze bears S 50° E.,
69.0 ft.
A 16" Fir scribed "3 MS 501 CSBT" in a double blaze bears N72 1/2° E., 71.6ft.
Compass Declination 20° East. 9/29/75

Vernon "Ray" Tracy
Jack Heritage & D. Wast
March & April, 1967
C.S. File No. 52/30

Sept. 68

Clell Goodwin
Vic Cangie
Lenora Ladig
CS 57/30
9/29/75 M 58-23

**Douglas County Surveyor's Record of
Government Corners Renewed**

25 T.S. 1 E R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

Corner #4 Mineral Survey # 501
 Found: Orig. 36" now 42" D.Fir, alive and well-healed bears N 60 1/4°W., 26.0ft.
 (rec. N62°W., 26.0 ft)
 an orig. 18" now 30" D.Fir, alive and well-healed, bears S 14°W., 24.0ft.
 (rec. S 16°, 24.0 ft.)

28

Gary L Langlitz
 M.Lenora Ladig
 A.Vic Cangie
 C.S. 57/36
 9/8/75
 M 58-23

At the corner point- we set a 1" X 30" I pipe with brass cap attached, marked:
 T 25 S R1E

RE-RENEWED SEE CORNER NO. # 49

DOUGLAS CO. SURVEYOR
 1975

M.S. Cor. 4
 501
 9/8/75

Compass Declination Setting: 20° East

Cor. # 5 Mineral Survey # 501
 Found: Orig. 12" now 14" W.Oak with previously opened upper blaze but no marks showing. We open lower blaze and find reverse scribe marks.
 The Original N.W. Tree, a 12" Pine is gone, however we find a scribed face, marked "6-501" lying on the ground near the true corner location.
 At the corner point located with reference to the orig. 12" now 14"W Oak bearing N 59 1/2°E., 48.0 ft., we set a 1" x 30" I. Pipe with brass cap attached, marked

29

DOUGLAS CO. SURVEYOR
 1975

T25S R1E
 M.S. Cor. 5
 501

We mark the following new BT's
 14" D.Fir bears S 28°E., 19.8 ft., scribed "5 MS 501 CS BT" on a double blaze, an 8" D.Fir bears N86°E., 17.6ft. Scribed "5MS501 CSBT" on a Double blaze.
 Note: This cor. lies on a steep south slope north of Steamboat Creek Forest Rd.
 Magnetic Declination: 20° East 9/10/75

Cor. # 6 Mineral Survey # 501
 Found: No identifiable remains of the orig. corner or accessories.
 New: At the corner point as determined by a resurvey of MS 501 we set a brass cap on a 1" X 30" I Pipe stamped

30

DOUGLAS CO. SURVEYOR
 1975

T25S R1E
 MS 501
 Cor 6

From Which: A 6" Fir scribed "6 MS 501 CS BT" in a double blaze bears S 12 1/2°W., 25.7 ft.
 A 10" fir scribed "6 MS 501 CS BT." in a double blaze bears N 62°W., 33.8 ft. Compass Declination 20° East. 9/29/75

U.S. Location monument # 2
 Found Rotted remains of 7" square wooden post, no marks remaining, supported in a mound of rock 6 ft. in diameter at the base and 3 ft. high
 From which
 an orig. 22" now 28" D.Fir bears N 73°W., 24.3 ft. alive and well-healed
 an orig. 24" now 36" D.Fir bears S 35°, 50'W, 6.1 ft. alive and well-healed
 We remove the remains of the wooden post and replace it with a 1" X30" I pipe supported it's full length in the rock mound, with brass cap attached, Mkd;

31

DOUGLAS CO. SURVEYOR
 1975

T25S R1E
 +
 U.S.L.M. 2

Note: This corner lies between Steamboat Creek and Steamboat creek forest RD.
 Magnetic Declination: 20° East 9/10/75

~~1/4 Corn to Sec.4 and 9
 Found-I.P. with properly marked brass cap. Two orig. BTs as follows
 BT's-Orig. 16" incense cedar, now a 19" snag, well-healed, bears N73°E., 21.1 ft
 Orig. 18" D.Fir, now a 20" snag, well-healed, bears S67°E., 11.7 ft.
 (rec.S71°E., 11.7 ft)
 New BT's-A 10" Grand Fir Bears S41°E., 14.8 ft. scribed "1/4 S9 CSBT on a Double blaze.
 A 7" D fir bears N38°E., 16.8 ft. scribed "1/4 S4 CSBT on a double blaze
 Compass declination setting 20° East 1/7/76~~

32

Gary L Langlitz
 Dennis Johnson
 Jerry Jackson
 A Vic Cangie
 Peter L Earle
 C.S. 59/2
 1/7/76

Douglas County Surveyor's Record of
Government Corners Renewed

T 25 T. S. R 1 E R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

L. E. Monrean, Doug. Co. Surveyors Office
P. L. Earle
Sept. 13, 1976
C.S. 59/24

32

Section cor. for Secs. 13 and 24 only, T25-1 W.
Found - 48" (rec. 60") Fir, now a stump, bears N.74°W., 29.0 ft. with blaze. I open & find scribing "T25S RIW S13 BT".
Stone, 16"x14"x7" (rec. 6"x10"x8" above ground, Orig. 12"x10"x8") found 3 notches on opposite faces and S 13 on another face. Rock has been dislodged by windfall bearing tree.
38" Fir (Rec. 36") is now a windfall. Tree has well healed blaze.
Steel tube with survey cap, dislodged by uprooted BT. Ren. #22, T25-1W.

Set - Brass cap at section corner stamped:
"County Surveyors Office" T 25 S
1976 R S 13 R
1 S 24 S 18 1
W S 24 E

Set - Corner stone on north side of cap, set steel tube on south side of cap
Set - 5/8" x 30" iron rod with alum cap. in BT stump, bears N.75°W., 28.7 ft.
Cap stamped "B.O. 1"
Set - Spike in 40" Fir stump, bears S.50°W., 33.8 ft. stamped "B.O. 2".
Set - Cedar post 2" square x 9 ft. Set post 2.4 ft. in the ground, bears North, 4.0 ft.

9/13/76

Witness Corner (south) for Secs. 12 and 13 of T.25-1W. 33
Found - 39" D. Fir bears N.87°06'W., 13.2 ft. with good scar.
33" D. Fir stump bears S.25°04'W., 31.7 ft. scribing partially visible.
11" Cedar bears S.73°12'W., 39.9 ft. scribing visible. Ren. #13
12" Pine bears N.14°08'W., 107.9 ft. with good scar.
Set - A 2" x 30" Galv. steel pipe 24" into the ground and constructed a mound of stones around it. I marked the attached 2 1/2" brass cap: T25S WC S12 S13 RIW R1E PLS 866 1978.

34

Closing Corner for Secs. 18 and 19 only.
Found - 2" Iron pipe with 2 1/2" brass cap marked U.S. General Land Office
T25S T25S
S24 S18 R1W R1E 1927.
S19^{CC}

30" Cedar snag bears S.28°E
9" D. Fir snag bears S.40°E
New BT's- 15" D. Fir blazed & scribed "T25S R1E S19 CC, BT" with brass washer marked "LS 866" attached, bears S.07°30'E., 31.3 ft.
20" D. Fir blazed & scribed "T25S R1E S18 CC, BT" with brass washer marked "LS 866" attached bears N.77°00'E., 80.5 ft.

35

1/4 Corner for Sec. 13 only of T.25-1W.
Found - 5/8" Steel tube buried 12" under the berm at the side of a skid trail
1" Alum. cap attached marked "Property Corner".
36" D Fir stump with axe marks in bark bears S.26°55'W., 20.8 ft.
12" Cedar stump approx. 16" high with face charred from slash fire bears N.45°00'E., 55.8 ft.
Set - Replaced with 2" x 30" Gal. Steel pipe 26" in the ground.
Placed tube next to pipe. Marked the attached 2 1/2" brass cap T25S RIW 1/4 S13 PLS 866 1978"
Cedar scribed "1/4 S13 BT" and attached brass washer marked "L.S. 866" bears S.20°55'W 77.8 ft.
Drove green 6 ft. steel fence post 18" into the ground and painted red, bears N.45°56'W., 55.8 ft.
Constructed mound of stones around the 2" x 30" steel pipe.

36

Closing Corner for Secs. 7 and 18 only.
Found - 1 1/2" Pipe with 2 1/2" brass cap properly marked as recorded U.S. GLO 1927.
Both had slid several feet down hill with pile of stones.
38" D. Fir, N.23°49'E., 90.5 ft. Shows good scar.
22" D. Fir, S.36°06'E., 97.3 ft. Shows good scar.
Set - I reset orig. pipe with brass cap S.00°58'E., 1.32 ft. from the pipe I had previously set for the witness corner to the corner of sections 12 and 13. I constructed a mound of stones around it.

William J. Rupper, L.S. #866
For: U.S. Forest Service
November 1978
C.S. 58/176

RE-RENEWED, SEE CORNER NO. #53
RE-RENEWED, SEE CORNER NO. #54

Douglas County Surveyor's Record of
Government Corners Renewed

E

T 25 T. S. R 1 E R.W/W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

37

1/4 Corner for Sec. 2 only. (North)

Found - 1" Iron pipe with a 1928 GLO brass cap attached properly marked.
Pipe is set loosely in ground.

From which - A 12" Douglas fir bears S.26°W., 14.52 ft. Has a single healed blaze.

A 17" Douglas fir bears S.45°E., 25.08 ft. This tree is still living but all signs of a blaze have been destroyed by logging activities.

Set - I place a mound of stone around the iron pipe.

New BT - An 18" Douglas fir bears S.70°30'E., 35.4 ft. scribed "1/4 S2 BT" on double blazes.

Note - Corner 1/4 S35 T24S, R1E, bears East, 65.97 ft. (Rec. N.88°14' 96 lks. or 63.36 ft.) U.S.F.S. bearing tree signs were placed on all BT's. This corner is about 50 ft. north of F.S. Rd. #2512.

1/4 Corner for Sec. 35 only for T24-1E.

Found - Orig. corner stone, which measures 20" x 14" x 5", is loosely set in the ground and is broken in half. Stone is marked "1/4 35".

From which:

A 30" Douglas Fir stump bears S.45°30'E., 29.7 ft. with a chopped out blaze as per 1928 record.

A down and decayed madrone, whose stump bears N.33°E., 11.88 ft. No marks visible.

A 14" Douglas fir stump bears N.44°W., (not 44°E.) 25.9 ft. and 27.72 ft. slope distance. I open snag lying alongside this stump and find scribing "1/4 S35 BT".

Set - Moving the corner stone aside, I set in its place a 1 1/2" x 5" iron pipe with a 2 1/2" brass cap attached marked:
T24S R1E 1/4 S35 P.L.S. 1636 1979

I bury corner stone alongside.

From which:

A 26" Douglas fir bears N.54°W., 70.2 ft. scribed "1/4 S35 BT" on double blazes.

A 19" Douglas fir bears N.24°E., 27.2 ft. scribed "1/4 S35 BT" on double blazes.

Note: Compass declination: 18°E. Corner 1/4 S2, T25S R1E., bears west, 65.97 ft. (Rec. S.88°14'W., 96 lks or 63.36 ft.) U.S.F.S. bearing tree signs were placed on all BT's. Corner is about 50 ft. north of F.S. road No. 2512.

4/19/79

Section corner for Secs. 35 and 36 only of T.24-1E.

Found - Original corner stone was found loosely set in the ground. The stone, which measures 14" x 9" x 5" is marked with 5 grooves on the west face and one groove on the east face. No other marks discernible.

A 38" D. Fir bears N.23°30'W., 72.6 ft. & has a nearly healed single blaze which has been previously opened.

A 24" D. Fir bears N.74°E., 107.58 ft. & has a healed single blaze. This tree has been badly damaged by rockfall.

Nothing remains of the other bearing trees of record.

Set - Moving the corner stone aside, I set in its place a 1 1/2" x 6" iron pipe with a 2 1/2" brass cap attached marked: T24S R1E S35 S36 S1 T25S R1E P.L.S. 1636 1979.

New BT - A 15" D. Fir bears N.25°30'W., 56.8 ft. scribed "24S R1E S36" on a double blaze.

Note: Compass declination: 18°E. Corner S1 S2 (T25S-R1E) bears S.80°30' W) 57.3 ft. (Rec. S.89°02'W., 0.86 ds.)

Corner lies approx. 75 ft. north of F.S. Rd. No. 2512. U.S.F.S. bearing tree signs were placed on all BT's.

4/26/79

Dennis Gaylord, L.S. 1636
U.S.F.S.
April 19, 1979
C.S. 60/24

(Set Stone Alongside)

T24S R1E

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 25 T. S. R 1 E E
R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 97301

Dennis Gaylord
U. Forest Service
April 1, 1979
C 60/24

Glenn Baughman
For: U.S. Forest
Service
Sept. 1980
C.S. 58/229

Glenn Baughman, LS 536
For: U.S. Forest Service
Sept. 1980
C.S. 58/229

40

Closing corner for SEcs. 2 and 1 only.

Found - 2" Iron pipe firmly set & protruding 14" above ground. A 2 1/2" brass cap attached to the pipe is marked: U.S.G.L.O. survey R1E T24S S35 C C S2 S1 T25S R1E 1928.
A 37" D. Fir bears S.63°E., 36.3 ft. & has a single healed blaze.
A 28" D. Fir bears S.26°30'W., 29.7 ft. & has a single healed blaze.

U.S.F.S. bearing tree signs were placed on both BT's and they were painted with a band of red paint. No new Accessories. The corner 35 S36 bears N.89°30'E., 57.3 ft. (Rec. N.89°02'E., 0.86 chs.) S 1
Corner lies 5 ft. north of F.S. Road #2512.

4/19/79

41

Closing Corner for Secs. 6 and 7 only.

Found - 1927 U.S. GLO brass cap, properly marked, on a 2" iron post firmly set, 10" above the ground. (C.S. Vol. 21 Pg. 9120)
21" D. Fir, orig. with healed blaze, bears N.6°E., 6.6 ft.
24" wind fallen D. Fir, orig., with healed blaze bears S.17°E., 49.5 ft.

New BT - a 11" D. Fir bears S.7°E., 42.7 ft. marked "T25S., R1E S7 CC BT" on a double blaze with a brass washer stamped "LS 536" nailed into lower blaze.

9/80

42

Section corner for Sec. 31; and Sec. 36 of T.25-1W. (Twsp. corner)

Found - 18"x12"x8" basalt stone with 6 notches in the north, south, east and west faces. Stone was laying on top of the ground.
A 62" D. Fir, orig. bearing tree, with healed blaze bears S.36°E., 47.5 ft. (Scribe marks destroyed in 1927 resurvey).
A 28" D. Fir, orig. BT, with healed blaze bears S.11 1/2°E., 30.0 ft. (Rec. 33.0 ft.) (Scribe marks destroyed in 1927 resurvey)
A 45" D. Fir, orig. BT, with healed blaze bears N.54 1/2°W., 52.8
A 22" D. Fir, orig. BT with healed blaze bears N.67 1/2°E., 56.8 ft.
A 24" Cedar (not of record) with healed blaze bears N.32°E., 30.1
Set - At the corner point A 2 1/2" x 30" iron pipe, 6" in the ground on bedrock in concrete, and in a 3 ft. diam. mound of stone, 3 ft. high with a 3" brass cap projecting 12" above the mound of stone and marked: "T25S R1W S 36 R1E S 31 T25 1/2S R1E S31 1980"

9/80

43

1/4 Corner for SEc. 36 only of T.25-1W

Found - A 1966 County brass cap properly marked. Ren. #7
A 50" D. Fir stump, Orig. BT, with scribe mark "4" visible, bears N.80 1/2°W.- 28.4 ft.
A 8" D. Fir snag, with scribe marks "1/4 S36 CS BT" visible on an unhealed blaze bears S.89°W., 12.9 ft.
A 24" Hemlock snag, with scribe marks "1/4 S36 CS Bt" visible on an unhealed blaze bears S.18°W., 18.6 ft. (Rec. 16°W.)
New BT's- A 10" Cedar, bears S.52°W., 33.8 ft. marked: "1/4 S36 BT" on a double blaze with a brass washer "LS 536" nailed into lower blaze.
A 16" D. Fir, bears N.38°W., 61.3 ft. marked "1/4 S36 BT" on a doubleblaze with a brass washer "LS 536" nailed into lower blaze

9/80

44

1/4 Corner for Sec. 31 only. (West)

Found - A 1927 US GLO brass cap properly marked, on a 1" x 36" I.P. laying on top of the ground. The monument was disturbed by See two windthrown trees which pulled it out of the ground. Ren. 8
A 20" D. Fir, orig., with healed blaze bears S.28°E., 29.0 ft.
A 12" Windthrown D. Fir, with healed blaze bears N.41°E., 4.0 ft.
Set - RESET the monument in its orig. position, 15" in the ground in a 3 ft. diam. mound of stone, 2 ft. high.
New BT - A 26" D. Fir, bears N.62°E., 104.5 ft. marked: "1/4 S31 BT" on a double blaze with a brass washer stamped "LS 536" nailed into lower blaze.

9/80

Douglas County Surveyor's Record of
Government Corners Renewed

T 25

T. S.

R I E

E
R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21001

48

Douglas County
Surveyors Office
L. E. Monrean,
Deputy
J. Lundeen
R. Smith
S.J. Flause
Sept. 21, 1984
S. 62/21

Closing Corner for Sections 3 and 4 only.
Found - 1928 GLO 2 1/2" cap on a 2" iron pipe protruding 21" above
ground, properly marked.
12" now 18" fir bears S.60°E., 14.2 ft. to center of root
crown 15.2 ft. to center of tree (Rec. S.60°E., 15.2 ft.) Has
well healed single blaze.
A 14" now 20" fir with well healed single blaze bears S.10°W.
25.7 ft. to center of root crown.
New BTs - 28" diam. D. fir double blazed and scribed "S 34 CS BT" bears
N.21 1/2°E., 29.7 ft.
29" diam. D. fir double blazed and scribed "T25S RIE CC S3
CS BT" bears S.3 1/2°E., 28.5 ft.
New BTs measured to center of root crown.

9/21/84

49

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Dec. 9, 1985
C.S. 62/29

Corner #4, Mineral Survey #501
Found - A Doug. Co. brass disk on an I.P. protruding 7 ins. above
ground marked as noted in Ren. #28.
An orig. BT, 36" now 39" dia. 3 1/2 ft. high D. fir stump with a
partial well healed lower blaze bears N.48 1/4° W., 26.0 ft.
agrees with Ren. #28. (Rec. N.48 1/4° W., 26.0 ft.)
An orig. BT, a 18" now 22" dia. 2 1/2 ft. high D. fir stump with a
single fully healed blaze bears S.14°W., 24.0 ft. agrees with
Ren. #28. (Rec. S.14°W., 24.0 ft.) This BT will be
lowered by May 1986 per Ron Murphy, N. Umpqua Ranger
District.
New BTs - 22" D. fir double blazed and scribed "4 MS 501 CS BT".
Bears N.2°W., 26.7 ft.
12" D. fir double blazed and scribed "4 MS 501 CS BT" bears
S.61°W., 27.5 ft.
Corner lies at west end of Steamboat Falls Campground near picnic tables.

12/9/85

50

Stamped
in Error

Section Corner for Secs. 5, 6, 7 and 8.
Found - 1927 GLO 3" brass cap on a 2" dia. I.P. leaning North protruding
29" above ground.
10" now 14" dia. western white pine with a partially healed
single blaze "T25S RIE 5/BT" bears N.52°E., 11.2 ft.
(Rec. N.55°E., 11.2 ft.) (Checked from plumb pos. of monument.)
10" now 10" dia. western white pine with a partially healed single
blaze "T25S RIE S8/BT" bears S.45°E., 15.8 ft. (Rec. S.43°E.,
15.8 ft.) (BT checked from plumb position of monument.)
12" now 20" dia. hemlock with a partially healed single blaze
illegible scribing visible bears N.24°W., 13.2 ft. agrees with
record. (Orig. BT called a spruce)
12" now 13" dia. dead still standing western white pine with a
partially healed single blaze "T25S RIE S7/BT" bears S.22°W.,
45.5 ft. agrees with record. (BT checked from plumb position of
monument.)
Set - Plumb position of Brass cap/iron pipe remonumented as corner
location distances and bearings fit well with record information.
B.C./I.P. returned to plumb position and a 3 ft. dia. x 2 ft.
high mound of stone placed around iron pipe.
New BT - 8" dia. western white pine double blazed and scribed "T25S RIE
S7 CS BT" bears S.19°W., 16.0 ft.
Corner lies on a gentle SE slope.

1/13/86

51

Douglas County Surveyors Office
Deputies: Randall Smith
Stephen Flause
January 13-14, 1986
C.S. 62/31

Section Corner for Secs. 28, 29, 32 and 33.
Found - 1927 GLO brass cap/iron pipe protruding 18" above ground, leaning
7" southeast of plumb.
8" now indeterminable dia. rotted 6" high D. fir stump. No scribing
found bears N.56°E., 17.16 ft. (agrees with record)
8" now 18" dia. D. fir with a fully healed single blaze bears
S.34 1/2°E., 13.5 ft. (Rec. S.33°E., 20.46 ft. dist. is
probably to NW BT.)
8" now 17" dia. D. fir with a fully healed single blaze bears
N.39°W., 19.6 ft. (Rec. N.39°W., 13.20 ft. dist. is probably
to SE BT).

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 25

T. S.

R 1 E

R. ^EW.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

cont. from prev. pg. - (cor. for 28, 29, 32, 33)

51

8" now 15" dia. D. fir with a fully healed single blaze bears S.67 1/2° W., 13.8 ft. (Rec. S.69 1/2°W., 14.52 ft.)
Set - USGLO brass cap/iron pipe returned to plumb position and a 2 ft. dia. mound of stone 14" high placed around I.P. BC/I.P. protrudes 4" above mound of stone.
Plumb position of BC/IP remonumented as corner location. The NW and SE BTs distances appear to be interchanged; if that problem is corrected the bearings and distances to orig. bearing trees agree closely with record information.
New BT - 14" dia. D. fir double blazed scribed "T25S R1E S28 CS BT" bears N.64 1/2°E., 51.3 ft.
Corner lies on level ground.

1/14/86

Douglas County Surveyor
Office
R. Smith/S. Flause
Jan. 13-14, 1986
C.S. 62/31

1/4 Corner for Sections 30 and 31

52

Found - A 1927 GLO brass cap on an I.P. protruding 11 ins. above ground.
18" now 24" dia. 6 ft. high fallen D. fir stump with a fully healed single blaze bears S.48°W., 23.8 ft. (agrees with orig.)
10" now 16" dia. 2 ft. high decayed hemlock stump, with a partially healed blaze, scribing visible "S 30 BT" bears N.10 1/2°W., 33.0 ft. (agrees with rec. Orig.)
6" now 10" dia. chinquapin with a partially healed double blaze no scribing visible bears N.26°E., 69.4 ft. (rec. N.26°E., 68.7 ft. dist. to center of trunk) Per Ren. No. 23
New BTs - 8" W. fir double blazed, scribed "1/4 S30 CS BT" bears N.19 1/4°E., 56.3 ft.
10" W. fir double blazed, scribed "1/4 S31 CS BT" bears S.30 3/4°W., 15.9 ft.
8" D. fir double blazed, scribed "1/4 S31 CS BT" bears S.56°W., 34.6 ft.
Corner lies on North edge of fire trail.

Douglas County
Surveyor Office
Randall Smith
Stephen Flause
April 8, 1986
C.S. 62/34

Section corner for Secs. 18 and 19 only. (west side)

53

Found - 1927 GLO brass cap, properly marked.
30" Cedar snag, bears S.28°E., 6.4 ft.
9" D. fir snag (down) bears S.40°E., 27.7 ft. Ren. #34
10" D. fir bears N.77°E., 80.5 ft.
15" D. fir snag bears S.07°30'E., 31.3 ft.
New BT - 6" D. fir bears N.02°W., 21.5 ft. scribed "X" on small upper blaze and "BT" on small lower blaze. A 1/2" brass washer marked "RLS 1035" is nailed flush to lower blaze.

Gerald V. Nygren
For: U.S.F.S.
June 11, 1987
C.S. 63/50

1/4 Corner for Section 13 only of T.25-1W.

54

Found - 1978 brass cap set by PLS 866, properly marked. Ren. #35
36" Fir stump bears S.26°55'W., 20.8 ft.
12" Cedar stump bears N.44°05'W., 55.8 ft.
16" Cedar bears S.20°55'W., 77.8 ft.
A 6' steel fence post bears N.45°56'W., 55.8 ft.
New BT - 8" D. fir bears N.37°W., 7.0 ft. with single blaze scribed "1/4 S13 RS1035 BT". A 1/2" brass washer marked "RLS 1035" is nailed flush to lower end of blaze.

"I hereby certify the above corner points were perpetuated as hereon described on June 11, 1987. U.S.F.S. bearing tree signs and monument signs were placed on all BT's without them and a 6" red band was painted around each BT.

West 1/4 Corner for Section 7 only.

55

Found - 1928 2 1/2" dia. GLO brass cap on a 1" O.D. iron pipe protruding 11" above ground. A 2 ft. dia. mound of stone is found along east edge of BC/IP. (Rec. raised mound of stone 3 ft., 2 ft. high E. of cor.) (orig. corner)
20" now 39" dia. D. fir with a fully healed single blaze, bears N.56°E., 19.1 ft. (Rec. N.60°E., 19.1 ft.) (Orig. BT.)
New BTs - 14" dia. D. fir double blazed and scribed "1/4 S7 CS BT" bears S.28°E., 4.6 ft.
15" dia. D. fir double blazed and scribed "1/4 S7 CS BT" bears S.2°E., 34.8 ft.
8" D. fir double-blazed & scribed "1/4 S7 CS BT" bears N.71°E. 32.7'.

Douglas County
Surveyors Office
Randall Smith, Dep.
Stephen Flause
Terrie Franssen
April 4, 1991
C.S. 64/13

Douglas County Surveyor's Record of
Government Corners Renewed

T 25 T. S. R 1 E R. W/W.M.

FORE-CHAPMAN CO., EUGENE, ORE., 1981

56

Closing Corner for Secs. 6 & 7 only. (NW Cor. Sec. 7)
Found - 1927 GLO 2" I.P., firmly set, projecting 9" above the ground
with a 2½" brass cap, properly mkd.
24" D.Fir stump bears N.61°E., 6.6 ft. with a healed blaze.
24" windfallen D.Fir bears S.17°E., 49.5 ft. with a healed blaze.
14" Grand Fir bears S.7°E., 42.7 ft. with healed blaze. Ren. #494
New BT - 8" Grand Fir bears N.44°E., 56.6 ft. scribed "T25S R1E S6 BT".
5/13/92

57

West 1/4 Corner, Section 7 only.
Found - 1927 GLO brass cap, properly mkd., on 1" I.P., firmly set, flush
with the ground.
30" broken top D.Fir bears N.50°E., 47.5 ft. with a healed blaze.
(Rec. N.49°E., 71 lks.) (1927 BT)
52" uprooted D.Fir bears S.46°E., 43.0 ft. with a burned blaze.
(Rec. S.51°E., 65 lks.) 1927 BT.
42" D.Fir stump bears N.2°E., 14.0 ft. with scribe marks "1/4
S7 CS BT" visible. Ren. No. 19
48" D.Fir stump bears S.78°E., 27.2 ft. with scribe marks
"1/4 S7 CS BT" visible. Ren. No. 19
New BT - 10" D.Fir bears S.59°E., 33.8 ft. scribed "1/4 S7 BT".
4/14/92

58

East 1/4 Corner Section 12 only, of T.25-1W
Found - 1966 DCSO brass cap, properly mkd., on 1½" I.P., firmly set,
projecting 16" above ground. Ren. No. 20
43" Fir bears N.60°E., 10.5 ft. with a healed blaze. (Rec.
N.63°E., 18 lks.) 1896 BT.
21" Fir stump bears N.47°W., 35.0 ft. with a healed blaze. (Rec.
N.49°W.) 1896 BT
36" Fir stump bears S.21°W., 42.4 ft. with scribe marks "12"
visible. (Rec. 60 lks.) 1927 GLO BT.
20" D.Fir bears N.78°E., 24.9 ft. with a healed blaze. Ren. No. 20
1/2" steel tube with 1" survey cap bears S.58°E., 1.6 ft. See
Ren. No. 57 in T.25-1W.
New BT - 9" D.Fir bears S.30°W., 59.9 ft. scribed "1/4 S12 BT".
5/14/92

59

Sec. Cor. for 25 and 36 only, of T.25-1W
Found - 1927 GLO brass cap on 2" I.P. firmly set, projecting 20" above
the ground.
42" Pine stump bears N.23°W., 33.7 ft. with a healed blaze. (1896
23" x 15 ft. tall Pine snag bears S.605W., 106.5 ft. with a
healed blaze. (Rec. 108.3 ft. Ren. No. 10
23" D.Fir bears N.39°W., 42.9 ft. with a healed blaze. (Rec.
42.0 ft.) Ren. No. 10
New BT - 6" D.Fir bears S.25°W., 31.9 ft. scribed "T25S R1W S36 BT".
4/27/92

60

Wit. Corner for Secs. 12 and 13 only, of T.25-1W
found - 1966 DCSO brass cap on 1½" I.P., firmly set, projecting 16"
above ground. Ren. No. 14
12" Yew bears N.26°E., 39.0 ft. with scribe marks "WC CS BT"
visible. 1966 BT.
8" Yew bears N.85°E., 24.9 ft. with scribe marks "WC CS BT"
visible 1966 BT.
1/2" steel tube with a 1" alum. cap is set flush with the south
edge of the 1" BC/IP. Ren. No. 24 in T.25-1W
New BT - 6" D.Fir bears N.42°W., 31.1 ft. scribed "T25S R1W WC S12 BT".
5/15/92

61

Sec. Cor. for Secs. 1 & 12 only of T.25-1W
Found - 1927 GLO 2" I.P., firmly set, projecting 9" above a 30" dia.
mound of stone with a 2½" properly mkd. brass cap.
60" d.Fir stump bears S.48°W., 19.1 ft. with a healed blaze.
32" d.Fir stump bears N.71°W., 26.4 ft. with a healed blaze and
a sheet metal cap over the stump. 1896 BT.
6" W.Fir bears N.59°W., 29.4 ft. with scribe marks visible. (Rec
Hemlock) Ren. No. 16
14" W.Fir snag bears S.74°W., 61.6 ft. with scribe marks visible
New BT - 10" W.Fir bears S.23°W., 73.0 ft. scribed "T25S R1W S12 BT".
5/13/92

Kristian DeGroot, L.S. #1941
For: U.S.F.S. April/May 1992
C.S. File 63/138

Note: All BTs have a 6" red band painted around the tree & the blazed face painted red. U.S.F.S sign 54-3, BEARING TREE, and sign 54-9 LAND SURVEYING MONUMENT, are nailed to all BTs. All new BTs have double blazed faces with a brass washer stamped "PLS 1941" nailed into the lower blaze. Brgs. are taken to the center of the tree at the root crown & dists. are measured to the root crown at the side & center of the tree.

Douglas County Surveyor's Record of
Government Corners Renewed

T 25 S T. S. R 1 E R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

62

Cor. Secs. 26, 27, 34, & 35

Found - 2" O.D. iron pipe buried 12" below the rocked road surface of USFS
Road 4713-500 with a 1927 2½" brass cap properly stamped.

No evidence of Grant's (1957) (Rem #1)

Set - 2½"x30" aluminum monument, 26" in the ground with a ¾"
aluminum cap stamped:

US DEPT. OF AGRICULTURE FOREST SERVICE

T25S R1E

S27 RM

S.29°E., 43.3

1997

PLS 1941

bears N.29°W., 43.3 ft.

Chiseled "X BO" in 3" tall letters in a vertical rock face that bears
S.13°E., 13.35 ft. to the center of the X.

5/8"x30" iron rod with plastic cap "BTS ENG-SUR" bears S.57°W.,
45.7 ft.

9" D.Fir bears N.57°E., 35.1 ft. scribed "T25S R1E S26 BT" with a
brass washer stamped "PLS 1941" nailed in lower blaze.

Painted a 6" red band and BT faces red and nail USFS "BEARING
TREE" and "LAND SURVEY MONUMENT" signs to
bearing trees.

Kristian DeGroot, PLS 1941

For: USFS

Crew: Les Fanning, Matt

Dixon, & Aaron Fanning -

March 1998

C.S. File 65/20-697

63

1/4 Cor. Secs. 27 & 34

Found - 1" O.D. iron pipe, firmly set, projecting 10" above the ground with a
2½" brass cap properly stamped.

30" high stumped D.Fir bears N.31°W., 37.0 ft. w/ healed face. 1927

24" Cedar root crown bears S.25°W., 15.2 ft.

Set - I build a stone mound, 48" dia., base to top of monument.

6" D.Fir bears N.21°E., 12.5 ft. scribed "¼ S27 BT"

6" D.Fir bears S.20°E., 12.5 ft. scribed "¼ S34 BT"

I nail a brass washer stamped "PLS 1941" into the lower blaze of the
new BTs and paint a 6" red band and BT face red and nail
USFS "BEARING TREE" and "LAND SURVEY
MONUMENT" signs to all BTs.