

Douglas County Surveyor's Record of Government Corners Renewed

T 25 T. S. R 2 E E
R. W.M.

MOORE-CHAPMAN CO., EUGENE, ORE. 21881

Dennis Gaylord U.S.F.S.
Douglas Co. Deputy
Surveyor
Witness: Travis Worthen
Sept. 12, 1977
C.S. 59/40

1

1/4 Corner for Secs. 22 and 23.
Found - 1928 U.S. GLO brass cap stamped S.S.G.L.O. 1/4 S22 S23 1928.
(Township & range not on Brass Cap) Pipe is bent 90° & buried.
Removed & straightened pipe, then Re-Set in exact same location.
Orig. 14" D. Fir bears N.31°W., 7.92 ft. is alive & well. Has a
healed blaze.
Orig. 24" now 31" D. Fir bears S.66°E., 31.02 ft. is alive & well
Has a healed blaze. Placed County Bearing tree signs on both.
Replaced Brass cap in exact orig. position. No new accessories.
Note: Corner lies in a partial cut unit, 800 ft. SE of Forest Service
Road #2553.

9/12/77

2

Section corner for Secs. 11, 12, 13 and 14. (W. C.)
Found - Orig. 14" Fir now a 15" D. Fir, corner tree has healed single
blazes on the NE, SE, SW and NW sides.
Orig. 20" now 23" D. Fir bears N.49°W., 10.56, has a single
healed blaze.
Orig. 16" now 17" White fir bears S.19°W., 26.4 ft. some scribing
visible on a nearly healed single blaze.
Orig. 14" now 16" White fir bears S.46°E., 17.82 ft. Some scribing
visible on a nearly healed single blaze.
Orig. 26" now 29" D. Fir bears N.75°30'E., 26.4 ft. has a single
healed blaze.
Set - I set a 1 1/2" iron pipe alongside the corner tree. A 2 1/2" brass
cap, stamped "County Surveyors Office T25S R2E S11 S12 S14 S13
North 1.0 ft. W.C. 1979", is located 1.0 ft. south of the
center of the corner tree.
No new accessories.

5/3/79

3

Section corner for Secs. 3, 2, 10 and 11.(W.C.)
Orig. 8" now 10" corner tree is a cedar with single blazes on the NE, SE,
SW, and NW faces. Scribing is visible in 3 of the blazes, which
are nearly healed. The SE face is healed over completely.
Found - Orig. 12" now 16" Cedar bears N.63°E., 16.3 ft. to center of tree
and 15.84 ft. to face. Scribing visible in a single partially
healed blaze.
Orig. 20" now 28" Cedar bears N.59°W., 30.5 ft. to center of tree
at base and 29.04 ft. to face. Has a single healed blaze.
Orig. 6" now 10" Cedar bears S.46°W., 15.18 ft. scribing visible on
a nearly healed single blaze.
Orig. 10" (?) now 31" Hemlock bears S.38°E., 35.7 ft. scribing
visible on a partly healed single blaze "25 R2 11 T"
Set - I set a 1 1/2" iron pipe with a 2 1/2" brass cap attached. Brass
capped monument is set alongside the corner tree north 0.5 ft.
of the center of the tree. The brass cap is stamped:
"County Surveyors Office T25S R2E W.C. S3 S2 S10 S11 South
0.5 ft. 1979"
No new accessories.

5/3/79

4

Sec. corner common to Sec's. 22, 23, 26, & 27.
Found - 1928 orig. Brass Cap, firmly set, protruding 16" out of the
ground & leaning slightly to the NW, properly marked.
BT's - NOTE: All measurements taken at the point the pipe enters
the ground.
14" Hemlock (orig. 8") with well healed blaze bears N.37°E.,
(Rec. N.45°E.) 24.4-ft.
9" Chinquapin with Forest Service BT Tag, bears N.24°W., 35.6-ft.
(Rec. N.15°W., 30.4-ft.). I chop open and find no trace of
scribing.
No trace of other Orig. BT's.
New BT's- 14" Fir, scribed "T25S R2E S27 CS BT" in double blaze, bears
S.70°W., 51.4-ft.
9" Hemlock scribed "T25S R2E S22 CS BT" in double blaze, bears
N.83°W., 38.7-ft.
34" Fir, bark scribed "T25S R2E S26 CS BT", bears S1°E., 54.8-ft.
Note - Corner lies West of F.S. Rd. No. 2529 (old)...(new) dead end off
of 3816 approx. 350-ft.

9/9/81

Dennis Gaylord, Deputy, Doug. Co. Surveyors
U.S. F. S.
Witness: Bill West
May, 1979
C.S. 60/24

Gregory E. Quibell
Deputy Doug. County
Surveyors Office
Debbie Stewart, witness
Sept. 9, 1981
C.S. 61 / 27