

Douglas County Surveyor's Record of
Government Corners Renewed

T 25 T. S. R 2 E R. W.M. E

MOORE-CHAPMAN CO., EUGENE, ORE. 97501

Dennis Gaylord U.S.F.S.
Douglas Co. Deputy
Surveyor
Witness: Travis Worthen
Sept. 12, 1977
C.S. 59/40

1/4 Corner for Secs. 22 and 23.
Found - 1928 U.S. GLO brass cap stamped S.S.G.L.O. 1/4 S22 S23 1928.
(Township & range not on Brass Cap) Pipe is bent 90° & buried.
Removed & straightened pipe, then Re-Set in exact same location.
Orig. 14" D. Fir bears N.31°W., 7.92 ft. is alive & well. Has a
healed blaze.
Orig. 24" now 31" D. Fir bears S.66°E., 31.02 ft. is alive & well
Has a healed blaze. Placed County Bearing tree signs on both.
Replaced Brass cap in exact orig. position. No new accessories.
Note: Corner lies in a partial cut unit, 800 ft. SE of Forest Service
Road #2553.

9/12/77

Section corner for Secs. 11, 12, 13 and 14. (W. C.)
Found - Orig. 14" Fir now a 15" D. Fir, corner tree has healed single
blazes on the NE, SE, SW and NW sides.
Orig. 20" now 23" D. Fir bears N.49°W., 10.56, has a single
healed blaze.
Orig. 16" now 17" White fir bears S.19°W., 26.4 ft. some scribing
visible on a nearly healed single blaze.
Orig. 14" now 16" White fir bears S.46°E., 17.82 ft. Some scribing
visible on a nearly healed single blaze.
Orig. 26" now 29" D. Fir bears N.75°30'E., 26.4 ft. has a single
healed blaze.
Set - I set a 1 1/2" iron pipe alongside the corner tree. A 2 1/2" brass
cap, stamped "County Surveyors Office T25S R2E S11 S12 S14 S13
North 1.0 ft. W.C. 1979", is located 1.0 ft. south of the
center of the corner tree.
No new accessories.

5/3/79

Section corner for Secs. 3, 2, 10 and 11.(W.C.)
Orig. 8" now 10" corner tree is a cedar with single blazes on the NE, SE,
SW, and NW faces. Scribing is visible in 3 of the blazes, which
are nearly healed. The SE face is healed over completely.
Found - Orig. 12" now 16" Cedar bears N.63°E., 16.3 ft. to center of tree
and 15.84 ft. to face. Scribing visible in a single partially
healed blaze.
Orig. 20" now 28" Cedar bears N.59°W., 30.5 ft. to center of tree
at base and 29.04 ft. to face. Has a single healed blaze.
Orig. 6" now 10" Cedar bears S.46°W., 15.18 ft. scribing visible on
a nearly healed single blaze.
Orig. 10" (?) now 31" Hemlock bears S.38°E., 35.7 ft. scribing
visible on a partly healed single blaze "25 R2 11 T"
Set - I set a 1 1/2" iron pipe with a 2 1/2" brass cap attached. Brass
capped monument is set alongside the corner tree north 0.5 ft.
of the center of the tree. The brass cap is stamped:
"County Surveyors Office T25S R2E W.C. S3 S2 S10 S11 South
0.5 ft. 1979"
No new accessories.

5/3/79

Sec. corner common to Sec's. 22, 23, 26, & 27.
Found - 1928 orig. Brass Cap, firmly set, protruding 16" out of the
ground & leaning slightly to the NW, properly marked.
BT's - NOTE: All measurements taken at the point the pipe enters
the ground.
14" Hemlock (orig. 8") with well healed blaze bears N.37°E.,
(Rec. N.45°E.) 24.4-ft.
9" Chinquapin with Forest Service BT Tag, bears N.24°W., 35.6-ft.
(Rec. N.15°W., 30.4-ft.). I chop open and find no trace of
scribing.
No trace of other Orig. BT's.
New BT's- 14" Fir, scribed "T25S R2E S27 CS BT" in double blaze, bears
S.70°W., 51.4-ft.
9" Hemlock scribed "T25S R2E S22 CS BT" in double blaze, bears
N.83°W., 38.7-ft.
34" Fir, bark scribed "T25S R2E S26 CS BT", bears S1°E., 54.8-ft.
Note - Corner lies West of F.S. Rd. No. 2529 (old)...(new) dead end off
of 3816 approx. 350-ft.

9/9/81

Dennis Gaylord, Deputy, Douglas Co. Surveyors
U.S. F. S.
Witness: Bill West
May, 1979
C.S. 60/24

Gregory E. Quibell
Deputy Douglas County
Surveyors Office
Debbie Stewart, witness
Sept. 9, 1981
C.S. 61 / 27

Douglas County Surveyor's Record of
Government Corners Renewed

T 25 T. S. R 2 E R, . W. M. E

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Dennis Gaylord
U.S.F.S.
Bill West
Oct. 26, 1978
C.S. 59/30

MOVED TO CS 62/50-9

1/4 Corner for sections 10 and 11.

REFERENCED NOTES ONLY

Found - 7" cedar corner tree, is still standing but nearly dead. Unhealed blazes show scribing of "1/4" on the west and "S11" on the east. 11" hemlock snag with a healed blaze bears N.49°30'W., 13.1 (Rec. N.46°W., 11.88 ft.) A 16" cedar snag bears N.62°30'E., 11.9 ft. (Rec. N.59°E., 11.54') Previously opened blaze has scribing "1/4 S11/BT"

This corner falls in a proposed landing & will therefore be destroyed during construction.

New accessories:

A 5/8" x 36" I. rod with a 1 1/2" alum. cap attached bears N.80°30'E., 70.7 ft.

17" cedar bears N.18°E., 56.1 ft. scribed "1/4 S11 CS BT" on a double blaze.

A 5/8" x 36" I. rod with a 1 1/2" alum. cap attached bears N.47°30'E., 64.9 ft.

Placed county BT signs on all 3 BTs and on corner tree.

10/26/78

Section corner for Secs. 16, 17, 20 and 21

Found - 2" diam. iron post, firmly set, projecting 12" above ground, leaning slightly northerly, with 1928 GLO brass cap marked: "T25S R2E S17 S16 S20 S21 1928". Used point where the I.P. comes out of the ground as the corner point.

12" D. fir stump, N.52°E., 9.3 ft. with log alongside with scribe marks "5S 2E S6 BT" visible on partially healed blaze.

12" D. fir, N.16°W., 35.6 ft. with healed blaze.

Set - Added a 2 foot diam. mound of stone. Iron pipe now projecting 4".

New BTs - 6" D. fir, S.41 1/2° E., 12.8 ft. scribed "T25S R2E S21 CS BT"

6" D. fir, S.25 1/2°W., 30.2 ft. scribed "T25S R2E S20 CS BT" on a single blaze.

Note - Corner is in cutting line of old clearcut unit on steep east slope. To reach, proceed up USFS Rd. #3816 approx 2 miles from Steamboat Creek, then follow north boundary of clearcut unit #25-2E-16-1 approx. 1/4 mile to the corner. Corner is about 530 ft. west of 2 small cks.

5/10/83

Section corner for Secs. 18 and 19; and Secs. 13, 24 of T.25-1E.

Found - 1927 GLO brass cap, properly marked, on 2" diam. iron post, firmly set, projecting 6" above ground, leaning westerly, Used the point where the I.P. comes out of the ground as the corner point.

Orig. 26" D. fir, stump, N.31°E., 31.9 ft. (Rec. 32.3 ft.) with healed blaze.

Orig. 44" D. fir, S.28°E., 9.9 ft. with healed blaze.

A roothole, N.38°W., 51.5 ft. with 14" D. fir log alongside with fragmentary scribe marks visible on partially healed blaze.

New BTs - 12" maple, N.78°E., 29.2 ft. scribed "T25S R2E S18 CS BT" on single blaze.

5" W. fir, S.73°W., 26.8 ft. scribed "T25S R1E S24 CS BT" on single blaze.

40" D. fir, N.70°W., 38.3 ft. scribed "T25S R1E S13 CS BT" single blaze. (Blaze is on old logging scar.)

Note: Corner is approx. 250 ft. south of USFS Rd. #3811-100 in the NW corner of clearcut unit #25-2E-19-5. Corner is about 66 ft. north of creek.

5/10/83

Section corner for sections 30 and 31; and secs. 25 & 36 of T.25-1E.

Found - 1927 GLO brass cap, properly mkd., on 2" iron post, firmly set, projecting 6" above the ground.

A 20" D. fir, N.32°E., 40.9 ft. with healed blaze.

A 21" R. cedar, S.42°E., 29.6 ft. (rec. 30.4 ft.) with healed blaze.

A 17" W. fir, S.56°W., 21.5 ft. (rec. 22.4 ft.) with healed blaze.

A roothole, N.86°W., 21.1 ft. with decayed log, size indeterminate alongside with fragmentary scribe marks visible on decayed blaze.

C O N T . N E X T P A G E

James N. Landrum
U.S. Forest Service
(Deputy, Doug. Co.
Surveyors Office)
Witness: Leonard
Herzstein
May 10, 1983
C.S. 62/10

Jim Landrum, U.S.F.S.
Deputy, Doug. Co.
Surveyors Office
Leonard Herzstein,
Witness.
May 10, 1983
C.S. 62/10

Jim Landrum, U.S.F.S.
Deputy, Doug. Co.
Surveyors Office
Leonard Herzstein,
Witness
May 12, 1983
C.S. 62/10

5

6

7

8

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 2 E. R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 97401

C O N T. _ _ _

Douglas County
Surveyors Office
S. J. Flause and
R. W. Smith, Deputies
March 30, 1988
C.S. 62/50-9

(1/4 Cor. 10 & 11)

set and protrudes approx. 5" above ground and bears N.41½°E., 66.6 ft. (Rec. N.47°30'E., 64.9 ft.)

Set - The corner position is perpetuated by establishing a brass cap monument within the apparent remains of the corner tree. This position agrees well with the well defined remaining evidence of the original northeast bearing tree. Two out of three distances to the references from Renewal #5 agree well with record and the distance to the NNE reference would indicate a possible error in slope measurement. Bearings from corner tree remains to the references from Ren. #5 indicate a possible problem with compass declination. Monument set is a 2 3/8" dia. brass cap marked "Douglas County Surveyors T25S 1/4 S10|S11 R2E 1988" on a 1" I.D. 32" long iron pipe protruding 10" above ground.

New BT - A 17" dia. 2 foot tall cedar stump with a boat spike driven into stump through a bearing tree tag. Boat spike is stamped "B0 1" and bears S.81°W., 24.5 ft. dist. from BC monument.

Monument on a northwest slope at top of clearcut and just off of log landing at turn to east in USFS Road #3850.

3/30/88

12

1/4 Corner for Sections 29 & 30

Found - 2½" dia. properly marked brass cap on a 1" O.D. iron pipe, protrudes 11" above ground. (U.S. General Land Office Survey, 1928; Original corner)

Accessories Found -

14" now 26" dia. D.Fir with a fully healed single blaze, bears N.82°E., 6.0 ft. (rec. N.82°E., 7.9 ft. Distance fits well with a slope measurement). O.B.T.

10" now 11" dia. D.Fir with a fully healed single blaze bears N.28°W., 10.6 ft. (rec. N.32°W., 10.6 ft. Bearing possibly read on wrong side of compass). O.B.T.

New Accessories -

12" dia. D.Fir double blazed and scribed "¼ S29 CS BT" bears S.35°E., 9.5 ft.

9" dia. Maple double blazed and scribed "¼ S30 CS BT" bears S.30°W., 36.4 ft.

1/4 Corner for Sections 29 & 28

Found - 2½" dia. brass cap on 1" O.D. iron pipe, protrudes 14" above ground. (U.S. General Land Office Survey, 1928; Original corner)

Accessories Found -

20" now 24" dia. D.Fir with a fully healed single blaze, bears N.65°E., 40.9 ft. (agrees with rec.) O.B.T.

8" now 9" D.Fir with a fully healed single blaze, bears N.85°W., 42.2 ft. to center of trunk 42.9 ft. to center of root crown. (rec. N.85°W., 42.2 ft.) O.B.T.

New Accessories -

11" dia. W.Fir double blazed and scribed "¼ S29 CS BT" bears S.33°W., 16.0 ft.

21" dia. Maple double blazed and scribed "¼ S28 CS BT" bears N.79°E., 35.0 ft.

Douglas County
Surveyor's Office
Randall Smith
Stephen Flause
Nov. 6, 1996
C.S. File 65/9-32

Douglas County
Surveyor's Office
Randall Smith
Stephen Flause
Nov. 6, 1996
C.S. File 65/9-33

13

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 2 E. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 97501

14

Douglas Co. Surveyor's
Office
Randall Smith
S hen Flause
N 21, 1996
C File 65/9-34

Section Corner for Sections 20, 21, 28 & 29
Found - 2 $\frac{1}{2}$ " dia. brass cap on a 2" O.D. iron pipe protrudes 30"
above ground. A 2 ft. dia. mound of stone is around base.
(U.S. General Land Office Survey, 1928; Original corner)
Accessories Found - (Original bearing trees)
12" now 12" dia. 6 ft. high Cedar stump with an unhealed
single blaze, scribing visible "25S 2E S21 BT" bears
N.67°E., 8.5 ft. (rec. N.67°E., 7.9 ft. dist. to blaze)
16" now 20" dia. 5 ft. high Hemlock stump with an unhealed
single blaze, scribing visible "25 2E S28 BT" bears
S.41 $\frac{1}{2}$ °E., 10.7 ft. (rec. S.39°E., 9.9 ft. dist. to blaze)
16" now 20" dia. 5 ft. high Hemlock stump with an unhealed
single blaze, scribing visible "25 2E S2 BT" bears
S.45°W., 15.1 ft. (rec. S.45°W., 14.5 ft. dist. to blaze)
9" now 9" dia. down and rotted Hemlock with a rotted
unhealed single blaze, bears N.31°W., 17.8 ft. to root
hole. (agrees with rec.)
New Accessories -
5" dia. D.Fir double blazed and scribed "T25S R2E S21 CS BT"
bears N.82°E., 28.2 ft.
5" dia. D.Fir double blazed and scribed "T25S R2E S21 CS BT"
bears N.43 $\frac{1}{2}$ °E., 23.8 ft.
3" dia. Cedar double blazed and scribed "X BT"
bears S.11°E., 11.2 ft.
5" dia. D.Fir double blazed and scribed "T25S R2E S20 CS BT"
bears N.75°W., 6.0 ft.
Note - Will set monument lower at a future date.

15