

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 2 E. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

20

Corner No. 7, of H. E. S. #93.

Found - Corner Stone, in place, mkd: "X" on top & "7 HES 93" on side facing claim.

Orig. 36", now 40" Pine Stump, S. 27° 45' E. 52.1 ft., shows good scar.

Orig. 40", now 50" Fir, alive, N. 69° W. 12.5 ft., opened & scribe vis.

Set - Brass Cap at Cor. in place of Stone, Reset Stone alongside:

County Surveyor's Office, 1969 T 26 S R 2 E Cor. #7 HES 93

New BT's: 8" D. Fir S. 16° E. 40.0 ft. mkd: "7 HES 93 CS BT".

8" D. Fir S. 72° E. 29.9 ft. mkd: "7 HES 93 CS BT".

This corner lies on steep, westerly slope of mountain.

11/5/69

21

Corner No. 8 of HES #93.

Found - No trace of Corner Stone.

Orig. 36", now 48" Fir, alive, N. 10° E. 32.3 ft., shows good scar.

Orig. 30", now 34" Fir Snag, N. 35° E. 91.1 ft., scribe visible on unhealed blaze.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969 T 26 S R 2 E Cor. # 8 HES 93

New BT's: 12" D. Fir N. 84° W. 19.3 ft. mkd: "8 HES 93 CS BT".

14" D. Fir S. 4° E. 21.5 ft. mkd: "8 HES 93 CS BT".

This corner lies on top of spur sloping S.E.

11/5/69

22

Corner No. 1 of H. E. S. #142.

Found - Stump of Orig. Corner Tree & remains of Orig. BT's. Open Corner Tree blaze & find "S142", scribe & reverse.

8", now 10" Cedar, N. 12° W. (Rec. N12E) 32.3 ft., scribe visible.

Ren. #5 BT's. Orig. BT. is N. 12° W. We tag.

10", now 11" Cedar, S. 60° E. 58.1 ft., scribe visible. We tag.

Set - At a Point 5.0 ft. W. of the center of Corner Tree Stump,

Witness Corner, Brass Cap mkd: County Surveyor's Office, 1969 T 26 S R 2 E Cor. #1 HES 142 Wit. Cor. 5 ft. E. to Corner.

Ren. #5 BT's. from Witness Corner: 10" Cedar N. 3° W. 32.1 ft.

11" Cedar S. 61° E. 61.6 ft.

10/24/69

23

Corner No. 2 of H. E. S. #142, common to No. 2, H.E.S. #227.

Found - Orig. 28", now 32" D. Fir Corner Tree with healed blazes on S.W. & S.E. sides, also bark scribed "2 HES 142" on S.W. & "2 HES 227" on S.E.

Remains of Orig. BT's. still in evidence.

14", now 15" D. Fir, alive & in good condition, N. 20° W. 29.7 ft.

16", now 15" D. Fir, alive, healed blaze, S. 14° E. 48.2 ft., We tag.

Set - At Base of Corner Tree on South Side, Brass Cap Mkd:

County Surveyor's Office, 1969 T 26 S R 2 E HES 142 HES 227

I. Pipe & Brass Cap is 2.0 ft. south of center of Corner Tree, Ren. #8

10/24/69

24

U. S. L. M. #142. (This monument used for tie to HES & Section Lines)

Found - 6x3'x2' Conglomerate Boulder, in place, & mkd: "USLM 142 X".

Orig. 14", now 20" D. Fir, alive, S. 80° E. 19.8 ft., shows good scar.

Orig. N.E. BT. gone completely. Orig. N.W. & S.W. BT's. are sawed stump.

Since Corner Stone is in good condition, we Do Not Set Brass Cap.

New BT's: (Bearings & Distances to "X")

15" D. Fir N. 59° E. 8.5 ft. mkd: "USLM 142 CS BT".

20" D. Fir S. 7° E. 25.2 ft. mkd: "USLM 142 CS BT".

This corner lies 50' E. of N.E. end of pond about 60'x120' in size.

The old Illahee Guard Station has been recently torn down.

10/27/69

25

FD. OK 1/85
R. DEAN
M 98-27

RE-RENEWED, SEE CORNER NO. #66

FD. 12/84
R. DEAN
M 98-16
C.S. 58/1004

Vernon "Ray" Tracy
Jack Heritage & V. Perron
Oct. & Nov. 1969 C.S. File 52/43

RE-RENEWED, SEE CORNER NO. #52

FD. 12/84
R. DEAN
M 98-6
C.S. 58/204