

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 2 E. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

31

Corner No. 5, of H. E. S. #178.

Found - No trace of Corner Stone.

Orig. 40", now 42" Pine Snag, S. 29 1/2° W. 27.1 ft., scribe visible on
unhealed blaze.

Orig. 24", now 36" D. Fir, (Rec. Tamarack) Alive, N. 46° 45' E. 66.0 ft.,
shows good scar, We Tag.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969 T 26 S R 2 E
Cor. #5 HES 178

New BT's: 8" W. Fir S. 43° E. 6.9 ft. mkd: "5 HES 178 CS BT".

13" D. Fir S. 25° W. 12.0 ft. mkd: "5 HES 178 CS BT".

This corner lies in power line clearing about 100 ft. E. of a 48" D. Fir,
#115, that has power line attached. Line course S. 80° E - N 80° W.
10/29/69

Corner No. 6 of H. E. S. #178.

Found - Orig. 14", now 28" Pine (decayed Stump) Corner Tree, cut low with
only bottom of axe blaze remaining, dug out center of stump.

Orig. 18", now 19" W. Oak, S. 2° E. 27.7 ft., now Snag, hollow.

Orig. 15", now 16" W. Oak, N. 5° W. 37.6 ft., now stump with "HES BT"
scribe visible on prev. opened blaze.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969 T 26 S R 2 E
Cor. #6 HES 178

New BT's: 8" D. Fir S. 75° W. 30.0 ft. mkd: "6 HES 178 CS BT".

9" D. Fir S. 20° W. 31.8 ft. mkd: "6 HES 178 CS BT".

This corner lies about 50 ft. south of power line.
10/29/69

Corner No. 7 of H. E. S. #178.

Found - Orig. 24", now 26" W. Oak Corner Tree, alive, shows good scar.

Orig. 14", now 16" W. Oak, alive, N. 69° E. 24.4 ft., open & find scribe.

Orig. 14", now 17" W. Oak dead Snag, S. 46 1/2° W. 35.0 ft., shows good
scar at base of cor. tree on south side.

Set - Brass Cap 2.0 ft. from center of Tree: County Surveyor's Office, 1969 T 26 R 2 E
Cor. #7 HES 178

New BT's: 8" D. Fir S. 47° W. 18.4 ft. mkd: "7 HES 178 CS BT".

8" D. Fir S. 33° E. 13.5 ft. mkd: "7 HES 178 CS BT".

This corner lies about 50 ft. S. of power Line. Bear. & Dist. from center
of Corner Tree.
10/29/69

Corner No. 1 of H. E. S. #182.

Found - Orig. 36", now 48" D. Fir Corner Tree, alive, shows good scar
facing claim.

Orig. 42" Pine, now only partial burned out stump, N. 3° 15' W. 100.3 ft.,
scribe marks visible on burned blaze.

Orig. 32", now 40" Pine, alive, N. 13° 45' E. 126.1 ft., scribe visible
on unhealed & burned blaze., We tag.

Set - Brass Cap 4 ft. N. 45° W. of center of Cor. Tree Mkd:
County Surveyor's Office, 1969 T 26 S R 2 E
Cor. #1 HES 182

New BT's: 8" D. Fir N. 41° W. 29.5 ft. mkd: "1 HES 182 CS BT".

13" D. Fir S. 84° W. 26.4 ft. mkd: "1 HES 182 CS BT".

This corner lies on S.E. slope. Bear. & Dists. from old Corner Tree.
10/30/69

Corner No. 3 of H. E. S. #182.

Found - Corner Stone, in place, mkd: "3 HES 182" on side facing claim.

Orig. 18", now 26" Fir Stump, cut low, S. 39° 30' W. 28.4 ft., no scribe.

Orig. 12", now 22" Fir Stump, cut through middle of blaze, S. 60° 45' E.
37.6 ft., scar shows plainly.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969 T 26 S R 2 E
(Reset Stone Alongside) Cor. #3 HES 182

New BT's: 12" Maple S. 84° E. 12.3 ft. mkd: "3 HES 182 CS BT".

12" D. Fir N. 3° E. 25.5 ft. mkd: "3 HES 182 CS BT".

12" D. Fir N. 80° W. 22.5 ft. mkd: "3 HES 182 CS BT".

This corner lies on very steep, westerly slope.
10/30/69

35

FDX
HES 178
Robert Doen
1/1985 498-20
CS 6315-2

Vernon "Ray" Tracy
Jack Heritage & V. Perron
October, 1969
C.S. File No. 52/43

RE-REVIEWED
CORNER #47