

Douglas County Surveyor's Record of  
Government Corners Renewed

T 26

T. S.

2 E

E  
R/W/W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

51

Corner #3, H.E.S. #227

Found - 3/4" brass disc in 1 1/4" I.P. (per C.S. 51/126) at corner  
3 ft. deep in east shoulder of Rd. #4760.

Set - I set a 4" x 4" x 96" creosoted post over the iron pipe.

From which:

- A 1" galv. I.P. with 2 1/2" brass cap bears S.89°57'E., 39.5 ft.  
(Rec. East 40.00 ft.) Ren. #3
- A 13" D. fir, good scar bears N.67°32'E., 65.7 ft. (Rec. N.41 1/2°E., 32.8 ft. per Ren. #3) from W.C. N.39°51'E., 32.8 ft. (my measurement.)
- A 17" Cedar, good scar, bears S.61°29'E., 48.3 ft. (Rec. S.7°E., 23.7 ft. per Ren. #3) from W.C. S.6°45'E., 23.2 ft. (my measurement).

52

Corner #2, common for H.E.S. #142 and #227

Found - 34" D. fir, 2 healed scars bark scribing "2HES 227", "2HES 142"

From which-

- A 1" galv. I.P. with 2 1/2" brass cap bears S.37°00'W., 2.34 ft.  
(Rec. South 2.0 ft. per Ren. #23)
- A 36" P. pine stump, "2 HES 142 BT HES 227 BT" visible, bears S.17°00'W., 29.1 ft. (Rec. S.18°15'W., 29.70 ft. per HES 142)
- A 60" D. fir stump hole bears West 49.0 ft. (Rec. West 50.16 ft. per HES 142).
- A 15" D. fir healed scar bears N.22°10'E., 30.4 ft. (Rec. N.20°W., 29.70 ft. per Ren. 8 and 23)
- A 17" D. fir healed scar, bears S.13°30'E., 48.3 ft. (Rec. S.14°E., 48.18 ft. per Ren. #8)

I ADD: Figures "↗ RM LS 1808" to brass cap.

Corner #5 H.E.S. #142

Found - 1" galv. I.P. with 2 1/2" brass cap in 36" cairn. Ren. #4

From Which:

- A 33" D. fir stump, previously opened face visible, bears N.86°25'W., 16.2 ft. (Rec. N.89°00'W., 16.5 ft. per HES 142)
- A 16" D. fir stump, portion of face visible, bears N.17°20'E., 30.4 ft. (Rec. N.20°E., 30.8 ft. per Ren. #4)
- A 23" rotted D. fir stump bears N.73°05'E., 23.9 ft. (Rec. N.74°20'E., 23.10 ft. per HES 142)
- A 16" D. fir, good scars, bears S.76°12'W., 21.4 ft. (Rec. S.77 1/2°W., 21.4 ft. per Ren. #4)

New BT - A 7" D. fir, scribed "5 HES 142 BT" with a 3/4" brass disc stamped "RLS 1808" nailed low to face, bears S.9°40'E., 35.5 ft.

53

Corner #1, H.E.S. #178

Found - 28" P. Pine scribing visible low.

From Which:

- A 1" galv. I.P. with 2 1/2" brass cap bears S.66°00'W., 1.47 ft. (Rec. West 2.0 ft. per Ren. #27)
- A fallen 14" oak snag bears S.42°00'W., 36.6 ft. (Rec. S.39°40'W., 34.98 ft. per HES 178)
- A 19" D. fir, good scar, bears S.55°20'W., 7.1 ft. (Rec. S.62°W., 7.4 ft. per Ren. #27)
- A 13" D. fir, good scar, bears N.76°00'W., 30.8 ft. (Rec. N.74°W., 31.2 ft. per Ren. #27)
- A 34" D. fir, good scar, bears N.37°40'W., 32.7 ft. (Rec. N.38°16'W., 32.34 ft. per HE S 178).

I ADD: Figures "↗ RM LS 1808" to cap.

54

1/4 Corner for Sections 15 and 16

CORNER REPORT ONLY

Found - 3/4" galv. I.P. with 2 1/2" brass cap marked "US General Land Office Survey Penalty \$350 for Removal 1/4 S16 S15 1929".

From which:

- A 25" D. fir, healed scar, bears N.44°30'W., 32.3 ft. (Record N.45°W., 30.36 ft. per GLO)
- A 35" D. fir, healed scar, bears N.81°15'E., 67.4 ft. (Record N.80°E., 66.00 ft. per GLO.

Cairn built to 36" around the pipe.

55

Robert L. Dean L.S. #1808  
For: U. S. Forest Service  
December 20, 1984  
M 98 - 6  
C. S. 58/204