

Douglas County Surveyor's Record of
Government Corners Renewed

T 26 T. S. R 2 E E
R. W. / W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

60

cont. - - - -

Corner #1, HES #93 cont.)

42" D. fir rotted stump in road fill, "93" visible at 14" center,
N.37°15'E., 62.04 ft. (Rec. N.38°30'E., 62.04 ft. per HES 93.)
36" D. fir stump, S.12°10'E., 41.58 ft. (Rec. S.11°45'E.,
41.58 ft. per HES 93).
22" D. fir, healed scar, S.9°30'W., 107.0 ft. (Rec. S.9°W.
108.24 ft. per Ren. #11)
46" rotted pine stump, N.79°45'W., 72.0 ft. (Rec. N.78°W.,
76.56 ft. per listing survey.)

61

Corner #2, H.E.S. #93

Found - 1 1/2" iron pipe per Ren. #13, 6" deep in driveway

From which:

55" D. fir, healed scar, bears S.87°45'E., 70.3 ft. (Rec.
S.88°E., 69.63 ft. per HES 93)
20" D. fir, healed scar, bears N.69°00'E., 40.4 ft. (Record
N.69°E., 40.26 ft. per Ren. #13.)

New Reference Monument

I set a 2" x 30" magnetic aluminum monument, marked "LS 1808
RM 2 HES 93 S55W 25 ft. T26S R2E 1985", in 36" cairn
N.55°17'E., 25.00 ft.

Corner #3, H.E.S. #93

CORNER REPORT ONLY

At corner location by NE BT per Ren. #14, I found a 3 ft. by 2 ft.
cinder stone, "H" visible, all other marks worn off by road travel, no
marks at corner location,

From which:

Found 2 1/2" brass cap, marked as per Ren. #17A bears
N.84°13'W., 1.60 ft.
18" D. fir, healed scar, bears N.13°00'E., 27.06 ft. (rec.
N.13°E., 27.06 ft. per Ren. #14)
28" D. fir, no marks, bears S.64°34'E., 26.9 ft. (Record
26.10 ft. to face of 12" fir per M 14-5)
24" D. fir, no marks bears N.73°53' W., 31.3 ft. (Record
30.95 ft. to face of 8" fir per M 14 - 5)
20" D. fir, healed scar bears S.2°45'W., 6.1 ft. (Rec. S.2°E.,
5.94 ft. per Ren. #14)
SE corner of cabin bears N.35°50'W., 37.2 ft. (Record N.34 1/2°W.,
36.3 ft. per Ren. #17A.)

I ADD: figures " RM LS 1808 to cap.

63

Corner #4, H.E.S. #93

At corner location by intersection of distances from BT's:

I set - a 3/4" x 36" iron rod in north shoulder of highway, stamped
"LS 1808" on top

From which:

43" D. fir, low healed scar, I open and find a burnt face 16"
deep, I count 70 rings to face, bears N.16°05'W., 58.75 ft. (
(Rec. N.17°10'W., 58.74 per HES 93)
18" D. fir, no marks, I scribe "4 HES 93 BT", bears S.44° 53'E.
121.98 ft. (Rec. per M14-5 S.44°54'E., 121.65 ft. to face of
8" fir.).
11" D. fir, no marks, stake and tack high facing corner, I
scribe "X BT" bears S.41°45'W., 110.99 ft. (Rec. per
M 14-5 110.74 ft. to face of 6" fir.)
a 1/2" galv. I.P. bears N.9°26'W., 32.48 ft. (Rec. N.9°45'W.,
no distance per M14-5, N.9°45'W., 30.37 per M51-51)
a 1/2" galv. I.P. no record, bears S.9°55'E., 64.51 ft.
New BTs- A 22" D. fir, scribed "4 HES 93 BT" bears N.59°20'W., 129.8 ft.
A 17" D. fir, scribed "4 HES 93 BT" bears S.36°30'W., 91.4 ft.
New RM- A 2" x 30" magnetic alum. monument, marked "LS 1808 RM T26S
R2E \4 HES 93 55 ft \ to cor 1985", in 36" cairn, bears
N.9°48'W 30" W., 55.00 ft.

I nail a 3/4" brass disc, stamped "RLS 1808", low to the face of each new
scribed BT.

Robert G. Dean L.S. #1808
For: U. S. Forest Service
January 25, 1985
M 98 - 27
C.S. 63/5