

Douglas County Surveyor's Record of Government Corners Renewed

T 26 T. S. R 2 E E R. W. W. M.

Corner #5, H.E.S. #93  
CORNER REPORT ONLY

FD B.C. 64  
By Mark Heimbürger 7-5-94  
FOR: John Bunn 1994-73 A&B

F.O.K.  
By K. DeGroot  
7-99 M133-29

Found - 1" galv. iron pipe with 2 1/2" brass cap per Ren. #18  
10" x 16" stone marked "5HES93" lies north 0.5 ft. +.  
48" D. fir, healed scar, bears N.66°00'E., 115.5 ft. (per HES 93  
N.66°30'E., 115.5 ft.)  
19" W. oak, burnt & hollow opening faces corner. bears S.24°50'E.,  
194.3 ft. (Rec. S.26°E., 193.4 ft. per Listing Survey)  
7" W. oak, healed scar, bears S.25°00'W., 7.3 ft. (Rec. S.26°W.,  
7.4 ft. per Ren. #18)  
34" D. fir, healed scar, bears N.69°10'W., 46.3 ft. (Rec. N.69°W.,  
46.6 ft. per Ren. #18)

Corner #6, H.E.S. #93

FD B.C. 65  
By Mark Heimbürger 7-5-94  
FOR: John Bunn 1994-73 A&B

F.O.K.  
By K. DeGroot  
9-99 M133-29

Found - 1" galv. I.P. with 2 1/2" brass cap per Ren. #19, from which:  
a 15" x 7" stone, marked "+" bears North 0.5 ft. +.  
11" S. pine windfall, "6HES93CSBT" bears N.76°15'W., 32.5 ft.  
(Rec. N.77°W., 33.0 ft. per Ren. #19)  
17" Oak snag, hollow axed opening faces corner bears  
N.61°20'W., 50.0 ft. (Rec. N.61°20'W., 39.60 ft. per HES 93,  
Rec. N.63°W., 49.50 ft. epr Listing Survey)  
10" W. oak, healed scar, bears N.35°50'W., 25.2 ft. (Rec. N.36°W.,  
25.3 ft. per Ren. #19)  
26" D. fir stump, "6H" visible at 5" center, bears S.54°30'W.,  
67.8 ft. (Rec. S.54°15'W., 36.30 ft. per HES 93)  
New BT - 16" D. fir, scribed "6HES93BT" a 3/4" brass disc stamped "RLS 1808"  
is nailed low to the face, bears N.87°50'W., 47.3 ft.

Corner #8, H.E.S. #93  
CORNER REPORT ONLY

66

Found - 1" galv. I.P. with 2 1/2" brass cap in 24" cairn per Ren. #21  
From which:  
16" D. fir, healed scar, bears N.83°30'W., 19.0 ft. (Record  
N.84°W., 19.3 ft. per Ren. #21)  
52" D. fir, healed scar, bears N.20°00'E., 32.9 ft. (Rec. N.19°30'E  
32.34 ft. per HES 93)  
36" snag, "8HES93BT" visible bears N.35°00'E., 91.1 ft. (Rec.  
N.35°30'E., 91.08 ft. per HES 93)  
48" D. fir stump, bears S.58°30'E., 36.6 ft. (Rec. S.59°E.,  
36.30 ft. per Listing Survey)  
19" D. fir, healed scar bears S.4°45'E., 21.0 ft. (Rec. S.4°E.,  
21.5 ft. per Ren. #21)

Corner #9, H.E.S. #93

67

Found - 1 1/4" x 32" galv. I.P. with 3/4" brass disc stamped "RS 404" per  
Ren. #12 from which:  
a 14" x 13" x 6" stone, marked "H9" lies west 0.5 ft. +.  
43" D. fir stump face visible, bears N.9°19'E., 47.21 ft. (Rec.  
N.8°30'E., 50.16 ft. per HES 93)  
12" D. fir healed scar bears S.78°45'E., 20.3 ft. (Rec. S.79°E.,  
20.46 ft. per Ren. #12)  
36" rotted D. fir stump, bears S.20°15'E., 10.9 ft. (S.19°E., 8.58  
per Listing Survey)  
38" rotted D. fir stump, bears S.46°10'W., 18.4 ft. (Rec. S.48°W.,  
19.14 ft. per HES 93) (N.48°W., per Ren. #12)  
24" D. fir healed scar bears S.81°00'W., 44.4 ft. (Record  
N.81 1/2°W., 44.88 ft. per Ren. #12)  
Set - In place of the 1 1/4" x 32" iron pipe, I set a 2" x 30" magnetic  
alum. monument, marked "LS 1808 9 HES 93 T26S R2E 1985". The  
iron pipe is inside the new monument. The original stone is now  
made part of a 36" cairn around the new monument.

Robert G. Dean, L.S. #1808  
For: U. S. Forest Service  
January 25, 1985  
M 98 - 27 C. S. 63/5