

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 6 E R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1

Clell Goodwin
Lenora Ladig
CS57/36
9/17/75

Section Corner common to Sec. 32 & 33
Found: 14" Pine blazed, scarred over and reopened several years ago showing faint scribe "S BT" on north face from which a 1" IP bears N 17°E, 16.0 ft.
Set: Brass cap on 1 1/2" x 30" IP stamped

DOUGLAS CO. SURVEYOR T27 S
1975 R 6 E

From which; A 14" Pine (original 12" Pine) bears S 75°W., 11.2 ft. The remains of a rotten stump (possible orig. 10" Pine) bears N 57°W., 23.6 ft.
An unrecorded 1" IP projecting 24" above ground and apparently used for the corner bears N 25°W., 13.1 ft.
New: A 16" Pine scribed "T27S R6E S 32 CS BT" in a double blaze bears N 26°W., 49.3 ft.
A 12" Pine scribed "T27S R6E S33 CS BT" in a double blaze bears N 28°E., 64.9 ft.
A thorough search of the area shows no other identifiable remains of the corner or accessories. Compass Declination 20° East.

2

Section corner for Secs. 30, 29, 31 and 32.

Found - No monument found.
A 26", orig. 20" White Pine bears S. 14°W., 16.5 ft. Blaze previously opened, faint scribing visible.
A 12" White Fir is down, Stump hole bears S. 45°W., 21.12 ft. Has a double healed blaze.
A stump hole bears N. 25°E., 16.5 ft.
No trace of NW BT.
Set - By reference to Orig. Pine BT, a 2 1/2" Brass cap 5" above ground stamped: County Surveyor's Office T 27 S R 6 E
1977 S 30 | S 29
S 31 | S 32

Dennis Gaylor, U.S.F.S.
Deputy, Douglas Co.
Surveyors Office
Walt Barton, Witness.
Apr 28, 1977
C.S. 9/31 59/31-35

New BT's- A 19" D. Fir bears N. 10°W., 36.2 ft. Scribed "T27S R6E S30 CS BT" on a double blaze.
A 19" D. Fir bears N. 61°E., 27.8 ft. scribed "T27S R6E S29 CS BT" on a double blaze.
A 14" White Pine bears S. 73°E., 46.5 ft. scribed "T27S R6E S32 CS BT" on a double blaze.
A 20" White Pine bears S. 52°W., 33.8 ft. scribed "T27S R6E S31 CS BT" on a double blaze.

4/28/77

3

Sec. Corner for Secs. 28, 29, 32 and 33.

Found - 3" x 3" x 40" Decayed post lying on ground. No scribing or notching visible. Base of post is very near corner location as determined from accessories. Stripping of top soil did not reveal any evidence of orig. post location.
A 8" Lodge pole pine bears S. 10°W., 11.22 ft. scribing visible on partly healed blazes, "27S R6E S3 T".
A 5" Lodge pole pine snag bears N. 40°E., 17.16 ft. faint indiscernible scribing visible on partly healed blazes.
A 8" L.P. Pine is down. stump hole bears S. 35°E., 43.56 ft. Faint indiscernible scribing visible on partly healed blazes.
A L.P. Pine is down & decayed. stump hole bears N. 35°W., 24.42 ft. No scribing visible on partly healed blazes.
Set - 2 1/2" Brass cap on 1" Gal. I.P. stamped: County Surveyors Office, T27S R6E S29 S28 S32 S33 1977. Monument set by reference to orig. accessories. Placed corner post alongside.
New BT's- A 13" Red Fir bears S. 54°E., 65.2 ft. Scribed "T27S R6E S33 CS BT" on a double blaze.
A 9" L.P. Pine bears N. 69°E., 27.7 ft. scribed "T27S R6E S28 CS BT" on a double blaze.
A 5" L.P. Pine bears N. 50°W., 12.0 ft. scribed "T27S R6E S29 CS BT" on a single blaze.

Note: Blazes on orig. BT's are from shoulder to mid-thigh in height and have two hack marks between the upper and lower blazes.

5/19/77

Dennis Gaylor, U.S.F.S.
Deputy, Doug. Co. Surveyors Office
Witness: Walter Barton
May 19, 1977
C.S. 59/34-21

9