

Douglas County Surveyor's Record of
Government Corners Renewed

T. 19 S. T. S. R. 10 W. R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 97001

9

1/4 Corner to Sec. 32, T19-10W. & Sec. 5, T20-10W.
Set - Iron Pipe with Brass Cap Mkd: RS 239 1/4 S 32 T19-10W.
S 5 T20-10W.

Scribed New BT's: 33" Fir S.72°W. 19.3 ft.
28" Fir N. 61° E. 31.3 ft.

Wilford N.
Haines
Nov. 1965
Map File
M 31 - 6

RE-RENEWED CORNER NO. #40
MICROFILM TO HERE IO/67

10

Section Corner to Sections 27 - 28 - 33 - 34.

Found - Orig. 7", now 16" Fir Corner Tree, now shattered stump,
find scribe & reverse.

Orig. 7" Fir, now 12" Snag, N.30°E. 11.9 ft., opened &
shows scribe.

Orig. 12", now 16" Fir Snag, S.60°E. 16.5 ft. (Rec. 12.5),
shows scar.

Orig. 12", now 30" Fir, S.51°W. 12.5 ft. (Rec. 16.5) alive,
opened to burl wood & Rescribe "T19S R10W S33 CS BT".

Orig. 12", now 17" Fir Snag, N.39°W. 10.6 ft., opened to burl.

At a point 1 ft. west of center of corner stump Set:

Set - Brass Cap Mkd: County Surveyor's T 19 S R 10 W
Office 1968 S 28 | S 27
S 33 | S 34

New BT's: 20" D. Fir N.71°W. 12.0 ft. mkd. T19S R10W S28 CS BT.

22" D. Fir S. 65°E. 48.5 ft. mkd. T19S R10W S34 CS BT.

16" D. Fir N. 89° E. 28.9 ft. mkd. T19S R10W S27 CS BT.

Note - This corner lies on flat at S.W. corner of proposed clear-cut
reported by U.S. Forest Service.

T. McCULLOUGH FOUND COR. IN GOOD CONDITION APRIL 1970 - C.S. 55/148 5/14/68

11

1/4 Corner to Sections 32 and 33.

Found - Original Corner Stone 24x15x10", mkd: "1/4", tipped over.

Orig. 14", now 26" Fir, alive, S.45°E. 9.9 ft., shows good scar.

We Rescribe: "1/4 S33 CS BT".

No trace of other Orig. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 19 S R 10 W
(Set in hole where stone Office, 1969 1/4 S 33 S 32
was tipped out of)

New BT's: 28" D. Fir S.41°W. 7.3 ft. mkd: "1/4 S32 CS BT",

This corner lies on steep S.E. slope in very dense brush. C.S. 60/17

C.S. 60/17 - 10/24/78 - E. ALVARADO - OFFICE - 6/26/69

12

Section Corner to Sections 11 - 12 - 13 - 14.

I find the original S.E. & S.W. BT's. for the corner.

At the indicated position for the tree corner, is an old rotten
stump with a 20" alder beside it on the south. At the position for the
N.E. BT. is another alder, badly broken & rotted. There is no sign
of the N.W. Hemlock BT except a rotted stump. Corner is at the head
of a ravine to the N.E. in large alder area. Corner is about 4 ch. E.
of N-S spur ridge top, about 5 ch. north of E-W spur ridge.

At corner point indicated by the remaining BT's., I drive an
old Iron Well point, 1 1/2 x 30", 18" above ground, under a 2' bank.
This is beside the north edge of a 20" alder which I bark scribe:
on the NE - S12, on the NW - S11, on the SE - S13, on the SW - S14.

26" Fir, scribed S.12FS, N.33°33'E. 92. lks.

Note - There are alder trees at the location of the corner and the
NE Orig. BT. There are no signs of the Orig. markings on these,
but they have the appearance of being sprouts from the broken stumps
of the Orig. trees. Pipe driven on the N. side of the Corner Tree,
Pipe hidden by being under a 2 ft. bank.

SEE REN. No. 13 9/19/58

Alan D. Reid, Forester
Lane County Restored Corners
Filed Feb. 8, 1971
C.S. File No. 53/1

13

1/4 Corner for Secs. 27 and 34.

Found - 2 old blazed trees east of the North fork of Smith River & by E.R. Alvarado
chopping out the blazed and finding them to be 70 & 61 yrs. U.S. Forest Serv.
old; (both trees have been dead at least 7 yrs.). We determined (Siuslaw)
this to be the orig. blaze line. Other blaze line are as recent June to Sept. 197
as 12-25 yrs. old. Calls to toe of slope, old trail & river were M 65 - 63
checked & found to agree with the GLO. C.S. 58/162

A 18" Rotten Alder snag bears N.8°W., 13.01 ft. with face chopped
out. No orig. scribing visible.

A 72" D. Fir (snag 5 ft. high) bears S.55°W., 56.8 ft.

CONT. NEXT PAGE

FD. 6X 7/12/77-21.5.F.S. SEE M 65-43
C.S. 58/162

5/14/68

Jan 78