

Douglas County Surveyor's Record of
Government Corners Renewed

19

T. S.

10

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

29

Section corner for Secs. 25 and 36 only.

REFERENCED OUT DUE TO LOGGING IN AREA

Found - Corner tree, 28" D. fir uprooted.

Brass cap on root wad.

Ren. #2

38" hemlock uprooted

40" D. fir uprooted

Set - At corner point - Set 5 ft. steel post 1 1/2 ft. above ground
Brass cap placed alongside.

New Accessories:

38" hemlock to rootwad bears N.87°W., 33.6 ft.

Uprooted hemlock, determined center of tree. At location
set 5 ft. steel post, bears S.82°W., 47.0 ft.

38" hemlock stump bears S.74°W., 47.3 ft. R.P. 8" x 3/8"
nail. Bearing and dist. to top of nail head.

36" hemlock stump bears S.41°W., 45.5 ft. R.P. 8" x 3/8"
nail. Bearing and dist. to top of nail head.

Referenced point: 43" hemlock snag bears N.71°E., 73.7 ft.
8" x 3/8" nail. Bearing and dist. to top of nail head.

Uprooted 28" D. fir bears N.23°E., 19.3 ft. (to rootwad). Original
corner tree.

40" uprooted D. fir bears N.2°E., 24.1 ft. (to rootwad)

Location: Go up F.S. Rd. #23 approx. 5.0 mile to location poster on North
side of road. From poster go North 10 chains to corner which lies
on North face.

9/24/82

1/4 Corner for Secs. 35 and 34

30

REFERENCED OUT FOR LOGGING.

Found - U.S.F.S. alum cap marked T19S R10W 1/4 34 35 1982 PLS 909. a.#27
23" D. fir bears N.63°E., (To PLS tag) 46.4 ft. scribing visible,

1/4 S35 BT.

17" D. fir bears S.49°W., (to PLS tag) 11.8 ft. scribing visible,

1/4 S34 BT.

Cap removed and stored at Mapleton Ranger District.

Reference Points: (bearings and dists. are to top of nail head)

34" D. fir with 8" x 3/8" nail, bears N.20°30'E., 95.2 ft.

14" D. fir with 8" x 3/8" nail, bears N.80°30'W., 53.0 ft.

25" D. fir with 8" x 3/8" nail bears N.80°E., 35.7 ft.

Location: Go to end of F.S. Rd. #942, continue along P-line (road to be
completed soon) approx. 0.4 mi. Corner is at junction of P-line
2300-942 and 2300-946 (from south) Corner falls on top of ridge.
Referenced out the corner from the center of road being built.

9/10/82

Witness corner for Corner to Secs. 27, 28, 33 and 34.

31

Found - 1" Iron pipe with 1968 County brass cap attached firmly set per
Ren. #10.

Orig. corner tree, now 16" rotted stub with scribing visible.

I.P. bears N.58°29'W., 1.3 ft. from center of corner stump.

(Rec. per Ren. #10, West 1.0 ft.)

Accessories found from Sec. corner:

Orig. 7" fir, now 12" snag with scribing visible in previous
opened blaze bears N.30°E., 11.9 ft.

Orig. 12" now 38" fir with good scar bears S.51°W., 12.5 ft.

Orig. 12" now 20" fir snag, showing previous axe work bears
N.39°W., 10.6 ft.

20" fir per Ren. #10 now 23" with good scar bears N.71°W., 11.0 ft.

22" fir per Ren. #10 now 37" with good scar bears S.65°E., 47.0 ft.
(Rec. 48.5 ft.)

16" fir per Ren. #10 now 18" with good scar bears N.89°E., 27.8 ft.
(Rec. 28.9 ft.)

Set - I add marks "W. C.. to" and "S.58 29 E 1.3 ft." to found
brass cap.

11/16/82

REFERENCED OUT CORNERS BY:
Ernesto R. Alvarado, U.S. Forest Service
Siouxlaw District.
Witnesses: Elwin Price
Sept. 1982
C.S. 59/30

Gregory Quibell
Deputy, Doug. Co.
Surveyors Office
Andy Smith
November 16, 1982
C.S. 62/1