

**Douglas County Surveyor's Record of
Government Corners Renewed**

T.19 S. T.S. R. 10 W. R.W.W.M.

MOKE-CHAPMAN CO., EUGENE, ORE. 21881

35

CONTINUED.....

County Surveyors
Office
Jan. 5, 1984

CC at SW corner of Sec. 31, T. 19 S., R. 9 W. (Tnsp. Corner) Ren. #20
This is a report only--no monuments or BTs were set or scribed.
No Original evidence of the corner mon. or its accessories could be
ascertained at this time.
Sketch - See file for sketch and additional documentation.

1/84

Forrest J. Hales
PLS #453
For: Hales, Forrest
March 30, 1984
M 96 - 35

East 1/4 Sec. Corner for Sec. 36 only.
Set - 5/8" x 40" Iron Rod mkd: F.J.H. 453 from which:
BTs - 40" Red Cedar stump bears S.9°55'W., 93.8-ft. to face.
28" Red Cedar stump bears S.42°36'W., 66.9-ft. to face.
Pd. BTs recorded by Hales in 1978. REN #19
1978 mon. was removed in logging.

RE-RENEWED DEED BOOK NO. #38

3/84

37

Ernesto R. Alvarado
U.S. Forest Service
Witnesses:
David Braley
Jennifer Hawks
May 7, 1984
C.S. 62/15

Section Corner for Secs. 25 and 36 only.
Found - The corner tree is uprooted with brass cap at the base of tree,
on the root-wad. In Sept. 1982, I referenced out the corner
point from the uprooted corner tree and uprooted BTs, so that
the area could be logged. My reference point is S.11°E., 4.6 ft
from the center of the root hole. See Ren. #29
Both BTs uprooted.
40" D. Fir (uprooted) bears N.0 1/2°W., 19.6 ft. (to center of
rootwad.
38" hemlock (uprooted) bears S.86 1/2° W., 48.7 ft. (to center
of rootwad.
Set - Reset old 1964 Douglas County brass cap at the center of root
hole of the corner tree. Cap properly marked. Corner tree
root wad bears N.28 3/4°E., 15.2 ft. to center of rootwad
See Ren. #2
Used the same stumps for BTs as previously used for reference points. Set
3/8" steel rebar on center of all three stumps and an 8" x 3/8" nail using
the corner. Bearings and distances are to the center rebar of the stumps.
New BTs- 43" hemlock stump bears N.78 3/4°E., 77.5 ft. scribed CSBT.
36" hemlock stump bears S.44°W., 50.5 ft. scribed T19S R10W S 36
CSBT.
38" hemlock stump bears S.75°W 51.05 ft. scribed CSBT.
(No stump available in Section 25)
Note: Go up Rd. #23 approx. 5.0 miles to location poster on Section line
post on South side of road. Corner lies N.1°E., 580 ft. on N. slope North
of landing in clearcut.

5/7/84

38

Ernest Alvarado
U.S.F.S.; Deputy,
Doug. Co. Surveyors
Office
Witnessess: Carol
Dickinson; Paul
Smith.
June 25, 1984
C.S. 62/15

1/4 Corner for Section 36 only. (East)
Found - Sandstone, 1.8 ft. x 1.0 ft. x 0.6 ft. with "X" chiseled on
top.
Hales 5/8" re-bar (1984) bears S.59 1/2°E., 13.49 ft. from
original stone. Ren. #19³⁶ (1978 survey, M71-62^{9/1984}
M 96-35)
Original BT, 42" cedar stump bears S.3°W., 100.4 ft. Found
reverse orig. scribing. Stump was rescribed by Hales "BT
1/4 S36".
31" cedar stump (Hales) bears S.32°W., 66.2 ft. open face,
scribing visible "BT 1/4 S36".
Set - County brass cap at exact position of the original stone, marked
DOUGLAS COUNTY SURVEYORS OFFICE T19S R10W S36 1/4 R9W 198
Original stone placed alongside cap. Cap surrounded with stumps.
New Accessories:
3/8" rebars driven into tops of both BT stumps.
Attention and property boundary signs on metal fence posts
placed on line North and South of corner + 4 ft.
Location: From Rd. #48, go 2.8 miles up Rd. #23 to gravel road running S'ly
(in Sec. 35 - clearcut). Drive up road 1.7 miles to where it
forks near East side of clearcut. Go down N'ly fork to landing
at end. From North end of landing, corner lies E'ly 450 ft. in
draw near cutting line. Distances are to top of stumps at rebar.