

Douglas County Surveyor's Record of
Government Corners Renewed

T 19 T. S. R 10 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 97401

Daniel Baker
LS #1978
For: Margaret
Crowell
M 107 - 1
(See CS 63/69 for
Lane Co. Info)

1/4 Corner for Sections 12 and 13
Set - U.S.F.S. Aluminum monument mkd. "T19S R10W 1/4 S12 S13
PLS 1978, 1988"
11" Hemlock, N.80°E., 10.4 ft. scribed 1/4 S12 BT.
9" Hemlock, S.27°E., 30.2 ft. scribed 1/4 S13 BT.
Note: 1/4 Cor. position as per re-estab 2187 (Lane Co.) bears
N.21°15'W., 12.33 ft.

46

RE-RENEWED, SEE CORNER NO. #48

Daniel Baker
LS #1978
For: Margaret
Crowell Filed
M 110-15 5/90
(Correcting
survey M107-1)

Section Corner for Secs. 11, 12, 13 and 14
CORNER REPORT ONLY
Found - Douglas County Brass Cap. Ren. #13 and Ren. #45
24" Fir stump, N.35½°E., 61.5 ft.
38" fir stump, S.36½°E., 56.1 ft.
30" Fir stump, S.6½°W., 39.0 ft.
Note: True corner point bears S.4°38'E., 1.30 ft. At this point found
a 1989 BLM brass cap and 3 new bearing trees:
10" fir, S.5 3/4°E., 27½ lks.
12" fir, S.70¼°W., 25 lks.
10" fir, N.30°W., 20 lks.

47

10/89

1/4 Corner for Sections 12 and 13
Set - 2½" x 31" U.S.F.S. aluminum monument.
11" hemlock bears S.86°E., 14.9 ft.
9" hemlock bears S.32°E., 35.9 ft. See Ren. #46
Note: 5/8" rebar set to mark corner position in C.S. 28557 (Lane Co.)
bears S.53°06'52"E., 6.18 ft.
Corner point from Lane Co. re-estab. 2187 bears N.50°24'13"E., 12.21'
(Position established from bearing trees.)

48

10/89

Les Roberts
For: International
Paper & US Forest
Service.
December 1990
M 111 - 33

Section corner for sec's 33 and 34, and 3 and 4 T. 20 R. 10
Found - 1952 G.L.O. brass cap.
BT's - 12" fir S.53° E., 13.7 ft. (scar vis) 1952 BT.
13" fir snag S.25° W., 7.3 ft. (scar vis) 1952 BT.
14" fir N.28° W., 10.9 ft. (scar vis) 1952 BT.
18" fir N.57° E., 6.4 ft. (scar vis) 1952 BT.
Set - 2½" X 30" aluminum pipe and cap for reference monument.
Brass cap (1952) bears N.89°42'30" E., 63.06 ft. from
reference monument. See renewal # 22

49

12/90

Douglas County
Surveyors Office
R.W. Smith
S.J. Flause
J. Pike
C.S. 64/26
May 6, 1992

1/4 Corner for Section 36; and Sec. 1 of T.20-10
Found - A 2½" dia. 1952 BLM brass cap on a 1½" O.D. Iron pipe firmly
set and protruding approx. 3" above ground.
A 36" Fir, now a fallen and partially rotted fir snag, with
evidence of a fully healed single blaze, the root hole of
which bears N.75°E., 39.6 ft. (as per record)
A 54" Fir now a 45" D.B.H. D.Fir with a fully healed single
blaze bears S.86°E., 53.2 ft. (Rec. S.83°45'E., 52.1 ft.)
(previously recorded dia. appears to be erroneous.)
New BTs - A 55" DBH 80 ft. tall fir snag with a high, open cruisers
blaze bears S.72°W., 57.8 ft.
A 6" DBH Alder bark scribed "1/4 S1 CS BT" bears N.86 3/4°W
30.7 ft. distant.
Monument is on a south slope near bottom of very steep south slope.
Monument on an east-west cutting line with older clear cut to north
Old growth to south. Monument is approx. 200 ft. south from a closed
logging spur road end.

50

5/6/92