

Douglas County Surveyor's Record of  
Government Corners Renewed

T 19

R 8

T. S.

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

20

1/4 Corner for Sec. 36 and Sec. 1 of T.20-8  
Found - 1" I.P. with GLO brass cap "1952".  
44" fir, N.49°E., 53.2 ft.  
15" Fir, S.26 1/2°W., 44.0 ft. (blown down)  
Set - 26" fir, S.36°E., 55.4 ft.

8/82

Donald Peel LS. 752  
For: International  
Paper Company  
Aug. 13, 1982  
M 92 - 77

21

1/4 Corner common to Secs. 15 & 22.

CONDITION REPORT ONLY

Found - 1958 B.L.M. B.C. (no record found).  
BTs - 48" fir bears S.75°W., 30-lks. (Orig.)  
56" stump bears N.50°E., 16-lks. (Orig.) part. scribe visible.  
19" fir bears N.25 1/2°E., 17-lks. (existing scribe).

11/82

SEE Vol. 46  
Pg. 17720

1/4 Corner common to Secs. 22, & 27.

22

CONDITION REPORT ONLY

Found - 1980 B.L.M. B.C. (no record found).  
BTs - 48" stump bears S.39 1/2°W., 19-lks. (Orig.)  
36" fir bears N.26°E., 29-lks. (Orig.)  
15" maple bears S.8°E., 114 1/2-lks. (not of record).

11/82

SEE Vol. 46  
Pg. 17719

23

1/4 Corner for Section 19 and 30

Found - 1 1/4" x 18" threaded bolt with nut buried 6" below ground.  
1" x 26" iron pipe set by Sam Konnie in Feb. 1967. Ren. #4  
24" cedar stump, S.72°E., 33.0 ft. (no marks) 1891 BT, Rec.  
S.70 1/4°E., 33.0 ft.  
48" double fir, N.06°E., 23.0 ft. (no marks), 1891 BT, Rec.  
N.06°E., 23.1 ft.  
40" downed fir, S.56°E., 64.0 ft. (no spike), 1967 BT, Rec.  
S.56 1/2°E., 63.9 ft.  
54" fir stump, N.78°E., 41.2 ft. (to spike) 1967 BT, Rec.  
N.77 1/2°E., 41.5 ft.

Set - 2 1/2" x 30" alum. pipe and cap in location of 1" pipe. Buried  
purple magnetic marker under alum. pipe. Place 1" pipe and  
1 1/4" threaded bolt beside alum. pipe. Cap marked: T19S  
R8W Sec. 19 1/4 + Cor Sec. 30 1985 P.L.S. 1039,

New Accessories:

54" fir stump, N.78°E., 41.2 ft. to 3/8" spike (painted/alum.  
washer).  
Fir root collar, N.10°E., 17.3 ft. to R.R. spike (Painted/alum.  
washer).  
Set metal fence post next to brass cap, Wired land survey mon-  
ument sign to fence post.

Corner lies on steep south slope about 120 ft. north of east-west draw.

Les Roberts  
L.S. #1039  
For: International  
Paper Co.  
Jan. 1985  
M 98 - 19  
C.S. 58/293

24

1/4 Corner for Sections 30 and 31.

Found - 18" burnt fir stump, N.86°E., 9.2 ft. to face. Record N.74 1/2°E.,  
9.2 ft. No marks visible.  
26" cedar stump, S.65°W., 14.5 ft. to face. Record S.65 1/4°W.,  
14.5 ft. Negative scribing visible.  
Set - 2 1/2" x 30" alum. pipe and cap. Buried purple magnetic marker  
under alum. pipe. Pipe set using face measure from original  
BTs. Cap mkd. "T29S R8W S30 1/4 + Cor S31 1985 P.L.S. 1039".  
New BT - 38" fir stump, S.72°E., 29.7 ft. to R.R. spike (painted/alum.  
washer).  
Set metal fence post next to brass cap. Wired land survey monument  
sign to fence post.

Corner lies on steep north slope in newly logged unit.