

Douglas County Surveyor's Record of
Government Corners Renewed

T 19

T. S.

R 8

R. W. W. M.

FOX-CHAPMAN CO., EUGENE, ORE. 97401

25

West 1/4 Corner for Section 30 only.
Found - 1957 GLO brass cap set firmly in ground.
44" fir stump, S. 20 1/4°W., 43.0 ft. (scar vis.), 1891 BT.,
Rec. S.20 1/2°W., 43.6 ft.
15" maple, N.48 3/4°E., 24.2 ft. (scribe vis.) 1957 BT Rec.
N.48 3/4°E., 23.8 ft.
22" hemlock snag, S.11 3/4°E., 11.7 ft. (scribe vis.) 1957 BT,
Rec. S.11 3/4°E., 11.9 ft.
New BT - 24" fir stump, S.78°E., 30.4 ft. to R.R. spike (painted/alum.
washer. Set metal fence post next to brass cap. Wired land
survey monument sign to fence post.
Corner lies on gentle south slope. New logged unit lies to east.

26

Closing corner for Sections 25 and ³⁶~~35~~ only of T.19-9
Found - (1957 GLO brass cap destroyed by cat road.)
50" fir, N.74°W., 18.6 ft. (scar vis.) 1899 BT. Rec.
N.73°W., 19.1 ft.
26" downed fir, S.71°W., 58.1 ft. (scribe vis.) 1957 BT. Rec.
S.71°W., 58.1 ft.
Set - 2 1/2" x 30" alum. pipe and cap. Buried purple magnetic marker
under alum. pipe. Corner set S.0°01'21"W., 152.34 ft. from
found west 1/4 corner of section 30. (See survey M87-78).
New BT - 42" fir stump, S.15°E., 53.7 ft. to RR spike (painted/alum.
washer) Set metal fence post next to brass cap. Wired land
survey monument sign to fence post.
Corner lies in cat road on gentle south slope. New logged unit lies to east.

Les Roberts
L.S. #1039
For: International
Paper Company
January 1985
M 98 - 19
C.S. 58/293

27

Center 1/4 corner for Section 30.
Set - 2 1/2" x 30" alum. pipe and cap. Buried purple magnetic marker
under alum. pipe. Cap marked "T19S R8W Sec. 30 C 1/4 + Cor.
1985 P.L.S. 1039".
1 1/2" iron pipe and cap bears N.77°40'15"W., 8.98 ft. (Pipe
set by International Paper Co. in 1959 during staff compass
survey.
New BTs - 18" fir, N.30°W., 19.9 ft. (painted/scribed/alum. washer)
54" fir, N.89°E., 53.8 ft. (painted/scribed/alum. washer)
Set metal fence post beside alum. pipe. Wired land survey monument sign
to fence post.
Corner lies on top of flat ridge about 20 ft. south of gravel road.

Daniel Baker
LS 1978
For: I.P. Co.
April 30, 1985
M 98 - 55
C.S. 58/289

28

Center 1/4 Corner for Section 26
Set - 2 1/2" x 31" I.P. Co. alum. monument marked "T19S R8W C 1/4
+ S26 PLS 1978 1985".
BTs - 21" fir, N.48°E., 18.4 ft. scribed "C 1/4 S26 BT".
12" fir, S.13°E., 25.0 ft. scribed "C 1/4 S26 BT".
An orange magnetic locator was buried below set monument. BT distances
were measured to a 60 penny spike driven low in the side of the tree.
4/30/85

29

West 1/4 Corner for Section 22
Found - 1952 GLO brass cap setting loosely in the ground, having been
disturbed by recent logging activity.
48" fir stump, S.55°E., 28.4 ft. (scar vis.) 1891 BT. Rec. S.55°E
28.4 ft.
18" maple, S.29°W., 35.3 ft. (scar visible) 1891 BT. Rec.
S.25°W., 34.3 ft.
20" fir, S.83°W., 20.3 ft. (scar vis.) ? BT.
Nail set in rock face, 23.7 ft., 1985 R.P. rec. 23.7ft.
R.R. spike in root collar of 48" fir stump, S.58°E., 25.5 ft.
Rec. S.58°E., 25.5 ft. 1985 R.P.
Set - Re-set 1952 GLO brass cap firmly in ground. Buried purple magnetic
marker under iron pipe. Set metal fence post, with survey
attention sign wired to, beside brass cap.
Painted all BTs red. Corner lies on steep west slope about 250 ft. west of
rock road in recently logged unit. (see C.S. 62/30 file for report of a
1985 referenced out information)

Les Roberts, L.S. 1039
October 4, 1985
C.S. 62/30