

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 19      T. S.      R 9      R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

**36**

Section corner for Secs. 25 and 36 only of T.19-10

Found - The corner tree is uprooted with brass cap at the base of tree, on the root-wad. In Sept. 1982, I referenced out the corner point from the uprooted corner tree and uprooted BTs, so that the area could be logged. My reference point is S.11°E., 4.6 ft from the center of the root hole. See Ren. #24

Both BTs uprooted.

40" D. fir (uprooted) bears N.0 1/2°W., 19.6 ft. (to center of root-wad.

38" hemlock (uprooted) bears S.86 1/2° W., 48.7 ft. (to center of rootwad.

Ernesto R. Alvarado  
U.S. Forest  
Service

Witnesses:

David Braley  
Jennifer Hawks  
May 7, 1984  
C.S. 62/15

Set - Reset old 1964 Douglas County Brass cap at the center of root hole of the corner tree. Cap properly marked. Corner tree root wad bears N.28 3/4°E., 15.2 ft. to center of rootwad. See Ren. #2.

Used the same stumps for BTs as previously used for reference points. Set 3/8" steel rebar on center of all three stumps and an 8" x 3/8" nail facing the corner. Bearings and distances are to the center rebar of the stumps.

New BTs - 43" hemlock stump bears N.78 3/4°E., 77.5 ft. scribed CSBT.

36" hemlock stump bears S.44°W., 50.5 ft. scribed T19S R10W S36 CSBT.

38" hemlock stump bears S.75°W., 51.05 ft. scribed CSBT.

(No stump available in Section 25).

Note: Go up Rd. #23 approx. 5.0 miles to location poster on Section line post on South side of road. Corner lies N.1°E., 580 ft. on N. slope North of landing in clearcut.

5/7/84

1/4 Corner for Section 36 only of T.19-10

**37**

Found - Sandstone, 1.8 ft. x 1.0 ft. x 0.6 ft. with "X" chiseled on top.

Hales 5/8" re-bar (1984) bears S.59 1/2°E., 13.49 ft. from original stone. Ren. #10<sup>34</sup> (1978 survey, M71-62) (M 96-35) (1984)

Original BT, 42" cedar stump bears S.3°W., 100.4 ft. Found reverse orig. scribing. Stump was rescribed by Hales "BT 1/4 S36".

31" cedar stump (Hales) bears S.32°W., 66.2 ft. open face, scribing visible "BT 1/4 S36".

Set - County brass cap at exact position of the original stone, marked DOUGLAS COUNTY SURVEYORS OFFICE T19S R10W S36 1/4 R9W 1984. Original stone placed alongside cap. Cap surrounded with stones.

New Accessories:

3/8" rebars driven into tops of both BT stumps.

Attention and property boundary signs on metal fence posts placed on line North and South of corner ± 4 ft.

Location: From Rd. #48, go 2.8 miles up Rd. #23 to gravel road running S'ly (in Sec. 36 - clearcut). Drive up road 1.7 miles to where it forks near East side of clearcut. Go down N'ly fork to landing at end. From North end of landing, corner lies E'ly 450 ft. in draw near cutting line. Distances are to top of stumps at rebar.

**38**

1/4 Corner for Secs. 34 and 35

Found - A 1957 U.S. Cadastral brass cap on a I.P. protruding 2 in. above ground, properly marked.

24" now a 50" dia. 3 ft. tall rotted cedar stump, no marks visible, bears N.11°W., 15.4 ft. (Rec. N.8°W., 15.8 ft.) Orig.

6" now a 18" dia. maple snag with a previously opened face and possible scribing found, bears N.45°E., 16.1 ft. (Rec. N.59°E., 15.8 ft.) Orig.

13" now a 19" tipped out and down cedar possible scar visible bears N.13°E., 31.8 ft. to root wad. Root hole left by tipped out tree bears N.6°E., 46.1 ft. (Rec. N.6 3/4°E., 44.2 ft.)

New BTs - 3" D. fir double blazed and scribed "X BT: bears S. 74 3/4°E., 21.0

8" alder bark scribed "1/4 S34 CS BT" bears N.70°W., 41.1 ft.

23" alder (dia. measured at 2 ft. high) bark scribed "1/4 S34 CS BT:" bears S.82 1/2°W., 32.8 ft.

Corner lies approx. 160 ft. north of a small creek and on a steep south slope. Monument was accepted as corner, intersection of distances from cap to BTs are near orig. distances.

9/12/84

Douglas County  
Surveyors Office  
Randall W. Smith  
Stephen J. Flause  
Sept. 12, 1984  
C.S. 62/21