

Douglas County Surveyor's Record of
Government Corners Renewed

T 19

T. S.

R 9

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE., 21881

39

Closing corner for Sections 25 and 36 only.
(1957 GLO brass cap destroyed by cat road)
Found - 50" fir, N.74°W., 18.6 ft. (scar vis.) 1899 BT. Rec. N.73°W.,
19.1 ft.
26" downed fir, S.71°W., 58.1 ft. (scribe vis.) 1957 BT. Re
S.71°W., 58.1 ft.
Set - 2 1/2" x 30" alum. pipe and cap. Buried purple magnetic mar
under alum. pipe. Cap marked "T19S S25 S36 T19S S30 C.C
R9W R8W 1985" Corner set S.0°01'21"W., 152.34 ft. from
found west 1/4 corner of section 30. See survey M87-78.
New BT - 42" fir stump, S.15°E., 53.7 ft. to R.R. spike (painted/alum.
washer.) Set metal fence post next to brass cap. Wired
land survey monument sign to fence post.
Corner lies in cat road on gentle south slope. New logged unit lies
to east.

Les Roberts
L.S. #1039
For: International
Paper Company
January 1985
M 98 - 19
C.S. 58/293

40

West 1/4 Corner for Section 30 only of T.19-8
Found - 1957 GLO brass cap set firmly in ground.
44" fir stump, S.20 1/4°W., 43.0 ft. (scar vis.) 1891 BT. Rec.
S.20 1/2°W., 43.6 ft.
15" maple, N.48 3/4°E., 24.2 ft. (scribe vis.) 1957 BT. Rec.
N.48 3/4°E., 23.8 ft.
22" hemlock snag, S.11 3/4°E., 11.7 ft. (scribe vis.) 1957 BT.
Rec. S.11 3/4°E., 11.9 ft.
New BT - 24" fir stump, S.78°E., 30.4 ft. to R.R. spike (painted/alum.
washer)
Set metal fence post next to brass cap. Wired land survey monument sign
to fence post.
Corner lies on gentle south slope. New logged unit lies to East.

Daniel Baker
For: Margaret Crowell
Sept. 19, 1988
M 107-1
C.S. 63/69

41

1/4 Corner for Section 7 only.
Set - U.S.F.S Aluminim monument stamped "T19S 1/4 R10W R9W PLS 1978
1988" *Removed ALUM. MON - set REBAR - POSITION CHANGE
C.S. 63/104 5/90*
New BTs-34" Fir, N.48°E., 115.5 ft. BLM BT.
26" Hemlock, S.72 1/2°E., 59.1 ft. scribed 1/4 S7 BT.
Note: 1/4 Cor. set by BLM in 1958 bears N.37°04'53"E., 74.85 ft.
9/19/88

Michael J. Schwartz
For: USFS-Siuslaw
National Forest
July, 1989
M 108 - 53 A&B

42

1/4 Corner for Sections 9 and 10
Found - 1968 3 1/4" BLM brass cap on a 2 1/2" x 28" iron pipe projecting 13"
out of the ground. Ren. #20
22" Fir stump, S.38°E., 8.1 ft. Healed face (1968 BT)
19" Fir, S.47°W., 25.1 ft. Healed face (1968 BT)
Set - RESET BLM monument 24" in the ground.
Reference monument, a USFS standard monument 26" in the ground
S.2°19'W., 61.0 ft. stamped "RM 1/4 S9 N2-19E 61.0ft. RLS1922
1989".

43

Section Corner for Secs. 9, 10, 15 and 16
Found - 1968 3 1/4" BLM brass cap on a 2 1/2" iron pipe projecting 12" out of
the ground. Ren. #18
15" Fir, N.41°E., 12.2 ft. healed face. (1968 BT)
16" Fir snag, S.25 1/4°E., 27.6 ft. scribing visible. (1968 BT)
24" Fir stump, S.35°W., 17.3 ft. healed face. (1968 BT)
20" Fir, N.38°W., 6.7 ft. healed face (1968 BT)
Set - Reference monument, a USFS standard monument 28" in the ground
N.89°24'W., 50.2 ft. stamped "RM T19S R9W S16 S89-24E 50.2ft
RLS1922 1989".

44

Section Corner for Sections 8, 9, 16 and 17
Found - 1969 BLM brass cap on a 2 1/2" iron pipe projecting 16" aout of
ground.
27" hemlock, N.46 3/4°E., 17.0 ft. scribing visible. (1969 BT)
14" hemlock, S.46 1/2°E., 10.3 ft. scribing visible. (1969 BT)
25" hemlock, S.42 3/4°W., 14.3 ft. scribing visible. (1969 BT)
10" hemlock, N.24 3/4°W., 28.6 ft. scribing visible. (1969 BT)
Set - Reference monument, A USFS standard monument 28" in the ground,
S.89°30'E., 64.3 ft. stamped "RM T19S R9W S9 N89-30W 64.3ft
RLS1922 1989".