

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 20 S. T. S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey, Deputy County Surveyor  
Vern Tracy, Head Chainman  
Clete Putnam, Rear Chainman  
January 1962  
C. S. File No. 49/89

Sec. Corner to Secs. 25 & 36, T20-6W. & Secs. 30 & 31, T20-5W. 27  
Found - Orig. 9" Fir, now 35", N.58°E. 20.5 ft., cut open & find  
good scribing "S". Tree in very good condition.  
Burned Remains of old Fir Snag N. 3°W. 42.9 ft. No scars or  
scribing found.  
Fir Tree, now 40", S.17°E. 5.3 ft., uprooted & down,  
shows good scar.  
Rotted Remnants of S. W. B.T., found good reverse scribing  
visible. Impossible to determine where tree had stood.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T20S  $\frac{S25}{S30}$   
Office, 1962 R6W  $\frac{S36}{S31}$  R5W  
New BT's: 17" D. Fir N.50°W. 37.8 ft. Mkd: T20S R6W S25 DCS BT.  
8" I. Cedar S.56 $\frac{1}{2}$ °W. 11.1 ft. Mkd: T20SR6W S36 DCS BT.  
40" D. Fir S.18 $\frac{1}{2}$ °E. 48.3 ft. Mkd: T20S R5W S31 DCS BT.

Corner to Sections 18 and 19, on range line R6W & R7W. 28  
Found - Fir Tree, 84", S.82°W. 23.1 ft. has been opened previously,  
good scribing "S18" visible on old face. (Todd's Tree).  
Fir Snag, dead several years, N. 5°W. 36.0 ft. (instead of 33.0')  
Bark all gone. Found scribing "S1" on old face, looks like  
Todd's scribing. I believe this is McClung's tree, but  
scribing put on by Todd later.  
No other BT's. found, location in logged over area.  
Set - Brass Cap at Cor. Mkd: Doug. Co. Surveyor's T20S  $\frac{S18}{S19}$  R7W R6W  
Office, 1962  
New BT's: 16" Hemlock S.76°E. 104.0 ft. Mkd: T20S R6W S19 DCS BT.  
8" Hemlock N.40°E. 123.5 ft. Mkd: T20S R6W S18 DCS BT.

$\frac{1}{4}$  Corner to Sections 36, R6W & Sec. 31, R5W. 29  
Found - Fir Tree, now 34", N.23°E. 19.1 ft. This tree has been opnd  
previously & good scribing "4S" visible on old face. Tree  
still in good condition.  
Rotted Remnants of old Fir Stump N.61°W. 116.5 ft. Too far  
gone to find any markings.  
Set - Brass Cap at Corner Mkd: County (Doug.) Surveyor's Office, 1962  
R6W  $\frac{1}{4}$  S36/S31 R5W T20S  
New BT's: 15" Hemlock S.54°E. 17.6 ft. Mkd:  $\frac{1}{4}$  S31 DCS BT.  
7" Hemlock N.63°W. 17.4 ft. Mkd:  $\frac{1}{4}$  S36 DCS BT.  
Note - Corner is on County Line betwn. Doug. & Lane Counties.

West  $\frac{1}{4}$  Corner to Section 30 only. 30  
Found - Old Fir Stump, 26", S.57 $\frac{1}{2}$ °W. 5.9 ft., chopped open old  
scar and found good scribing "S".  
Rotted Base of Stump & roots of Fir S.74°E. 13.2 ft.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962  
T20S R6W W  $\frac{1}{4}$  S30  
New BT's: 8" D. Fir S.10°E. 25.7 ft. Mkd: "  $\frac{1}{4}$  S30 CS BT."  
8" D. Fir N.31°E. 24.7 ft. Mkd: "  $\frac{1}{4}$  S30 CS BT."

East  $\frac{1}{4}$  Corner Section 25, T20S R7W. 31  
Found - Haines" "T" iron & cap at Corner. Also  $\frac{1}{2}$ " Galv. I. Pipe.  
Old Fir Stump S.83°W. 29.0 ft., instead of 32.3 ft. Found  
good scribing, part of "4" & a "B".  
Old Fir Stump S.42°E. 5.3 ft., old face burned away, had  
been previously opened.  
Did not find sandstone called for in old notes.  
8" Fir S.67°E. 30.3 ft. scribed "  $\frac{1}{4}$  S BT".  
8" Double Maple East 18.9 ft. scribed in bark "  $\frac{1}{4}$  S BT".  
Did not set Brass Cap.  
One New B.T.: 4" D. Fir S.58°W. 23.3 ft. Mkd:  $\frac{1}{4}$  S25 CS BT.  
No other trees available.

FD. T-IRON  
+ BTs  
4/91 - D. Peck  
M113-45

RE-RENEWED CORNER NO. #74

RE-RENEWED CORNER NO. #67