

Douglas County Surveyor's Record of  
Government Corners Renewed

T 20 S. T. S. R 6 W. R. W. W. M.

KOKE-CHARMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 20 - 21 - 28 - 29.

Found - Gov't Brass Cap set in 1950

SAME AS COR. #39

Fir S. 34°E. 25.1 ft. Tree in good condition, good scar.

Fir N. 56 1/2°E. 38.2 ft., Tree dead, scribing visible.

Fir S. 31 1/2°W. (Not N. 31 1/2°W.) 18.5 ft. Tree dead, scribe visible.

Hemlock Snag, dead, N. 57°W. 17.2 ft, scribing visible.

Since 3 of the BT's. mkd. in 1950 are now dead, I blaze & scribe

3 new Trees: 8" D. Fir S. 84°W. 40.2 ft. Mkd: T20S R6W S29 DCS BT.

8" D. Fir N. 77°W. 7.8 ft. Mkd: T20S R6W S29 DCS BT.

~~8" D. Fir N. 77°W.~~

13" D. Fir N. 80°E. 28.0 ft. Mkd: T20S R6W S21 DCS BT.

East 1/4 Corner to Section 13 only, T20S R7W - West bndry. T20-6W. 43

Found - 20" Fir, now 40", N. 67°W. 42.2 ft. (slope dist.) Had been chopped open previously & good scribing "S" is visible on small portion of old face.

10" Fir, now 32", East 23.8 ft. (slope dist.) Old scars barely visible.

Set - Brass Cap at Cor. Mkd: Doug. Co. Surveyor's Office, 1962

T20S R7W 1/4 S13

New BT: 16" D. Fir S. 16°W. 15.1 ft. Mkd: 1/4 S13 DCS BT.

1/4 Corner between Sections 18 and 19. 44

Found - One BT., a 32" Fir given in the GLO Notes as a 22" Fir bearing N. 15°W., 25 lks. from a small Fir mkd. for the 1/4 Sec. Post. The tree mkd. for the post has uprooted and slid down the slope so in its place I set:

Set - 4" Dogwood Post Mkd: 1/4 S C.S., and mkd. following BT.:

42" R. Fir mkd: 1/4 S C.S. B.T. bears S. 40°W. 21 lks.

Section Corner to Sections 17 - 18 - 19 - 20. 45

Found - One Orig. BT., a 12" Fir, uprooted but with the marks S19 still plain in the wood. From this tree I set:

Set - 4" Dogwood Post mkd: S17, S18, S19 and S20 C S, and from it I marked 4 new BT's:

18" R. Fir mkd: T20S R6W S17 CS BT. bears N. 38°E., 38 lks.

30" R. Fir mkd: T20S R6W S18 CS BT. bears N. 70°W. 47 lks.

6" Yew mkd: T20S R6W S19 CS BT. bears S. 47°W. 90 lks.

24" R. Fir mkd: T20S R6W S20 CS BT. bears S. 24°E. 54 lks.

Section Corner to Sections 13 - 14 - 23 - 24. 46

Found - No trace of corner post set 1872 nor N.W. BT. - SE BT.

14" Fir S. 55°W. 9.9 ft., now 19" Fir Snag, scribed "S23" visible.

Set - 5/8" Monel Pipe.

New BT's: 46" Fir Snag S. 7°W. 21.6 ft. Mkd: with "W" nail & plate.

42" Fir Stump N. 17°W. 16.8 ft. Mkd: with "W" nail & plate

36" Fir S. 64°W. 30.5 ft. Mkd: with "W" nail & plate.

Note - Calls from Corner given in C. S. File No. 53/1

Section Cor. to Sec. 7 & 18, T20-6W. & Secs. 12 & 13, T20-7W. 47

Found - Orig. 9" Fir, now 26" Fir N. 46°E. (should be S. 46°E.) 21 lks or 13.9 ft.

scribing visible. Orig. 40" Fir, now 48", N. 6°E. 11 lks. or 7.3 ft.,

faces not chopped out. 60" Fir, 64" now, S. 34°W. 69.3 ft.,

faces not chopped out.

Set - 3"x3"x4' Vine Maple Post, Plates & "W" Nails.

26" Dead Fir S. 49°E. 12.9 ft., Orig. BT.

48" Fir N 3°E. 7.8 ft., Orig. BT.

14" Fir N. 79°W. 30.7 ft. Orig. BT.

Deputy Co. Surveyor, Milo E. Godfrey  
Vernon Tracy and Cleete Putnam  
February 1962  
C. S. File No. 49/89

R. N. Hinkson  
Wit: C. L. Foster  
April 11-12, 1942  
C. S. File No. 53/1  
(Lane County Records)

Weyerhaeuser Co.  
By Glen  
McChesney  
April 1958  
C.S. File  
No. 53/1

Weyerhaeuser Timber Co.  
Lyle E. Boustead, Land Agent  
October 13, 1958  
C.S. File No. 53/1