

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

54

Center of Section 33.
SET - 1/2" Steel Rod
SCRIBED - 24" Fir S. 50° E. 18.0 ft.
24" Fir N. 31° E. 12.5 ft.

Oct. 1966

Wilford N.
Haines
For: Wolley Logging
10/1966
M 32 - 34

MICROFILM TO HERE 10/67

55

1/4 Corner, Sections 28 and 27.
Set - 5/8" Steel Rod
BT's - 8" Fir, S.55°W., 11.2 ft.
12" Fir, N.14°E., 15.3 ft.

January, 1973

Wilford N. Haines
For: Max Dodd
January, 1973
M 50 - 43

56

Section Corner for Sec. 31, T20-6 and Sec. 36, T20-7.
Found - Haines "T" Iron with copper washer attached in
good condition. Ren. #20. from which:
44" Fir, now a stump bears N.57°W., 91.9 ft. bark
scribed "T22S R7W S36 BT".
Note - We rescribe to read T20S instead of T22S.
60" Fir, now a stump bears N.41°30'E., 20.1 ft. bark
scribed "SXXX1 BT"
"X" chiseled in vertical sandstone face with copper
washer nailed to rock above "X" bears S.68°W.,
95.7 ft.

Note - Both BT stumps have been treated with preservative,
bark removed except for scribed portion, and metal
capped. This corner lies approx. 30 ft. east of Smith
River in an area normally flooded in periods of high
water. The 44" stump an "X" are located on the west
side of Smith River.

7/15/74

Gary L. Langlitz
Surveyor's Office
Peter Earle
July 15, 1974
C.S. 57/2

57

1/4 corner to Sec. 31 and Sec.32 See M3-23 & REN.#13
Found- Haines T iron firmly in the ground and two BT's as follows
26" now 30" fir blazed and healed over bears S60°W., 38.0 ft. (call: S60°W.,
38.5 ft)
20" now 24" fir bark scribed "1/4 S31" bears N54°W., 11.9 ft. (call; N51°W.,
11.9 ft.) at the corner we set-
SET- 1" x 30" I.P. with brass cap stamped T20S, R6W
DOUGLAS CO. SURVEYOR S 31 | S32
1976 1/4

with haines "T" iron driven in north of the corner
We do not mark any trees at this time as this area is to be logged. Compass
Declination 20° East 1/8/76

58

SW 1/16 in Section 33.
Found - Haines T iron removed approx. 50' from previous corner position.
1 1/2" iron pipe at fence angle.
20" Fir, low face overgrown.
Reset - Haines T Iron.
Haines 1 1/2" i. P. bears N.34 3/4°W., 415.5 ft.
Center of tree measurement bears S.87°E., 89.6 ft.
Accessories added:
24" Fir bears S.50 1/4°E., 122.8 ft.
Power Pole "7C-158-151" bears N.76 1/2°W., 141.2 ft.

Frank O. Williams
Glen McChesney
For: Weyerhaeuse Co.
Jan. 14, 1975
C.S. 59/11

59

Township corner Secs. 36, 31, 1 and 6 of T.20-6 & 5; and T21-6 & 5.
Found - 1958 Doug. Co. Surveyors brass cap lying on ground alongside road.
Cap mkd: Doug. Co. Lane Co. Ren. #26A

1958
R T 20 S R
6 S36 | S31 5
W S 1 | S 6 W
T 21 S

SBLM 1962

Surveyors Office

Also found hole which brass cap had been pulled out of.

Gregory Quibell
Doug. Co. Surveyors
Office Deputy
John Powell
Randy Smith
5/10/83
C.S. 62/7