

Douglas County Surveyor's Record of
Government Corners Renewed

T 20 T. S. R 6 R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21091

65

1/4 Corner for Section 30 and 29
Found - 1 1/4" Iron pipe with DCSO brass cap dated 1962. Ren #36
12" Fir stump S.61°E, 30.6 ft scribe visible
18" Fir snag S 9 1/2°E, 16.1 ft scribe visible
17" Fir N 82 1/4°W, 8.9 ft closed face BLM tag
22" Fir N 23 1/2°W, 7.2 ft Weyco and GLO tags BT not of record.

Donald Peel
For: Weyerhaeuser Company
June, 1991
M 113 - 45

66

1/4 Corner for Sections 30 and 31
Set - 2" x 41" Iron pipe with brass cap in large mound of stones.
Cap mkd T20S R6W 1/4 S30
S31
PLS 752
1991
BTs - 23" Fir S 31°E, 24.3 ft scribed 1/4 S31 BT
25" Fir S 87°W, 19.7 ft scribed 1/4 S31 BT
38" Fir N 56°W, 23.7 ft scribed 1/4 S30 BT
26" Fir N 52°E, 7.2 ft scribed 1/4 S30 BT

67

1/4 Corner for Section 30 Only
Found - 1 1/4" Iron pipe with DCSO Brass cap dated 1962. Ren. #30
24" Fir N.34°E., 25.0 ft. closed face.
22" rotten Fir stub S.62°W., 7.1 ft. previously opened to visible scribing. (Rec. S.57 1/2°W)
16" Fir ~~S.28 1/2°E.~~, 25.7 ft. closed face-BLM Tag. Not of record. 6/91
S.08 1/2°E PER D. PEEL 9/9/91

68

Section Corner for Sections 25, 26, 35 & 36.
CONDITION REPORT ONLY; SEE RENEWAL # 24.
Found - 3/4" Iron Pipe with Douglas County Brass Cap dated 1961.
18" Fir snag, S.38°E., 14.0 ft. - visible scribing.
rec. S.40°E., 20 lks. - 1872 O.B.T.
rec. S.40°E., 12.7 ft. to "W" nail - 1957 Weyerhaeuser.
37" Fir stump, N.34°E., 35.9 ft.
rec. N.29°E., 34.3 ft. to "W" nail - 1957 Weyerhaeuser.
18" Fir, S.78°W., 28.3 ft.
rec. S.78°W., 28.0 ft. to "W" nail - 1957 Weyerhaeuser.
rec. S.79°W., 28.3 ft. - 1961 Douglas County.
29" Fir, N.41°W., 29.0 ft. - closed face.
rec. N.49°W., 28.9 ft. to "W" nail - 1957 Weyerhaeuser.
rec. N.48°W., 29.6 ft. - 1961 Douglas County.
27"2 Fir, S.21°E., 54.1 ft. - closed face.
rec.S.21°E., 54.0 ft. - 1961 Douglas County.

See BLM
Resurvey
Pg 20370
for 1997 Resurvey
FD OK
Roberts
4/96
M123-60

David H. Wellman
For: Weyerhaeuser Co.
July 1994 M120 - 55

69

1/4 Corner for Sections 35 & 36.
Found - 3/4" Iron pipe, S.10 1/4°W., 3.4 ft. - origin unknown.
6" Fir, N.2°W., 5.3 ft. to pipe - 1978 Drain Dist. BLM.
14" Fir blow down, S.31°E., 19.5 ft. to pipe - 1978 Drain Dist. BLM.
Set - 2 1/2" Brass Cap on 3/4" x 36" iron pipe marked: "T20S R6W 1/4 S35|S36 PLS 2163 1994"
New Accessories -
11" Fir, N.45 1/2°E., 27.6 ft. scribed "1/4 S36 BT"
10" Fir, S.61°E., 35.7 ft. scribed "1/4 S36 BT"
11" Fir, S.33°W., 28.6 ft. scribed "1/4 S35 BT"
12" Fir, N.45°W., 24.0 ft. scribed "1/4 S35 BT"
6' Fence post 1 ft. north.