

Douglas County Surveyor's Record of  
Government Corners Renewed

20

T. S.

7

R. W. W. M.

KOBE-CHARMAN CO., EUGENE, ORE. 21881

Wilford N. Haines  
Surveyor for Wooley  
Logging Co.  
1956.  
Map File No. M 3 - 23.

Section corner to sec. 36, T20S, R7W., and Sec. 31, T20S, R6W. (Township corner to T 20 S, Rgs. 6 & 7 W. - not common with T 21 S, Rgs. 6 & 7 W.)  
Found original bearing tree, a Vine Maple, N.43°E., 15.8 feet.  
Set angle iron at point for corner.  
From which:  
44 inch Fir, N. 57°E., 91.9 feet.  
X in rock cliff, S. 68°W., 95.7 feet.  
60 inch Fir, W. 41°30'E., 20.1 feet. (Had XXXI carved in)

RENEWED CORNER NO. #79

1

James W. Byron, Deputy County Surveyor  
M. Godfrey  
S. Bilow  
May 27, 1958  
C. S. File No. 49/93

Section Corner to Sections 13, 14, 23, & 24.  
Found - 2 Orig. BT's.  
Orig. 6", now 10" rotted stump S.84°E. 11.2 ft., shows scribe marks on old face.  
Orig. 10", now 24" Hemlock N.47°E. 6.6 ft. I open & find good scribing.

No trace of Orig. N. W. BT. found.  
Find 60" Fir bears S. 33°W., 24.7 ft.

Set Brass Cap at Corner Mkd:  $\frac{S14}{S23} | \frac{S13}{S24}$  T20S R7W County Surveyor's Office, 1958

New BT's: 36" Cedar bears N. 2 1/2°E. 41.0 ft. scribed T20S R7W CS BT.  
60" R. Fir bears S. 33°W. 24.7 ft. scribed S23 CS BT.  
14" Hemlock " bears N. 18°W. 81.5 ft. scribed S14 T20S R7W CS BT.  
No trees near in S. E. Quad.

RENEWED CORNER NO. #108

2

Section Corner to Sections 25, 26, 35, & 36. *FO. OK 9/98 BY H. CHRISTENSEN M130-35*  
Found - Four Orig. BT's.

N. W. BT. shows good scar, I do not open.  
Other BT's. now snags, show good scribing. All check distances.  
N. E. Orig. BT. checks record bearing. - S. E. Orig., I find to be S. 54°E. record S. 39°E.  
S. W. Orig. BT. I find to be S. 71°W. record S. 61°W.  
N. W. Orig. BT. N. 19°W. record N. 40°W.

I also find Stone as recorded at Corner. (Martin) (I add CS)  
New BT's: 30" R. Fir bears S. 18°W. 16.0 ft. scribed 363 T20S R7W S35 BT.  
26" R. Fir bears S. 31°E. 13.8 ft. bark " T20S R7W S36 BT (I add CS)  
21" R. Fir bears N. 63°E. 9.0 ft. bark " T20S R7W S25 BT 363 (I add CS)

Set Brass Cap at Corner Mkd:  $\frac{S26}{S35} | \frac{S25}{S36}$  T20S R7W County Surveyor's Office, 1958

3

James W. Byron  
M. Godfrey  
S. Bilow  
May, 1958  
C. S. File #49/20

1/4 Section Corner to Sections 13 & 24.  
Found - Orig. W. C. chised "+ W.C." on sandstone ledge.  
Find Stone that checks size of Orig. corner stone out of ground at corner. I do not find any chised marks on corner stone nor any trace of Orig. BT's.

Set Brass Cap at Corner Mkd:  $\frac{1}{4} \frac{S13}{S24}$  T20S R7W County Surveyor's Office, 1958

New BT's: 12" R. Fir bears N. 43 1/2°E. 20.0 ft. scribed 1/4 S13 CS BT.  
7" R. Fir bears S. 55°E. 26.4 ft. scribed 1/4 S24 CS BT.

RENEWED CORNER NO. #109

4

James W. Byron, Deputy  
M. Godfrey  
S. Bilow  
July, 10, 1958  
C. S. File 49/93.

Section Corner to Sections 26, 27, 34, & 35. *FO. OK 10/95 BY EDWARDS M122-71*  
Found - Two Orig. BT's.

Orig. 60", now 72" Fir Stump. I open & find good scribing "BT", record N. 40°W. I find should be N. 46°W. 52.8 ft.  
Orig. 48", now 60" Fir Stump shows good scar. I do not open. Checks record dist. & bearing S. 32°W. 26.4 ft.

Set Brass Cap at Corner Mkd:  $\frac{S27}{S34} | \frac{S26}{S35}$  County Surveyor's Office, 1958  
T20S R7W

New BT's: 8" Hemlock bears S. 82°E. 5.7 ft. scribed S35 T20S R7W CS BT.  
6" Hemlock bears S. 13 1/2°W. 33.8 ft. scribed S34 CS BT.  
10" Cedar bears N. 12°E. 80.0 ft. scribed S26 T20S R7W CS BT.  
No suitable Trees near in N. W.

5