

Douglas County Surveyor's Record of  
Government Corners Renewed

T 20 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

East  $\frac{1}{4}$  Corner to Section 25 only. 23

Found - Haines' "T" Iron & Cap at Cor. Also  $\frac{1}{2}$ " I. Pipe.  
Old Fir Stump S.83°W. 29.0 ft., instead of 32.3 ft.,  
good scribing, part of "4" & a "B".  
Old Fir Stump S.42°E. 5.3 ft., old face burned away,  
had been previously opened.  
Did not find sandstone called for in old notes.  
8" Fir S.67°E. 30.3 ft. scribed " $\frac{1}{4}$  SBT".  
Double Maple, 8", East 18.9 ft. scribed in bark " $\frac{1}{4}$ S BT".

Did not Set Brass Cap.

Blazed & Scribed one new Tree: 4" D. Fir S.58°W. 23.3 ft. Mkd:  
" $\frac{1}{4}$  S25 CS BT".

No other trees available.

West  $\frac{1}{4}$  Corner to Section 30 only, T20S R6W. # 95 24

Found - Old Fir Stump, 26", S.57°W. 9.9 ft., chopped open  
old scar & found good scribing "S".  
Rotted base of stump & roots of Fir S.44°E. 13.2 ft.  
Set - Iron Pipe with Brass Cap Mkd: County Surveyor's Office, 1962  
T20S R6W  $\frac{1}{2}$ " S30.

Blaze & Scribe new Trees: 6" D. Fir S.10°E. 25.7 ft. Mkd:  $\frac{1}{4}$  S30 CS BT.  
8" D. Fir N.31°E. 24.7 ft. Mkd:  $\frac{1}{4}$  S30 CS BT.

West  $\frac{1}{4}$  Corner to Sec. 19, T20S R6W. 25

Found - Fir, now 26", N.5°W. 13.2 ft., chopped open & found  
good scribing "4".

No trace found of S. E. Bearing Tree.

Set - Brass Cap at Cor. Mkd: Doug. Co. Surveyor's Office, 1962  
T20S R6W  $\frac{1}{2}$ " S19

New BT: 26" D. Fir N.77°E. 14.8 ft. Mkd: " $\frac{1}{4}$  S19 DCS BT"

West  $\frac{1}{4}$  Corner to Section 31, T20S R6W. 26

Found - Fir, now 33", N.55°E. 13.2 ft., chopped open & fd.  
good scribing "4C". Ring count shows scribing to be  
about 90 yrs. This proves it to be McClung's cor. set  
in 1872. Tree in good condition.

No trace found of N. W. B.T.

Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1962  
T20S R6W  $\frac{1}{2}$ " S31

New BT: 20" Fir S.50°E. 35.5 ft. Mkd:  $\frac{1}{4}$  S31 CS BT.

Corner to Sections 25 and 36 only. 27

Found - Sandstone Rock, 16" x 8", about 16" above ground, Mkd. "CC"  
on top. Haines' "T" iron & cap driven alongside. Rock  
& "T" Iron pushed partly over by log which had fallen on  
top of them.

Old Fir Snag, badly rotted, S.12°E. 11.2 ft. with scrbing,  
"6" S31" visible on previously opened old face.

No trace of Orig. S.W. or N.W. Trees found.

44" Fir N.16 $\frac{1}{2}$ °W. 30.0 ft., bark scribed "T20S R6W CC S25  
Haines' metal disc also nailed to tree-BT 363".

New BT: 5" D. Fir S.71°W. 66.3 ft. Mkd: "CS BT".

DID NOT SET BRASS CAP

Milo E. Godfrey, Deputy County Surveyor  
Vernon Tracy  
Clete Putnam  
January 1962  
C. S. File No. 49/89

(See Also H-3)

8

Fed. T Iron  
& BTs - 6/41  
D. Peck - m 113-45

RE-RENEWED. RECORDED NO. # 95