

Douglas County Surveyor's Record of  
Government Corners Renewed

T 20 S T. S. R 7 W R. W. W. M.

KOKE-CHAPMAN CO. EUGENE, ORE. 21881

28

East  $\frac{1}{4}$  Corner to Section 13 only, T20S R7W.  
Found - 20" Fir, now 40", N.67°W. 42.2 ft. (slope dist.) Had been chopped open previously & good scribing "S" is visible on small portion of old face.  
10" Fir, now 32", East 23.8 ft. (slope dist.) Old scars barely visible.  
Set - Iron Pipe with Brass Cap Mkd: Doug. Co. Surveyor's Office, 1962  
T20S R7W  $\frac{1}{4}$  S13  
Blaze & Scribe one new Tree: 16" D. Fir S.16°W. 15.1 ft. Mkd:  $\frac{1}{4}$ S13 DCS BT.

FOOK 9/18 B.H. CHRISTENSEN H130-35

29

Wit. Cor. to  $\frac{1}{4}$  Cor. to Sections 25 and 36.  
Found - Fir Stump, now 40", S.26°W. (instead of S.26°E) 33.0 ft., recently opened, good scribing " $\frac{1}{4}$ S BT" visible on old faces facing to N.E.  
Did not find N.W. Bearing Tree or Corner Rock.  
Corner lies on left (West) bank of Smith River, approx. 10 ft. from present edge of water. 107  
Set - Iron Pipe with Brass Cap Mkd: County Surveyor's Office, 1962 T20S R7W  
WC  $\frac{1}{4}$  S25 30 ft.  
S36 E. to cor.  
New BT's; 7" D. Fir N.87°W. 45.2 ft. Mkd: WC  $\frac{1}{4}$  S25 CS BT.  
9" D. Fir S.55°W. 33.7 ft. Mkd: WC  $\frac{1}{4}$  S36 CS BT.

~~Wit. Corner to  $\frac{1}{4}$  Corner to Sections 25 and 36.  
Found - Fir Stump, now 40", S.26°W. (instead of S.26°E) 33.0 ft., recently opened, good scribing " $\frac{1}{4}$ S BT" visible on old faces, facing to N. E.  
Did not find NW Bearing Tree.  
Did not find Corner Rock.  
Corner lies on left (West) bank of Smith River approx. 10 ft. from present edge of water.  
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1962  
T20S R7W WC  $\frac{1}{4}$  S25 30 ft. E.  
S36 to Corner.  
New BT's: 7" D. Fir N.87°W. 45.2 ft. Mkd: WC  $\frac{1}{4}$  S25 CS BT.  
9" D. Fir S.55°W. 22.7 ft. Mkd: WC  $\frac{1}{4}$  S36 CS BT.~~

30

South  $\frac{1}{4}$  Corner to Section 36.  
Found - Haines "T" Iron & Cap at Corner.  
Fir Stump, now 36", N.12°W. 13.2 ft., previously chopped open & good scribing " $\frac{1}{4}$ " visible on old face.  
No trace of S. E. Bearing Tree. Area has been clean cut.  
No live trees near.  
New BT: 36" Fir Stump N.38°E. 27.2 ft. Mkd: " $\frac{1}{4}$  S36 CS BT."  
Note - Stumps are badly charred but otherwise in good condition.

31

Corner to Sections 35 and 36 only.  
Found - Haines "T" Iron at corner.  
Fir, now 60", N. 6°W. 29.7 ft., previously cut open. Good scribing "35" visible on old face. Haines rescribed this tree (in bark) "T20S R7W S35 BT".  
28" Fir N.32°W. 68.2 ft. scribed by Haines, in wood, "T20S R7W S35 BT".  
Both trees have Haines' metal disc nailed to face.  
New BT: 17" Madrone N.50°E. 51.3 ft. Mkd: T20S R7W S36 CS BT.  
Corner lies on top of spur running N.35°W. about 4 ch. W. of top of ridge NE & SW. No trace found of Orig. N.E. or S.E. BT's.

32

Closing Corner to Sections 2 and 1, T21S R7W - South Boundary of T20-7W.  
Found - Haines "T" Iron, no cap. 30" Fir S.6°E. 27.7 ft., has been previously opened, scribing visible on old face, mostly illegible.  
Stump N.65°E. 17.2 ft. Cut too low to find scars or scribing.  
No trace of S. W. BT's. found.  
New BT: 17" D. Fir S.62 $\frac{1}{2}$ °W. 67.8 ft. Mkd: T21S R7W CC S2 CS BT.  
Haines' has rescribed 30" Fir S.6°E. 27.7 ft., "S1 BT" in bark.

Milo E. Godfrey, Deputy County Surveyor  
Vernon Tracy & Cleto Putnam  
February 1962 and March 1962  
C. S. File No. 49/89

Godfrey & Crew  
May 1962  
C.S. File No. 49/20