

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 20 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

see 1949 Resurvey  
B.L.M.

R. N. Hinkson  
Wit: W. Lyons  
March 12,  
1943  
J.S. File No.  
53/1

1/4 Sec. Cor. to Sec. 34, only, South Bdy., T19S R7W.  
Only one of the Orig. BT's. were standing at this corner. It was  
a White Fir, 30" diam., with the scribe marks nearly rotted away.  
From this BT., I Set a 4" Hemlock Post Mkd: C.S. 1/4 S34 on the North  
face & mkd. a new BT: 72" Fir mkd: CS 1/4 S BT., bears N. 53° W., 18 lks.  
As this is the 1/4 Corner for Section 34 only, I did not mark a new  
Bearing Tree in Section 3.

38

International  
Paper Co.  
By W.F. Dailey  
Sept. 1957  
C. S. File  
No. 53/1

Closing Corner to Sections 2 and 3, T20-7W.  
Because of road to be constructed, it was necessary to remove the  
monument (1 1/8" iron rod & 2 BT's.) to the corner of Secs. 2 & 3, T20-7W.  
Prior to removing the monument we marked new BT's. as follows:  
30" Fir bears S. 69° 15' E., 83 lks. dist., Mkd: T20S R7W S3 BT.  
48" Cedar bears S. 53° 45' W., 137 lks. dist. mkd: T20S R7W S4 BT.  
Original BT's. remain as follows:  
64" Fir bears N. 17° E., 75 lks. dist., plainly blazed & healed.  
When the road construction was complete the monument (1-1/8" iron rod)  
was firmly set in the road bed, the top of which is flush with the  
top of the road subgrade.

39

Wilford N Haines  
For H. Woolley  
Jan. 21, 1958  
Map File M 8 - 31

C. C. For Secs. 33 and 34, <sup>T. 20-7</sup> ~~T21-7W.~~  
Set Lot Maker, 1" X 36" T. Rod at corner point with brass cap inscribed,  
"Wilford N. Haines, Survey Point 239"  
from Original Bearing Trees.

40

Milo E.  
Godfrey  
Stoffel  
& Stone  
Feb. 11, 1964  
C. S.  
File No.  
49/89

Section Corner to Secs. 23 - 24 - 25 - 26.  
Found - Haines' "T" Iron and Cap. (See Ren. #7)  
36" Fir Stump N. 2° E. 11.9 ft. scribing visible on old face.  
Fir Tree N. 18° W. 13.2 ft., uprooted & dead.  
24" Fir S. 20° W. 17.8 ft., broken off approx. 6 ft. above  
ground, top splintered.  
26" Fir S. 38° E. 17.5 ft., now dead snag, approx. 50 ft. high.  
New BT's: 14" Red Cedar N. 69° W. 48.6 ft. Mkd: T20S R7W S23 CS BT.  
20" Red Cedar S. 26° W. 61.3 ft. Mkd: T20S R7W S26 CS BT.  
Note - Corner is approx. 40 ft. East of small branch of Panther Creek  
and 80 ft. West of logging road.  
No trees available East of Line.

FO. OK BY R. WARD, MAR. 2001  
M 136-60 & CS 65/36-17B

41

Wilford N. Haines  
Corners Found by M. E. Godfrey, Deputy  
February 1962  
C. S. File No. 49/89 Haines Map M 21 - 72

Closing Corner to Sections 30 and 31, T. 20 S. R. 6 W.  
Found - Sandstone Rock, 16 x 8 x 12 ins. above ground, firmly set,  
1 notch on S. side, "+" & "CC" on top.  
Haines' "T" Iron alongside Rock.  
42" Fir N. 30° E. 16.6 ft. (instead of N. 37 1/2° E. 12.5 ft.)  
prev. opnd. scrbing. vis. on old face. Tree in good condition.  
42" Fir S. 63° E. 12.6 ft. (instead of S. 56° E. 14.5 ft.) Shows very  
good scr. Did not open. Tree in good condition.  
38" Fir Stump S. 37° W. 47.5 ft. (instead of S. 34° W. 49.5 ft.)  
Chopped open & fd. bottom of old scar with axe marks just below  
top of stump. Apparently scribing all on log which was gone.  
No trace of Maple to N. W.  
Note - Weyerhaeuser Marked following trees with "W" Nails & Plates. (1963)  
42" Fir N. 31° E. 15.0 ft. (Orig. BT.) Wm L. Wilt (C.S. 53/102)  
42" Fir S. 67° E. 10.8 ft. " "  
38" Fir Stump S. 37° W. 46.0 ft. " "  
4" Chinquapin N. 66° W. 13.0 ft.

FO. T. Iron & Rock  
3 BTs - D. Peel  
49/1113-45

SEE ALSO HAINES F.O. H-3

42

C. C. to Sections 19 and 30, T20-6W. Corner Found O. K.  
Found - Haines' "T" Iron at Corner  
Orig. 7", now 60" Fir N. 73° E. 11.2 ft. Prev. opnd. & good scribing  
visible. Apparently bark scribed "T20S R6W S19 BT 363".  
18" D. Fir S. 69° E. 40.2 ft., scribed in wood, pitched over,  
cannot read scribing. About 4 years old.  
Stump Hole & Maple Shoots S. 32 1/2° E. 20.5 ft.  
No trace of Orig. N. W. or S. W. BT's.

43