

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 7 W R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Sec. Cor. Sections 29-30-31-32 (continued)

New BT's: 8" Hemlock S. 21° E. 20.4 ft. mkd. T20S R7W S32 CS BT.

17" Maple N. 26° W. 39.9 ft. Mkd: T20S R7W S30 CS BT.

Note - This corner lies on East edge of Canyon at toe of W. slope,
20 ft. East of small creek, Corner N. of S. edge of
Oxbow fire.

57

Wit. Cor. $\frac{1}{4}$ Corner to Sections 21 and 28.

Found - Brass Cap & BT's. as recorded in Ren. #17 & #35.

Orig. Dead Fir Snag N. 2° W. 18.5 ft., now badly burned,
no scribe found.

Haines' 18", now 24" D. Fir N. 57 $\frac{1}{2}$ ° E. 292.5 ft., burned
scribe " $\frac{1}{4}$ "B" visible on nearly healed blaze. Haines'
button on face. Tree will probably die.

Haines' 12", now 14" D. Fir S. 69° W. 79.4 ft., healed blaze,
Alive, only slightly burned.

Note - Bearing & Distances above are to true $\frac{1}{4}$ corner.

15" R. Cedar, now dead, N. 30° W. 18.9 ft., burned out 75
inside, no scribe.

Haines' S.W. BT. bears S. 25° W. 32.8 ft. Alive & good cond.

New BT: 30" D. Fir N. 3° E. 7.0 ft. mkd. W.C. $\frac{1}{4}$ S 21 CS BT.

Note - Brass Cap only slightly burned mkd. 1962, 60 ft. E. to Cor.

Witness Corner lies approx. 100 ft. west of centerline of Yellow
Point Road on very steep, East slope.

Original Corner falls in slide area. No "T" Iron found.

58

Sec. Cor. to Sections 20 - 21 - 28 - 29.

Found - "T" Iron & BT., See Ren. #12.

Orig. 10", now 34" Hemlock N. 69° W. 52.1 ft., burned out inside,
No scribe found. Alive.

Haines' BT., 24" Red Cedar N. 16° W. 71.4 ft., dead, burned,
scribe burned off. Haines' button on face.

All other BT's. destroyed. 73

New BT's: (only slightly burned, both alive)

24" Hemlock N. 81° W. 67.0 ft. mkd. T20S R7W S20 CS BT.

22" D. Fir S. 86° W. 94.9 ft. mkd. T20S R7W S29 CS BT.

Note - No other BT's. available due to Oxbow burn. Corner lies on
south slope, approx. 150 ft. N. of small creek, cors. west.

Sept. 8, 1966

59

Sec. Cor. to Sections 17 - 18 - 19 - 20.

Found - Haines' "T" Iron at Corner, See Ren. # 8.

Orig. 36", now 43" Fir S. 52° E. 53.5 ft., now burned stump,
faint scar. We do not open.

Orig. 36", now 48", Fir S. 14° W. 17.8 ft., recorded S. 26° W.
Open & find scribe marks.

No trace N.E. nor N.W. BT's.

Set Brass Cap at point of intersection of distances from remaining BT's.

Set - Brass Cap at Cor. Mkd: County Surveyor's
Office 1966

T 20 S	R 7 W
S 18	S 17
S 19	S 20

Reset "T" alongside Brass Cap & Red Steel Fence Post.

No live trees available for BT's., so rescribe originals:

48" Fir Stump S. 14° W. 17.2 ft. mkd. T20S R7W S19 CS BT.

43" Fir Stump S. 52° E. 53.5 ft. mkd. T20S R7W S20 CS BT.

Note - This corner lies on very steep N. slope on E.-W. cutting line.

60

$\frac{1}{4}$ Corner to Sections 17 and 20.

Found - Haines' "T" Iron at Corner, See Ren. # 9.

Orig. 50"?, now 43" Fir N. 49° W. 23.8 ft., recorded as N. 44° W.
Alive, shows faint scar. We do not open.

Orig. 30"?, now 58" Fir S. 34° E. 19.1 ft., now Snag, we open

Vernon "Ray" Tracy
J. Heritage & J. Rabe-Frank Young (BIM)
Sept. 1966
C. S. File No. 54/22

RE-RENEWED SEE CORNER NO. 73