

Douglas County Surveyor's Record of  
Government Corners Renewed

T20 T.S. R 7 R.W.W.M.

KORE-CHAPMAN CO. EUGENE, ORE. 31851

79

Section Corner for Section 36, T20-7 and Sec. 31, T20-6.  
Found - Haines "T" Iron with copper washer attached in good condition. Ren. # 1, from which:  
44" Fir, now a stump bears N.57°W., 91.9 ft. bark scribed "T22S R7W S36 BT".  
Note - We rescribe to read T20S instead of T22S.  
60" Fir, now a stump bears N.41°30' E., 20.1 ft. bark scribed "SXXX1 BT".  
"X" chiseled in vertical snadstone face with copper washer nailed to rock above "X" bears S.68°W., 95.7 ft.  
Note - Both BT stumps have been treated with preservative. bark removed except for scribed portion, and metal capped. This corner lies approx. 30 ft. east of Smith River in an area normally flooded in periods of high water. The 44" stump an "X" are located on the west side of Smith River.

Gary L. Lan 'itz  
Peter Earle  
Surveyors Office  
July 15, 19  
C.S. 57/2

7/15/74

80

South 1/4 Corner, Sec. 31 of T.19-7.  
Found - 1949 Brass Cap.  
D. Fir stump 32" 4.6 ft. high. bears N.30°W., 9 ft.  
D. Fir stump 40", 3 ft. high. bears N.30°W., 35.5 ft.  
Stumps have been peeled, treated and covered with metal roof and tagged.  
Corner is along cutting line, approx. 200 ft. south of road #20-7-5.3 line crossing tag on road near SW section corner.

Robert J. Walter  
for  
U.S. Department  
of the Interior  
C.S. 58/11  
Oct. 4, 1974

See M87-8 FOR CURRENT STATUS.  
FO. OK 10/95 BY EDUARDO M122

81

Section corner for Secs. 22, 23, 27 and 26.  
Found - 5/8" Iron rod set by Wilford N. Haines in 1967 and a 2" x 10" x 10" rock with "X". Ren. #71  
48" D. Fir, orig. BT with old face & old BT tag. No scribes vis. bears N.7°E., 55.4 ft. (Rec. 62.7 ft.)  
36" Cedar, orig. BT. Badly burned stump, bears S.66°E., 41.0 ft. (Rec. 35.6 ft.)  
48" Maple, possible orig. BT, bears S.84°W., 56.0 ft. (Rec. 42.2 ft.)  
36" Cedar, orig. BT. badly burned face, bears N.55°W., 75.9 ft. (Rec. 77.9 ft.)

Bruce A. Shaner  
For: Woolley Logging  
Aug. 11, 1976  
M 61 - 17

These measurements agree with those made by Haines in 1967. As Haines had been at this same cor. in 1946 & used it again in 1967, I must agree with his position in 1976. Cruiser marks are on several trees around the corner.

New BT's - 28" D. Fir, scribed "T20S R7W S27 BT" bears S.87°W., 24.8 ft.  
28" D. Fir, scribed "T20S R7W S22 BT" bears N.28°W., 33.0 ft.  
14" D. Fir, scribed "T20S R7W S23 BT" bears N.15 1/2°E., 75.2 ft.  
26" D. Fir, scribed "T20S R7W S26 BT" bears S.86°E., 95.3 ft.

8/11/76

82

1/16 Corner for Secs. 22 and 23 (NORTH)  
Found - A 5/8" I.R. as set by Haines (M35-3) is firmly set and protrudes 10" above the ground.  
A 24" Alder now a fallen 26" DBH alder bears S.16°E., 9.0 ft. Tree has fallen on blaze, no scribing is visible.  
A 24" Alder now a 28" DBH alder bears N.03°W., 25.4 ft. (Rec. N.01°W., 25.4 ft-) and is bark scribed 1/16 S22 BT.  
These trees from Haines survey.  
Also an unrecorded bearing tree, an Alder, 11" DBH bears S.01°W., 20.2 ft. and is unmarked except for a BLM bearing tree tag.  
Set - Haines monument is accepted as found.  
New BT - The unrecorded 11" DBH Alder bearing tree (as noted above) is scribed 1/16 S22 CS BT and new DCSO bearing tree tags are added to all bearing trees found.

Stephen J. Flaese  
Deputy, Dou Co.  
Surveyors Office  
Terrie Plou  
Karen Mosle  
May 14, 1981  
C.S. 61/24

5/14/81