

Douglas County Surveyor's Record of  
Government Corners Renewed

T 20 T. S. R 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

89

1/4 Corner to Sections 19 and 20. REN #62  
Found - 1960 GLO Brass Cap, set firmly in ground, with metal fence post alongside.  
36" Fir Stump, N.73°W., 31.4' (Scribe Vis.), 1966 C.S.B.T (Record N.75°W., 28.2')  
New BT - 6" Fir, S.87°E., 24.1' (Scribed/Aluminum Washer/Painted R ).  
Wired survey monument sign to metal fence post.  
Corner lies on Northwest slope about 100' from top of ridge. Ridge runs NE-SW.

90

1/4 Corner to Sections 20 and 29. REN #11  
Found - Haines "T" Iron, (1961), 1" diam.  
26" Fir, N.25°W., 21.0' (Scar Vis.), 1961 BT. Rec. N.26°W., 20.5'.  
35" Fir, S.34°W., 32.0' (Scar Vis.), 1961 BT. Rec. S.34°W., 33.8'.  
New  
Accessories - Replaced "T" Iron with 2 1/2" x 30" alum. pipe and cap. Buried purple magnetic marker under pipe. See filed survey for procedures.  
Set metal fence post, with survey monument sign wired to, beside aluminum pipe.  
Corner lies on South slope about 100' North of small creek.

91

Center 1/4 Corner to Section 20.  
Set - 2 1/2" x 30" alum. pipe and cap. Buried Purple magnetic marker under pipe. See filed survey for procedures.  
New BTs - 6" Fir, S.52°W., 12.9 ft. to spike (Scribed/Aluminum Wash /  
(Accessories) Painted)  
8" Fir, N.52°W., 17.1 ft. to spike (Scribed/Alum. Washer/ Painted)  
Set metal fence post, with survey monument sign wired to, beside aluminum pipe.  
Corner lies on steep north slope about 140' north of dirt road.

92

East 1/4 Corner section 12 only T 20-8  
Found - A 1954 G.L.O. brass cap bent to the West. Properly stamped.  
BT's - A 16" fir stump bears S63 E, 10.2' (scar visible), 1884 BT. rec.  
S65°E, 8.6 ft.  
54" fir stump bears S52°W, 6.2' (no marks). 1954 BT rec.  
N52°W. 4.6 ft .  
44" fir stump bears N51°W, 46.4 ft. (scribe vis.) 1954 BT rec.  
N51 1/2°W, 46.2 ft.  
New Bt - 8" fir bears N14°W, 10.0 ft. (scribed/painted red).  
"R.R." spike in top of 54" fir stump. Stump bears S3°W, 5.3 ft. from corner.  
Set metal fence post, with survey attention sign wired to, beside cap Painted all BT's red. Corner lies on Westslope about 60 ft. East of a small draw.

93

North East Corner Section 12, T20-8  
Found A 1954 brass cap set loosely in the ground about 15' down the hill from original position. Re-set brass cap from original BT's. Brass cap disturbed by logging activity.  
A 30" fir stump bears N50E, 25.1 ft. (no marks)  
1884 BT rec. N47°E, 25.1 ft.  
52" fir stump bears N36 1/2°W, 43.0 ft. (scribe vis.)  
1954 BT rec. N36 1/2°W, 42.2 ft.  
58" fir snag bears S87 1/2°W, 24.4 ft. (scribe vis.)  
1954 BT rec. S87 1/2°W, 24.4 ft.  
Set aluminum fence post, with survey attentionsign wired to, beside brass cap, painted all BT's red. Corner lies on North slope about 250 ft. south of North Sister Creek.

Les Roberts, P.L.S. 1039  
Roberts Surveying, Inc. Eugene  
For: International Paper Co.  
June, 1985  
M 99 - 7, & C.S. 63/18

Les Roberts  
For International  
Paper Co. Dec. 1986  
M 103 - 63