

Douglas County Surveyor's Record of
Government Corners Renewed

20 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Bureau of Public Roads
L. A. Copenhaver
October 17, 1955.
See C. S. File No. 42/27.

$\frac{1}{4}$ corner to secs. 17 & 18.

This corner has been replaced and marked $\frac{1}{4}$ S18 S17 and covered with on foot of cushion material. 1954

Two bearing tree posters and one location poster were obtained from the Bureau of Land Management and placed as follows:

Bearing Tree 10" alder 65.6 feet, N. 77° 00' E., to $\frac{1}{4}$ corner.

Bearing Tree 16" fir 80.8 feet, N. 35° 00' W., to $\frac{1}{4}$ corner.

Location poster on 10" fir with a tack showing location of the tree to the $\frac{1}{4}$ corner and scribed 167.4 feet West to corner.

Also, an old location poster is on a 48" stump which is scribed "T 20 S, R 8 W, S 18, $\frac{3}{4}$ talleys S to corner". A tack shows approx. location of stump to corner. The notice bears the markings:

V X
— III
—

RE-RENEWED SET-CORNER NO. #10

John M. Phillips
June 22, 1959
C.S. File No. 51/26
See sketch in file.

$\frac{1}{4}$ Corner Sections 13 & 14.

Replacement of damaged Bearing Tree:

Found - A Brass Cap

Sec. 14 B.T.: A D. Fir Stub 3' high approx. 8" DBH (Burnt Down) N. 72° W. 16.9 ft. dist.

Sec. 13 B.T.: A Green D. Fir, scroched, but should survive in good shape. 14" DBH S. 58° 30' E. 34.6 ft. dist.

I replaced the destroyed B.T. by:

A D. Fir 5 $\frac{1}{2}$ " DBH N. 10° W. 43.5 ft. dist. mkd. $\frac{1}{4}$ S 13 B.T.

John M. Powell
Joe Brady
Oct. 1965
C. S. File No. 53/66

Wit. Corner for $\frac{1}{4}$ Corner W. Side Sec. 18, only.

Found - Brass Cap, GLO, 1954.

26" Fir N. 41 $\frac{1}{4}$ ° E. 31 lks. scribed $\frac{1}{4}$ S18 BT.

20" Hemlock S. 40 $\frac{1}{4}$ ° E. 5 lks. This tree is blown down.

Set- Brass Cap for Witness Corner 40 ft. West to County Surveyor's Office, 1965 $\frac{1}{4}$ / S18 T20S R8W

New BT's: 12" Hemlock N. 72° W. 7.8 ft. scribed W.C. S18 CS BT.

12" Hemlock N. 40 $\frac{1}{2}$ ° E. 4.3 ft. scribed W.C. S18 CS BT.

Oct. 14, 1965

Vernon "Ray" Tracy
Jack Heritage & E. West
July 31, 1967
C.S. File No. 54/67

Witness Corner to Section Corner Secs. 34 & 35, T20-SW. and Secs. 3 & 2, T21-SW.

Found - 1950 Cadastral Brass Cap, firmly set & properly marked. Burned Stumps of Bearing Trees.

We go 75 ft. south for witness corner & Reset Cadastral Brass Cap and steel fence post alongside, now marked:

W. C. 75 ft. N. to Cor. T20S R8W S 34 | S 35
T21S R8W S 3 | S 2

New BT's: 54" D. Fir Stump N. 30° E. 7.5 ft. mkd. W.C. T20S R8W S35 CS BT.

48" D. Fir Stump S. 47° E. 28.4 ft. mkd. W.C. T21S R8W S2 CS BT.

60" D. Fir Stump N. 51° W. 27.6 ft. mkd. W.C. T20S R8W S34 CS BT.

Note - The old position of this corner was near centerline of new logging access road to be constructed. This witness corner lies on S.W. slope of ridge S.W. of proposed road junction.

MICROFILM TO HERE 10/67

Renew Witness Corner to Sections 34 & 35, T20-SW. and Sections 3 & 2, T21-SW.

We move Witness Corner set in July, 1967, See Ren. #4, above, from its location 75 ft. S. of true corner, 20 ft. N. or 55 ft. south of true corner location.

New BT's: 12" Hemlock Stump N. 38° W. 6.7 ft. mkd. W.C. T20SR8WS34 CS BT.

8" Hemlock Stump N. 12° E. 10.5 ft. mkd. W.C. T20S R8WS35 CS BT.

14" Hemlock Stump S. 88° E. 6.4 ft. mkd. W.C. T21SR8WS 2 CS BT.

Nothing available in Section 3.

We obliterate scribe on BT. stump marked in July, 1967.

Reset - Steel Fence Post alongside Brass Cap.

Note - This W. C. lies in "Y" of new logging roads on top of ridge.

10/31/67

Vernon "Ray" Tracy
Jack Heritage & V. Perroni
Oct. 31, 1967
C.S. File No. 54/67