

Douglas County Surveyor's Record of  
Government Corners Renewed

T.20 S. T. S. R.8 W. R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 97501

23

Section corner for Sections 10,11,14 and 15.  
Found - 1954 G.L.O. brass cap set firmly in the ground.  
Fnd. BTs- 20" Fir stump, S.30°W., 27.5' (scar vis.) Record S.30°W., 27.7'  
(1954 BT)  
22" Fir stump, S.32°E., 4.5' (scar vis.) Record S.31 3/4°E., 4.6'  
(1954 BT)  
40" Fir, N.43°E., 18.0' (scar vis.) Record N.43 1/2°E., 17.8'  
(1967 BT)  
New BTs- 8" Alder, N.89°E., 23.6', scribed/painted red.  
8" Alder, West, 22.4' scribed/ painted red  
9" Alder, N.59°E., 16.6', scribed/painted red.  
Note - Corner lies on S.W. slope about 120' west of spur ridge.  
Ridge bears N.10°W., and S.10°E.

1/18/93

24

1/4 Corner for Sections 11 and 14.  
Found - 1954 G.L.O. brass cap firmly set in the ground w/6' steel fencepost.  
Fnd. BTs- 15" Fir snag, S.57°W., 35.0' (scar vis.) Record S.57°W., 35.6'  
(1954 BT)  
17" Fir snag, N.45°W., 12.0' (scar vis.) Record N.43 1/4°W., 11.2'  
(1954 BT)  
12" Fir snag, S.75°E., 33.3' (scar vis.) Record S.76°E., 33.0'  
(1967 BT)  
20" Fir snag, N.34°E., 17.5' (scar vis.) Record N.34 1/2°E., 17.2'  
(1967 BT)  
New BTs- 6" Fir, S.02°W., 23.3' scribed/painted red.  
7" Fir, N.73°W., 22.0' scribed/painted red.  
Note - Corner lies on south slope about 150' east of ridge. Ridge  
bears N.70°E., and S.70°W.

1/25/93

25

West 1/4 Corner for Section 30 T. 20 S. R. 8 W. only  
Fnd- 1950 G.L.O. Brass cap set firmly in the ground and  
marked "W.C. S 1/4 S 30". True corner bears N 1° 27' E, 7.26'.  
At true corner point I find a 14" rotted fir stub. No marks  
visible.  
New Accessories - 72" alum. post w/ survey mon. sign att., beside brass cap.  
8" Fir, N 76°E, 5.4' (scribed W.C. 1/4 S BT)  
8" Fir, S 03°W, 9.1' (scribed W.C. 1/4 S BT)  
Note - Also found 2 bearing trees ofr true 1/4 corner;  
14" Fir stump, S 85° E, 14.5' (No marks), 1883 BT. Rec. S 85 1/2° E  
13.9'.  
18" Fir stump, N 33° E, 23.9' (Scar vis.), 1950 BT. Rec. N 33° E  
25.7'.  
Painted all bearing trees red. 3/93

East 1/4 Corner for Section 25, T 20 S R 9 W only.

26

Found- 1954 G.L.O. Brass cap set firmly in the ground.  
22" Fir, N 85° W, 15.8' (scar vis.), 1954 BT. Record N 85 3/4° W  
15.8'  
28" Fir, S 12° W, 6.6' (scar vis.), 1954 BT. Record S 13° W, 6.6'  
Set - 72" aluminum post, with land monument survey sign attached to,  
beside brass cap. Painted all bearing trees red.  
Note - Corner lies on West slope about 50' South of the N.W. corner  
of Section 30. See also Vol. 43 Pg 16710 for BLM Renewal. 3/93

1/4 Corner for Sections 19 and 30 T. 20 R. 8 W.

27

Fnd - 1950 G.L.O. Brass cap set firmly in the ground.  
28" Fir stump, N 68° W 15.8' (scar vis), 1950 BT. Record N 68° 3/4 W  
15.8'.  
34" Fir stump, S 20° W 48.5' (scar vis.), 1954 BT. Record S 19° 3/4 W  
48.5'.  
See also Vol. 43 Pg 16747 for B.L.M. Renewal.  
New Accessories -  
8" Fir, S 53° W, 16.2' (Scribed and painted red).  
10" Fir, N 41° W, 30.8' (Scribed and painted red).  
72" aluminum post, with land survey sign attached to, beside brass  
cap.  
Note - Corner lies on West slope about 300' West of gravel logging road.  
3/93

Les Roberts L.S. 1039  
For: International Paper Co.  
Jan.-Feb. 1993  
M 116 - 53  
C.S. 63/149

By: Les Roberts  
For: International  
Paper Co.  
March 1993  
CS 63/149  
M 116 - 60