

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T. 20 S. T. S. R. 9 W. R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Les Roberts  
PLS #1039  
For: International  
Paper Co.  
Dec. 3, 1982  
M 90 - 33

Center 1/4 Corner of Sec. 20. 36  
Set - 1 1/2" x 36" I.P. w/B.C.  
New BTs- 20" fir bears N.85°W., 21.2-ft. (scribed).  
          26" fir bears S.1°E., 23.8-ft. (scribed). 12/82  
1/4 Corner common to Secs. 20 & 29. 37  
Found - 1953 GLO B.C.  
BTs - 24" downed fir bears N.2°E., 32.0-ft. (scar visible) 1953 BT.  
New BTs- 15" fir bears S.38°E., 32.7-ft. (scribed).  
          17" maple bears N.39°E., 38.5-ft. (scribed). 12/82

Les Roberts  
PLS #1039  
For: International  
Paper Co.  
Feb. 1983  
M 93-63 & M 93-64

Center 1/4 Corner of Sec. 15. 38  
Set - 1 1/2" x 36" Iron Pipe and Brass Cap.  
New BT's- 23" fir bears N.77°E., 32.2-ft. (scribed / set washer).  
          28" fir bears N.15°W., 54.5-ft. (scribed / set washer).

South 1/4 Corner common to Secs. 14, & 23. 39  
Fd. - 2 1/2" I.P. set in 1960. Ren. # 2.  
BT's - 24" cedar stump bears S.65°E., 5.9-ft. (no marks)...1891 BT.  
          34" fir stump bears N.44°W., 16.5-ft. (no marks)...1891 BT.  
          60" fir stump bears N.74°W., 13.2-ft. (scribe vis)...1953 BT.  
          38" fir stump bears S.49°E., 22.7-ft. (scribe vis)...1967 BT.  
Set - 1 1/2" x 36" I.P. & Brass Cap beside the 2 1/2" pipe  
New BT - 12" fir bears S14°E., 6.4-ft. (scribed/set washer). 2/83

Stephen L. Swinehart L.S. 2013  
For: U.S. Forest Service - Siuslaw National Forest  
July 1983  
M 94 - 77

Section corner for 8 and 9 only. (SOUTH) 40  
Found - 1954 GLO brass cap (1953-54 Cadastral survey)  
          18" fir windfall, rotten hull w/ scribing bears N.63°E., 12.1  
          to blaze. (6" N.60°E., 10.6 ft.) root hole matches orig. callow  
          36" fir windfall w/healed blaze bears N.6°E., 18.0 ft. to blaze.  
          (36", N.25°W., 23.8 ft.)  
          18" maple w/BT tag bears S.44 3/4°E., 13.1 ft. Tag, S.59°E., 14.9'.  
New BTs - 43" fir, "T20S R9W S8 BT", N.25 3/4°W., 51.3 ft.  
          34" fir, "T20S R9W S9 BT, N.70 1/2°E., 42.6 ft.  
We raised a stone mound around the monument.

Section corner for Secs. 16 and 17 only. (NORTH) 41  
Found - 1953 GLO brass cap  
          60" fir stump, S.48°E., 94.4 ft. with visible scribing (55",  
          S.48°E., 94.4 ft.)  
New BTs- 22" fir "T20S R9W S17 BT" bears S.37°W., 62.0 ft.  
          50" fir "X BT" bears N.10 3/4°W., 40.0 ft.  
We raised a stone mound around the monument.

South 1/4 corner for section 9 only. 42  
Found - Brass cap marked 1/4 S9 rusted off  
          1" iron pipe with concrete core (1921)  
          7" vine maple windfall with no visible marks - root hole,  
          N.1 3/4°W., 49.1 ft. (Mensch, N.1°W., 47.5 ft.)  
Set - F.S. Alum. cap and pipe. Buried old pipe alongside  
New BTs - 9" fir, "1/4 S9 BT", bears N.28 3/4°W., 64.7 ft.  
          6" fir, "1/4 S9 BT" bears N.9 3/4°E., 65.0 ft.  
We raised a stone mound around the monument.

North 1/4 corner for section 16 only. 43  
Found - Broken stone monument with no visible marks. (1891)  
          27" fir stump with healed face and county location tag bears  
          N.10°W., 7.9 ft. (N.5°W., 7.9 ft. Theil)  
Set - F.S. alum. cap and pipe. Buried stone.  
BTs - 8" alder, "1/4 S16 BT" bears S.83°E., 54.1 ft.  
          19" hemlock, "1/4 S16 BT" bears S.6 1/2°E., 75.0 ft.  
We raised a stone mound around our monument