

Douglas County Surveyor's Record of
Government Corners Renewed

T 20

T. S.

R 9

R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

44

Section corner for Secs. 9, 10, 16 and 15.

Found - Orig. fir corner tree, now 44" with dead top (36").
58" fir stump with blaze, N.70°E., 31.5 ft. (36", N.71°E., 30.4 ft.)
58" fir stump, N.13°W., 26.6 ft. (36", N.19°W., 22.8 ft.)
38" fir stump, S.4°W., 22.1 ft. (38", S.9°W., 19.1 ft.)
29" fir stump, S.43°E., 29.3 ft. (15", S.40°E., 30.4 ft.)
Set - 2" brass caps and 1" x 30" iron pipes for reference monument:
One marked "S9 RM" is N.20°27'W., 41.33 ft. from the corner.
The other marked "S10 RM" is N.70°06'E., 37.88 ft. from the corner.
We raised stone mounds around the monuments.

Stephen Swinehart
L.S. 2013
For. U.S. Forest
Service
July 1983
M 94 - 77

45

East 1/4 corner for section 9 only.

Found - GLO brass cap marked "1/4 S9 1921" with concrete core - cap
rusted off.
22" fir windfall with healed face - face is N.73°E., 40.8 ft.
(24", N.83°W., 40.9 ft.)
30" fir windfall with possible face - face is S.87°W., 23.0 ft.
(36", S.70°W., 37.6 ft.)
Set - F.S. alum. cap and pipe. Buried the old pipe alongside.
New BTs - 16" hemlock, "1/4 S9 BT" bears S.72 1/2°W., 93.1 ft.
12" alder, "1/4 S9 BT" bears N.51 3/4°W., 46.3 ft.
We raised a stone mound around the monument.

7/83

46

Witness corner for 1/4 corner, Secs. 16 and 17

Note - The true location of the 1/4 corner is at the top of a cutbank
above the 20-9-29.1 road. The 5/8" Iron rod set by the county
in 1968 has slid out and lies NW of true corner. Ren. #"
Found - 28" fir stump with scribing, N.7 1/2°E., 9.2 ft. (1953).
1953 GLO brass cap on 1" iron pipe for witness corner, S.5° W.,
30.57 ft. from the true 1/4 corner.
We X out "30 ft. N. to cor." stmped on cap.
Found - 12" hemlock with blaze & scribing, N.84 1/4°E., 27.8 ft. (rec.
1968, N.84°E., 28.1 ft.)
16" hemlock with healed blaze, S.67 3/4°E., 20.2 ft. (rec. 1968
S.67°E., 21.2 ft.)
New Witness BT:
14" hemlock, S.12 1/4°E., 47.2 ft. scribed "1/4 S16 WC" BT".
We set fence post & signs at the witness corner. It is impractical to set a
monument at the true corner location at this time. We searched for but found
no evidence of Theil's original corner.

Stephen Swinehart
L.S. 2013
For: International
Paper Company
November 1983
M 95 - 53

47

Section corner for secs. 16, 17, 20 and 21.

Found - 1953 GLO brass cap on 2" galv. pipe.
48" fir stump with no marks, N.27 3/4°E., 38.2 ft. (1891 rec.
N.28°E., 35.6 ft.)
26" fir stump with no marks, S.78 1/4°E., 18.1 ft. (1891 rec.
S.76°E., 16.5 ft.)
36" fir stump with no marks S.5 3/4°W., 9.5 ft. (1891, S.9°W.,
8.6 ft.)
40" fir stump, S.53 1/4°E., 69.7 ft. (1953, S.52 3/4°E., 70.0 ft.)
23" fir stump with healed face, S.70°W., 91.3 ft. (1953, S.70°W.,
92.4 ft.)
36" fir stump with healed face, N.19 1/4°W., 58.8 ft. (1953 rec.
N.21°W., 60.1 ft.)
Set - We set 2 reference monuments:
RM 1, bears N.9°52'E., 34.66 ft.
RM 2 bears S.86°26'W., 69.95 ft.
We set a steel fence post near the brass cap.
The reference monuments set at the SW section corner are 5/8" x 30" rebar
with a yellow plastic cap marked "S Swinehart" L.S. 2013."