

Douglas County Surveyor's Record of
Government Corners Renewed

T 20 T. S. R 9 R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 91881

Les Roberts
L.S. # 1039
November 26, 1986
C.S. 63/50

West 1/4 Corner for Section 27

64

CORNER REPORT

Found - 1953 GLO survey brass cap up-rooted by recent logging.
32" maple stump, S.46°E., 21.3 ft. (scar vis.) 1953 BT.
(Rec. S.43½°E., 19.8 ft.)
48" cedar stump, N.46°W., 22.7 ft. (no marks) 1953 BT.
(Record N.46°W., 21.8 ft.)
8" spike in top of 48" cedar stump, N.45°W., 21.3 ft. to spike.
8" spike in side of 18" maple stump, S.79°E., 36.9 ft. to spike.

Set - Re-set 1953 GLO brass cap firmly in ground using distances of
21.3 ft. and 36.9 ft. from 8" spikes set in 3/13/86. Buried
purple magnetic marker under iron pipe.
Set metal fence post, with survey attention sign wired to,
beside brass cap.

Corner lies on steep East slope about 350 ft. west of West Branch Road
11/26/86

South 1/4 Corner for Section 27

65

CONDITION REPORT

Found - 1953 GLO brass cap bent over from recent logging activity.
50" fir stump, S.59°W., 76.4 ft. (scar vis.) 1953 BT.
(Record, S.59°W., 72.6 ft.)
(NE maple BT set in 1953 is gone. and 6" alder set in 1967 is down.)

Set - Re-set 1953 GLO brass cap firmly in ground using hub and tack
R.P.'s set on 3/13/86. Buried purplemagnetic marker under
iron pipe.
Set metal fence post, with survey attention sign wired to,
beside brass cap.

Corner lies on steep East slope about 50ft. West of Smith River Road.
Corner is also about 500 ft. North of Scare Creek Bridge.

11/26/86

1/4 Corner for Sections 33 and 34

66

Found - 1953 GLO brass cap set firmly in the ground.
53" cedar, N.81°W., 67.9 ft. (no marks), 1877 BT (Rec.
N.80½°W., 66.0 ft.)
10" hemlockstump, N.75°E., 15.5 ft. (scribe vis.) 1953 BT.
(Rec. N.77¼°E., 15.2 ft.)
19" maple, N.74°W., 14.1 ft. (scar vis) 1953 BT. (Rec. N.75 3/4°W.
14.5 ft.)
NE cedar BT set by Theil in 1877 and found in 1953 is gone.

Because of planned logging activity in this area in the near future:
I SET the following R.P.'s:
50" fir stump, S.10°E., 24.15 to 6" steel spike.
20" fir snag, N.77°E., 27.60 ft. to 6" steel spike.
20" maple, N.72°W., 14.50 ft. to 6" steel spike.

Corner lies on west slope in NW corner of old unit. Logging unit is about
15 years old.

10/31/88

Les Roberts
L.S. #1039
Ted Baker
Notekeeper
Oct. 31, 1988
C.S. 63/85

Section corner for Secs. 27, 28, 33 and 34

67

Found - 1953 GLO Brass cap set firmly in the ground.
16" fir, N.14°E., 20.0 ft. (scar vis) 1953 BT (Rec. N.13½°E.19.8')
18" fir, S.51°W., 24.3 ft. (scar vis) 1953 BT (Rec. S.56¼°W.,
25.7 ft.)
24" fir, N.52°W., 18.0 ft. (scar vis.) 1953 BT (Rec. N.51 3/4°W.,
17.8 ft.)
28" fir, S.08°E., (scar vis.) 1953 BT.(Rec. S.10°E., 2.3 ft.)

Because of planned logging activity in this area in the near future
I SET the following R.P.'s:
16" fir, N.26°E., 17.95 ft. to 6" steel spike.
18" fir, S.48°W., 24.30 ft. to 6" steel spike.
28" fir, S.32°E., 1.75 ft. to 6" steel spike.

10/31/88

see the next PG

For 64 A, 65 A, 66 A : 67 A