

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 10 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21001

Les Roberts
Apr. 24, 1992
C.S. 63/138 (Corner Restoration Forms)

130

Center South 1/16 Corner Section 34. (Condition Report Only)

- Found - 1983 BLM iron pipe and brass cap lying on the ground. Re-set iron pipe and brass cap from found 1983 BTs.
11" Fir, N.85°W., 207.9 ft. (scar vis.) Rec. N.85¼°W., 207.9 ft.
16" Fir, S.6°E., 48.2 ft. (scar vis.) Rec. S.6¼°E., 48.2 ft.
- Set - 72" alum. post, with land survey monument sign attached to beside brass cap. Painted all bearing trees red.
- Note - Corner lies on flat ground about 80 ft. south of south bank of Smith River.

131

South 1/16 Corner Section 34 & Section 33.

- Found - 1951 GLO iron pipe and brass cap lying on ground. Re-set pipe and cap from NE Willow BT.
48" Downed Willow, N.41°E., 9.2 ft. (no marks) 1951 BT. Record N.41°E., 9.2 ft.
SW Alder BT was washed away by Smith River.
- Set - 72" alum. post with land survey monument sign attached beside brass cap.
- New Accessories -
18" Maple, S.50°W., 33.8 ft. (scribed/painted red)
24" Alder, S.83°E., 31.7 ft. (bark scribed/painted red)
- Note - Corner lies 25 ft. east of Smith River and 15 ft. north of small draw. Draw bears N.80°W.

132

Les Roberts
L.S.1039
For: International Paper
Dec. 1992
M 118-47

Corner Secs. 33 & 34; 3 & 4 T21-10

- Found - 1951 GLO brass cap
30" Hemlock, N.85°W., 64.3' (scribe vis.), 1951 BT
33" Fir, N.70°E., 148.5' (scar vis.), 1951 BT (rec. 87.1)
38" Fir, S.59°W., 64.5' (scar vis.), 1951 BT
36" Maple, S.20°E., 26.5' (scribe vis.) 1983 BT

133