

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 10 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

South $\frac{1}{4}$ Corner to Section 35 only, T20-10W. 32
 Found - No trace of Brass Cap, but 1951 BT's., as follows:
 20", now 24" Hemlock, alive, N. $45\frac{1}{4}^\circ$ E. 45.5 ft., scribe
 marks visible on nearly healed blaze.
 24", now 26" Hemlock, alive, N. $54\frac{1}{4}^\circ$ W. 92.4 ft., scribe
 marks visible on partially healed blaze.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T20S R10W $\frac{1}{4}$ S 35
 (Set 6' Steel fence post Office, 1968 T21S
 alongside B.C.)
 Note - The $\frac{1}{4}$ corner of Sec. 2, T21-10W bears S. $87\frac{3}{4}^\circ$ E. 13.9 ft.
 and 14 ft. west of new logging road, course N. 30° W. - S. 30° E.
 5/8/68

C. S.
File
No.
54/1

$\frac{1}{4}$ Corner to Sections 29 and 32, T21-10W. 33
 Found - 3"x3"x4.8" squared Post & BT's. as Rec. in Ren. #8 by
 Roy Gibson in 1957 by proportional measurement.
 40", now 42" Fir Sawed Stump, N. 17° W. 37.0 ft. scribed.
 8", now 10" Maple, alive, leaning badly, S. 43° E. 14.8 ft.,
 scribe visible.
 Set - Brass Cap at Gibson's Corner Point Mkd: T 20 S R 10 W
 County Surveyor's $\frac{1}{4}$ S 29
 Office, 1968 S 32
 New BT's: 6" Hemlock N. 18° W. 19.2 ft. mkd. $\frac{1}{4}$ S29 CS BT.
 4" Hemlock S. 9° E. 30.8 ft. mkd. $\frac{1}{4}$ S32 CS BT.
 Note - This corner lies on spur sloping N.W. approx. 300 ft. E. of creek,
 course N. W. in dense brush.

Vernon "Ray" Tracy
Jack Heritage & V. Perron
May, 1968
C. S. File No. 53/66

★ SEE
C.S. 62/19
4/2/84

Closing Corner for Sections 7 and 18, T20-10W. 34
 Found - 24"x20"x10" S. S. mkd: "CC +" & 2 notches on N. edge and
 4 notches on south edge, firmly set
 and in place.
 Orig. 18", now 46" Fir, alive, S. 10° E. 10.6 ft., shows good scar.
 We Rescribe: "T20S R10W S18 CC CS BT".
 Orig. 10", now 28" Fir, alive, N. 36° W. 29.0 ft., shows faint scar.
 We Rescribe: "CC CS BT".
 Set - Brass Cap in place of rock & Mkd: County R T 20 S R
 Surveyors 11 CC $\frac{S}{S}$ $\frac{7}{18}$ 10
 Office, '68 W W
 New BT: 8" Hemlock N. 45° E. 39.2 ft. mkd. T20S R10W S 7 CC CS BT.
 Note - This corner lies on top of spur ridge, sloping N., approx.
 495 ft. south of corner of secs. 12 & 13, T20-11W., see below.

Witness Cor. to Sections 12 and 13, T20-11W. 35
 Found - Orig. 18", now 26" Fir Corner Tree, now dead Snag, leaning
 badly with very poor bark scribe.
 Orig. 30", now 60" Fir, alive, S. $71\frac{1}{2}^\circ$ E. 9.9 ft., shows fair
 bark scribing.
 Orig. 30", now 64" Cedar, alive, S. $34\frac{1}{2}^\circ$ W. 41.6 ft., shows faint
 scar. We do not open.
 Orig. 12", now 16" Cedar, 5' high stub, N. 82° W. 14.5 ft., blazes
 rotted out, no scribing found.
 Set - Wit. Corner 10 ft. west of True Corner mkd:
 County Surveyor's R T 20 S R
 Office Wit. Cor. 10' 11 S 12 | 10
 1968 E. to Cor. W S 13 | W
 New BT: 40" Cedar N. 26° W. 18.5 ft. mkd. WC T20S R11W S12 CS BT.
 64" Cedar S. $29\frac{1}{2}^\circ$ W. 35.9 ft. mkd. W.C. T20S R11W S13 CS BT.
 (Orig. BT.)
 Note - This corner lies on steep northerly slope, approx. 100 ft. E.
 & 150 ft. S. of creek, course N.E. & approx. 495 ft. N. of
 of C.C. Sections 7 & 18, T20-10W, see above.