

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 20 T. S. R 10 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORG. 21981

Ernesto R. Alvarado
U.S.F.S.
Deputy, Doug. Co.
Surveyors Office
Witness: Jill O'Neil
April 15, 1978
C.S. 59/46

1/4 Corner for Section 1 only, T20-11
Found - 2 1/2" brass cap in good condition, 4" below the road surface marked T20S R11W S1 only 4/85. Ren. #45
Uprooted D. Fir stump bears N.84°W., 33.10 ft.
22" D. Fir bears N.52°W., 43.04 ft. scribe marks visible.
New BT - 18" D. Fir bears S.70°W., 31.32 ft. double faced scribed 1/4 S1, upperblaze and CS BT lower blaze.
Note: Go south on USFS Road #1909 about 3.6 miles to the Siuslaw National Forest boundary sign on the left side of the road. The corner lies in the center of the road.

RE-RENEWED, SEE CORNER NO. #83

61

4/15/78

Richard J. Hintz
PLS 497
For: International Paper
4/78 M 69-78

Center 1/4 Corner for Section 4.
Set - 5/8" Iron Rod
BT's - 30" Fir stump bears N.4°00'E., 27.4 ft. scribed.
40" Fir bears N.85°00'W., 16.8 ft. scribed.

RE-RENEWED, SEE CORNER NO. #67

62

4/78

P. Fox, Engineer
#3282
For: U.S. Forest Serv.
Sept. 28, 1977
C.S. 60/11

*FD OK 4/87
R. HINTZ
M104-9*

Section corner for 13 and 24 only, T.20-11.
Found - 1968 Douglas County brass cap in mound of rock on steep rocky hillside. Ren. #27
48" Fir stump with tag bears S.81°W., 9.9 ft.
30" Fir stump with tag bears N.74°W., 8.6 ft.
15" Cedar stump with tag bears N.50°W., 16.6 ft.
Drilled hole in rock ledge to receive the iron pipe and a recess was made for the brass cap and then cemented in place.
No new accessories.

9/28/77

63

Forrest Hales
For: International Paper
April 1979
M 76 - 55

1/4 Corner for Secs. 31 and 32. *FD OK 2/92 BY STUNTZNER M114-80
FD OK 2/94 BY DOUG C.S. 63/130-4*
Set - 1 1/2" Pipe post with Brass cap in road ditch.
BT's - 16" D. Fir bears N.19°20'E., 59.8 ft.
5" Pond. Pine bears N.76°W., 84.4 ft.
14" D. Fir bears S.25°50'W., 169.1 ft.
1 Iron axle post bears S.1°03'W., 65.29 ft.

FD OK 1/96 P. Halar M123-37

64

Section corner for Secs. 31 and 32.; and Secs. 5 and 6 of T21-10.
Set - 1 1/2" x 36" Pipe post with brass cap
BT's - 28" D. Fir bears S.42°30'E., 84.4 ft.
16" R. Cedar bears N.7°W., 28.6 ft.

RE-RENEWED, SEE CORNER NO. #85

65

Center 1/4 Corner for Sec. 32.
Set - 1 1/2" x 36" Pipe post with brass cap.
BT's - 32" Hemlock bears N.32°30'E., 6.0 ft.
36" R. Cedar bears S.11°W., 19.4 ft.

April 1979

66

Ernesto R. Alvarado
U.S. Forest Service
Deputy - Doug. Co. Surveyor
Greg Martin - Witness
March 20, 1980
C.S. 61/6

Center 1/4 Corner for Sec. 4
Found - 1/2" machine axle with gear at top (no record)
36" D. Fir stump bears N.2°E., dist. 28.39 ft. open face scribing visible: 1/4 BT. (Rec. 30", N.4°E., 27.4 ft.) Ren. #62
57" D. Fir bears N.87°W., dist. 16.84 ft. partially healed face, scribing: 1/4 BT. (Rec. N.85°W., 16.8 ft.) Ren. #62
Set - 2" Douglas County Surveyor brass cap on 1" steel pipe mkd. T20S R10W C 1/4 S4 1980
1/2" re-bar is inside 1" steel pipe, and gear is deposited alongside.
New Accessories:
New bearings and distances to found BT's.
36" D. Fir stump bears N.4°E., dist. 28.5 ft.
57" D. Fir bears N.85°30'W., dist. 16.8 ft.

Attention signs and boundary signs on metal fence posts placed west and north of corner. Location: Take Burma Rd. to I.P. Rd. #20-10-4.1 Location Poster on edge of rd. approx. 0.1 mile from junction with rd. #20-10-3.3 Corner bears N.10°W., dist. 150 ft. from poster and lies on north lope in clear cut.

3/20/80

67