

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 20 S T. S. R 10 W R.W.W.M.

ROCKE-CHAPMAN CO., EUGENE, ORE. 21981

68

Frank M. Pumphrey
LS# 1677
For: International
Paper Co.
Aug. 1980
M 85 - 37

*FNO. OK 12/90
M 111-47 A-F
FO. OK 2/92
STOUTNER
M 114-80*

1/4 Corner to Secs. 31, T.20S. R.10W.; and Sec. 36, T.20S. R.11W.
Set - 5/8" x 30" Rebar with alum. cap mkd. "1/4 Sec. 36 31".
Set 4" below surface.
B.O.'s- 3/4" Iron pipe bears N.82°11'30"E., 298.22 ft.
3/4" Iron pipe bears S.55°46'56"E., 287.06 ft.
Fence post with 16P nail in top of post bears N.56°E., 33. t.
Fence post with 16P nail in top of post bears S.33°E., 36. t.
Fence posts are tagged. Corner lies in middle of field.

9/80

Richard Hintz
For: International
Paper Co.
July 1980
M 74 - 3

1/4 Corner to Secs. 8 and 17
Set - By apportionment - 5/8" Iron Rod.
BT's - 20" Hemlock bears N.43 15'E., 37.6 ft. scribed.
18" Hemlock bears N.24 30'W., 11.8 ft. scribed.
Note - Found corner from County Surveyor's file map # M 35 - 80
bears N.45 13'E., 17.79 ft.

69

Richard J. Hintz
For: Internat. Paper
February, 1982
M 91 - 24

Witness Corner to 1/4 cor. common to Sec. 33, & Sec.4, of T.21-10.
Set - 1-1/4" x 36" I.P. with B.C. stamped "P.L.S. 497", 2.0-ft.
south of corner position, which is in a field ditch.
New BTs- 32" fir bears N.65°45'E., 265.5-ft. (scribed).
68" maple bears S.57°30'W., 320.5-ft. (to face). 2/82

70

Sec. cor. common to Secs. 32, & 33, and Secs. 4, & 5 of T.21-10.
Found - Iron Pipe with U.S.G.L.O. B.C. dated 1918, & a plow share.
New BT - 14" alder bears S.70°W., 4.7-ft. (scribed). 2/82
(SEE REN. #1)

RE-RENEWED, SEE CORNER NO. #72 71

Gregory Quibell
Deputy, Douglas Co.
Surveyors Office
Randy Smith, witness
March 22, 1982
C.S. 61/30

Sec. corner common to Secs. 32 and 33; and Secs. 4 and 5 of T.21-10
Found - 2" I.P. filled with concrete firmly set protruding 6" out of
ground. The top 10" of said I.P. has brass cap attached and
is broken off and lying on ground. Cap is an unrecorded GLO
cap stamped "General Land Office Survey" T20S R10W SE2 S33
S 5 S 4 T21S 1918. See C.S. Renewal #'s 1 and 71.
Also found unrecorded 20" x 5" plow shear along side iron pipe.
14" alder with possible well healed blaze and newly bark scribed
"S 5 BT", bears S.63°W., 4.7 ft. (Rec. 5.7 ft.) bark scribing
per Ren. #71.
15" now 20" fir stump with scribed "BT" visible bears N.32°E.,
28.2 ft. (rec. N.45°30'E., 29.0 ft.)
12" now 15" fir snag approx. 40 ft. tall with well healed blaze
bears N.30°E., 23.8 ft.
12" alder is gone as is any orig. evidence. (Ren. #1)
Set - At the location of the 2" I.P. filled with conc. I set a 1" x 30"
I.P. with brass cap attached marked "Douglas Co. Surveyor"
T20S S32 S33 S5 S4 R10W T21S 1982.
I buried both parts of found GLO I.P. and brass cap along
with plow shear alongside new brass cap.
New BT's- 16" fir scribed "T20S R10W S33 CS BT" in double blaze bears
N.2°E., 83.8 ft.
7" fir scribed "T21S R10W S4 CS BT" in double blaze bears S.1°E
16.2 ft.
24" cedar scribed "T21S R10W S5 CS BT" in double blaze bears
S.71°W., 32.9 ft.

3/22/8

1/4 Corner for Secs. 9 and 10
Found - No evidence of 1952 BLM monuemnt.
30" D. fir BT, marked by BLM in 1952 now a 36" D. fir stump with
IPCo tag reading N.87°W., 44.6 ft.
14" maple BT, marked by BLM in 1952 gone.
78" D. fir stump with IPCo tag reading S.45°W., 37.7 ft. (no rec.)
Set - 1 3/8" galv. iron pipe with brass cap marked "Sec. 9/10, T20S
R10W 1982 LS 1667"

From which:

36" D. fir stump, with IPCo tag, bears S.87°E., 44.6 ft.
78" D. fir stump, with IPCo tag, bears N.45°E., 37.7 ft.
18" maple stump, with IPCo tag, bears S.84 1/4°W., 56.1 ft.

8/82

W. Carey Weatherly
For: International
Paper Company
Aug. 1982
C.S. 58/276

73