

Douglas County Surveyor's Record of
Government Corners Renewed

20 T. S. 11 R. W. W. M.

Section corner common to Sections 4, 5, 8, and 9.

Found- The remains of the original corner post.

10

The original cedar bearing tree in Section 5, which is blown down and the scribing is almost gone.

I set a 4" X 4' cedar post next to the original corner post, and scribe four new bearing trees:

Western R. Cedar 14 inch DBH, bears S32°00'E. a distance of 42.5 feet.

An Alder 21 inch DBH S.60°30'W. a distance of 31.5 feet.

An Alder 16 inch DBH bears N.80°00'W. a distance of 39.0 feet.

D. Fir 22inch DBH bears N.6°00'E. a distance of 74.5 feet.

1/4 Section Corner common to Sections 5 and 8.

11

Found - The stump of the original bearing tree, scribing is barely visible on the Section 8 bearing tree & no scribing is apparent on the remains of the Sec. 5 bearing tree.

I reset the corner from these bearing trees at the original distances, which agree. This corner lays on top of a ridge as called for in the orig. notes.

For the 1/4 corner I set a 1" X 36" galvanized iron pipe from which:

An Alder 11" DBH bears N.41°00'E. a distance of 3.0 feet.

An Alder 9" DBH bears S.82°00'E. a distance of 4.4 feet.

6/25/69 - FOUND O.K. Y.R.T.

Section Corner common to Sections 8, 9, 16 & 17.

12

Set from the Orig. Cedar BT. Cannot find the other evidence found by Cole in 1923, so Set a 1 1/2" Pipe in the pasture at the orig. dist. from the bearing tree & mark a 23" Maple which bears S.56°00'E. 213.8 ft. - SEE REN.#5

65

1/4 Section Corner common to Sections 8 & 17.

13

Which is witnessed by the Stump & felled Douglas Fir BT. - REN.#4

New BT's: Alder 26" DBH, bears S. 55°00'E. 46.8 ft.

Alder 9" DBH, bears N. 29°00'E. 13.7 ft.

66

Section Corner 7, 8, 17 & 18.

14

Drive a 1 1/4" Pipe and Mark Two New BT's. as follows:

Alder 15" DBH, bears N. 5°00'W., 52.5 ft.

Spruce 19" DBH, bears N.20°00'E., 36.5 ft.

All area to the South is in pasture. The corner lays on the shoulder of a cat road at the edge of the pasture & 10 ft.

North of a small creek along the edge of the pasture.

84

1/4 Section Corner common to Sections 17 & 18.

15

1 1/4" Pipe and Marked the following BT's:

Hemlock 10" DBH, bears S. 4°15'E., 39.3 ft.

D. Fir. 26" DBH, bears S.78°45'W., 19.9 ft.

67

Section Corner common to Sections 16, 17, 20 & 21.

16

Set by proportion 5233.5 ft. South of the Sec. Cor. common to Secs. 17, 18, 19 & 20, & mark the following BT's:

Hemlock 24" DBH, bears S.34°00'E. 28.5 ft.

Cedar 18" DBH, bears S.60°00'W. 69.2 ft.

Maple 16" DBH, bears N.41°00'E. 34.3 ft.

Hemlock 20" DBH, bears N.29'30'W. 50.6 ft.

The 20" Hemlock & the Cedar are located on the West bank of a creek which flows NE.

SEE M 35-74

68

1/4 Section Corner to Sections 16 & 17.

17

I Drive a 1 1/4" Pipe & Mark:

D. Fir 36" DBH, bears N.85°00'E., 20.0 ft.

Hemlock 16" DBH, bears West 13.7 ft.

71

South 1/4 Corner of Section 17.

18

Drive & Pipe & Scribe: Hemlock 24" DBH, bears S.16°00'W., 11.0 ft.

Spruce 24" DBH, bears N.52°00'E. 23.1 ft.

SEE M 35-74

Warren D. Hootman
For Cape Arago Lumber Co.
Sept. 10, 1957
C. S. File No. 42/305

Survey by Warren D. Hootman
For Coos Bay Pulp Corp.
July 1, 1959
C. S. File No. 51/29
Map File M 15 - 22