

Douglas County Surveyor's Record of  
Government Corners Renewed

T 20 T. S. R 11 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

- C O N T. -

109

L.E. Monrean  
Peter Earle  
Mike Tompkins  
Douglas Co. Surveyors  
Office  
Dec. 5, 1976  
C.S. 9/26

Found - 11" Hemlock bears N.65 1/2°E., (Rec. N.62°E.,) 20.3 ft. Tree has open double blaze, visible scribing "20S R11 S33 CS BT". This tree is dying.  
New BT's - A 11" Hemlock, bears S.76 1/2°E., 23.0 ft. Tree double blazed and scribed "T21S R11W S4 CS BT".  
A 10" Hemlock bears N.72°E., 42.5 ft. Tree double blazed and scribed "T20S R11W S33 CS BT".

12/15/76

110

Larry E. Monrean  
P. Earle  
K. Cheney  
Douglas County Surveyor's Office  
March 2, 1977  
C.S. 59/31

Section Corner for Secs. 31 and 32; and 6 and 5 of T21-11.  
Found - Orig. 42" Fir now a 46" decayed stump. Stump has well healed blaze which we open. Find good scribing "T21S R11W S6 BT"  
Orig. 27" Fir now a 34" Tip out (Root hole well defined). Tree has well healed blaze which we open, find good scribing "T20S R11W S32 BT". Tree is decayed.  
Possible Orig. BT to the SE recorded as a 36" Fir. Found a badly decayed stump, no scribing, approx. 18".  
NW BT an alder not found.  
Set - A 1" x 36" I.P. with brass cap attached 30" deep at sec. cor. mkd. "Douglas County Surveyor T20S R11W S31 S32 S6 S5 T21S 1977"  
From Which:  
46" Fir stump, bears S.22°W., 13.2 ft. to face.  
Stump hole bears S.27°E., 23.1 ft. to center (Rec. S.29 1/2°E., 23.1")  
New BT's A D. Fir 14" bears S.39°W., 16.5 ft. Tree double blazed and scribed "T21S R11W S6 CS BT"  
A D. Fir 14" bears S.62 1/2°E., 4.6 ft. Tree double blazed & scribed "T21S R11W S5 CS BT".  
A W. Fir 9" bears N.34 1/2°W., 14.2 ft. Tree double blazed & scribed "T20S R11W S31 CS BT".  
A D. Fir 18" bears N.7°E., 25.2 ft. Tree double blazed & scribed "T20S R11W S32 CS BT".

Note: This corner falls on the top of a ridge running S.35°W.,

3/2/77

111

G. Langlitz  
R. Kimberling  
June 16, 1977

Sec. Cor. for Secs. 33 and 34; and 4 and 3 of T21-11.  
Found - 1964 Doug. Co. Surveyors brass cap set 12" above ground on 1" Pipe properly marked. Ren. #38  
A Fir, uprooted and down, approx. 54" bears N.55°W., 31.0 ft. Both scars visible.  
A Fir stump, 48" now 42" bears S.25°E., 12.8 ft. (Rec. 11.9 ft.)  
A Fir, 48" now 50" bears S.55°W., 19.8 ft. to well healed blaze, 20.8 ft. to opened blaze with visible "B" scribe mark.  
A 9" Hemlock now 16" bears S.58°E., 26.4 ft. (Rec. 27.4 ft.) with well healed double blaze.  
A D. Fir snag, 36" now 34" bears N.17°W., 50.0 ft. double blazed, partial healed with trace scribing visible.  
New BT - A 11" Hemlock measured below fork bears N.1°E., 29.7 ft. double blazed and marked T20S R11W S34 CS BT.

6/16/77

112

Larry E. Monrean  
Karen Cheney  
Steve J. Flause  
June 15, 1977

Douglas County Surveyors Office  
C.S. 59/34

1/4 Corner For Sec. 33 and Sec. 4 of T21-11  
Found - A 1" Iron pipe at 1/4 Corner as proportioned by Stuntzner per Ren. #59  
A D. Fir 32" bears N.50°W., 1.8 ft. Tree bark scribed "S 33 1/4".  
A D. Fir 42" now 52" bears N.82°E., 9.5 ft. Tree has unhealed blaze scribed "S 33 1/4".  
Set - A 1" x 30" Iron pipe with brass cap attached at 1/4 corner as determined by Stuntzner, cap stamped "Douglas Co. Surveyor" T20S  
1/4 S 33 S 4 R11W  
1977  
Set - 1" I. pipe along easterly edge of cap.  
New BT- A 48" D. Fir bears S.4 1/2°W., 88.4 ft. Tree double blazed and scribed "1/4 S4 CS BT".

Corner lies at NE corner of stand of timber

6/15/77

FD. OK 5/15/80  
E. ALVARADO  
C.S. 61/6

FD. OK 5/20/80  
E. ALVARADO  
C.S. 61/6