

Douglas County Surveyor's Record of  
Government Corners Renewed

T 20 T. S. R 11 R. W. W. M.

MOKE-CHAPMAN CO., EUGENE, ORE. 21881

113

1/4 Corner for Sec. 31 and Sec. 6 of T.21-11.

No monuments or accessories found.

Position determined by single proportionate measurement/

Set - At the corner point we set a 1" x 30" I.P. 26" in the ground on a steep SE slope, with brass cap attached marked:

County Surveyors Office

R 20 S

R 11 W S 31

S 6

T 21 S

BT's - A 18" D. Fir double blazed & scribed "1/4 S6 CS BT" bears S.18°W., 29.8 ft.

A 14" D. Fir double blazed & scribed "1/4 S31 CS BT" bears N.31°W., 18.3 ft.

Corner is located approx. 100 ft. east of top of spur ridge running NE.

9/20/77

Douglas Co. Surveyor  
Office

Gary L. Langli

R. B. Kimerlin

P. L. Earle

S. J. Flause

Sept. 1977

For: Doug. Co.

Land Dept.

(See CS File 59/

Notes in C.S.

59/40

114

1/4 Corner for Sec. 32 and Sec. 5 of T21-11

Set - A 1" x 36" I.P. with brass cap set 6" above ground in a 30" mound of stone and marked: "Douglas County Surveyor" 1978

T 20 S R 11 W

1/4 S 32  
S 5

T 21 S R 11 W

BT's- A 9" Spruce bears S.14°E., (55°@+25°) 49.8 ft. I double blaze and scribe "1/4 S5 CS BT".

A 7" D. Fir bears N.20°E., (69.4@+35°) 56.8 ft. I double blaze and scribe "1/4 S32 CS BT"

Corner is 5 ft. North of a westerly stream.

4/19/78

R. B. Kimberling

P.L. Earle

F.C. Silagy

Doug. Co. Surveyors

Office

April 19, 1978

C.S. 59/46

1/4 Corner for Section 1 only. East boundary.

Found - 2 1/2" brass cap in good condition, 4" below the surface of road. marked T20S R11W S 1 only 4185. Rep. #98

Uprooted D. Fir stump bears N.84°W., 33.10 ft.

22" D. Fir bears N.52°W., 43.04 ft. scribe marks visible.

New BT - 18" D. Fir bears S.70°W., 31.32 ft. double faced scribed 1/4 S 1 upperblaze and CS BT lower blaze.

Note - Go south on USFS road #1909 about 3.6 miles to the Siuslaw National Forest boundary sign on the left side of the road. The corner lies in the center of the road.

4/15/78

115

Section corner for 16, 15, 21 and 22.

Found - Unrecorded 2" brass cap set by Dennis A. Crow #845 LS marked T20S R11W S16 S15 S21 S22 1973 845 LS

16" Cedar with a dead top, bears N.8°W., 21.00 ft. with visible scribing mkd. S15 BT.

60" D. Fir sawed off stump bears S.69°W., 7.07 ft. with faded bark scribe visible, "BT T20 R11W (the size of the loop on the "B" is one inch). Original bearing tree.

Tags on the D. fir stump indicate that it was visited by Bob B. from the Douglas Co. Forest Appraisal Dept. Oct. 23, 1953 and W. Camp from U.S. Plywood 7/23/65. Rogert Ward, Land Surveyor for Champion International talked with Mr. Camp about the tag and the bark scribing since orig. notes did not mention scribing. Mr. Camp said that he found a number of BT in the five mile area that were bark scribed instead of being blaze and scribed.

Set - Brass cap at corner mkd: Douglas County Surveyors Offices, 1978 T20S R11W S16 S15 S21 S22.

Steel fence post with attention poster alongside monument.

New Accessories: Unrecorded brass cap bears N.89°30'E., 2.45 ft.

6" Alder bears S.86°30'E., 18.20 ft. bark scribe T20S R11W S22 C.S. BT.

60" D. Fir sawed off stump bears S.63°30'W., 4.62 ft. rescribed CS BT on a lower blaze.

16" Cedar bears N.16°E., 19.8 ft. rescribed CS below old scribing.

Note: From road junction of 1909.3 and 1901.1, take the NE spur road to the first cat road on left side of road; then follow the cat road past the landing to a location poster on the left side.; then go N.24°E about 75 ft. to the corner.

116

Ernesto R. Alvarado, USFS  
Deputy, Douglas Co. Surveyors Office  
Witness: Jill O'Neil  
April, 17, 1978  
C.S. 59/46

RE-RENEWED CORNER NO. #223

JAN 78

RE-RENEWED CORNER NO. #162