

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 11 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

137

Section corner for Secs. 20, 21, 28 and 29
Found - Orig. corner tree, 60" Spruce (now stump) opened in NE face,
partially visible scribes in rotted face, from which:
County Surveyor brass cap bears N.70°E., 4.0 ft. marked
"T20S R11W S20, S21/ S29, S28 1964." Ren. #35
48" D. fir, stump, bears N.52°E., 118.0 ft. scribed T20S R11W S21
CS BT
Other 1964 BTs not found, possibly lost in logging and slide
New BT's- 5" Hemlock bears S.64°E., 5.7 ft. marked "X" at breast height
& BT at face.
5" D. Fir bears N.88°W., 18.8 ft. marked "X" at BH & BT at face
16" Hemlock bears N.23°W., 217.7 ft. scribed T20S R11W S20 BT.

138

1/4 Corner for Sections 28 and 21.
Set - Alum. cap on alum. pipe at proportioned distance marked "T20S R11W
1/4 S21 / S28 1981 PLS 1342"
No original evidence found.
New BT's- 5" D. fir bears S.86°E., 21.1 ft. scribed 1/4 BT at face, "X" at BH.
46" W. R. Cedar stump bears N.41°W., 17.0 ft. scribed "1/4 S21 BT"
76" D. fir stump bears S.43°E., 28.9 ft., poor condition, tagged
only.

139

Section corner for Secs. 21, 22, 27 and 28
Found - Original corner tree, rotted remains of small D. fir from which
orig. BTs bear:
34" D. fir snag bears N.70°E., (rec. N.65°E.) 16.5 ft. No scribing
old choppings, cut to flush stump.
Possible SE BT: 22" uprooted cedar snag now bears S.26°E., 22.2 ft.
(rec. S.68 1/2°E., 20.5 ft.)
24" Hemlock rotted remains bears S.45°W., 18.7 ft. (rec. ori
S.53°W., 15.2 ft.)
Possible NW BT, 40-48" Hemlock rotted remains bears N.56 1/2°W.,
13.2 ft. (Rec. orig. N.53°W., 9.2 ft.)
Set - Alum. cap on alum. pipe marked "T20S R11W S21, 22, 28, 27 1981
PLS 1342"
New BTs- 10" D. fir, N.32°E., 11.4 ft. scribed S22 T20S R11W BT.
12" D. fir, S.55°E., 24.3 ft. scribed S27 T20S R11W BT.
10" D. fir, S.27 1/2°W., 3.3 ft. scribed S28 T20S R11W BT.
8" D. fir, N.38°W., 8.7 ft. scribed S21 T20S R11W BT.
Note: For additional orig. evidence as per line tree witness corner,
see plat.

140

1/4 Corner for sections 28 and 27.
Set - Alum. cap and alum. pipe at proportioned distance marked: T20S
R11W 1/4 S28/S27 1981 PLS 1342.
No evidence of original corner found.
New BT's- 38" D. fir bears S.57°W., 55.6 ft. scribed "E 1/4 S28 BT".
12" Hemlock bears S.81°E., 37.0 ft. scribed "W 1/4 S27 BT".

141

Section corner for Sections 28, 27, 33 and 34.
Found - Original NE BT and re-established orig. corner.
Set - Alum. cap and alum. pipe marked "T20S R11W S28, S27, S33, S34 1981
PLS 1342"
From which: 16" now 31" orig. Alder bears N.50°E., 43.6 ft., visible partial
bark scribes.
New BT's- 14" D. fir bears S.67°E., 84.7 ft. scribed T20S R11W S34 BT.
53" W.R. cedar bears S.53°W., 78.4 ft. scribed T20S R11W S33 BT.
18" alder bears N.46°W., 43.2 ft. bark scribed T20S R11W S28 BT.
Note: Corner position falls on alder flat as orig. called. Calls to N. S. E.
and west checked with old blazes.

142

1/4 Corner for Sections 28 and 29.
Set - Alum. pipe with alum. cap marked "T20S R11W 1/4 S29/S28 1981
PLS 1342", at proportioned distance.
No original evidence found. Corner falls in old timber stump flat as called.
New BT's- 20" Hemlock bears N.19°E., 3.1 ft. scr. W 1/4 S28 BT".
16" D. fir bears S.25°E., 15.0 ft. scr. W 1/4 S28 BT.
18" Hemlock bears S.32°W., 7.4 ft. scr. E 1/4 S29 BT.

Ronald E. Stuntzner, PLS 1342
For: Siuslaw National Forest
Oct.-Nov. 1981
M 91 - 53

FO OK 11-91
L. ROBERTS
M/14-29