

Douglas County Surveyor's Record of
Government Corners Renewed

20 T. S. 11 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 97401

183

Michael J. Schwartz
L.W. Hunnemuller,
For: U.S. Forest Service
October, 1985
M 99 - 79 A&B

WEST 1/4 Section Corner to Section 19 Only, (T20-10)
SET - A 3 1/2" x 30" Aluminum flared pipe with alum. cap., stamped:
T20S R11W R10W 1/4 S19 1984 PLS 1922
BT's - 7" D. Fir, bears S.10°E., 2.4 ft. dist., scribed 1/4 S19 BT
10" D. Fir, bears N.38°E., 21.2 ft. dist., scribed 1/4 S19 BT

Daniel Baker
For: U.S.F.S.
June 10, 1986
M 102 - 12

Section corner for Secs, 25 and 36; and 30 & 31 of T.20-10
Found - 2 1/2" iron pipe with brass cap. Ren. #77
7" dead chittum, S.71 1/2°E. 27.4 ft. (Rec. N.E.)
63" fir, S.17 3/4°W. 73.4 ft. bark scribed.
18" rotted maple, N.31 1/2°W., 24.6 ft.
16" cedar, N.16 1/2°W., 46.2 ft. closed face.
New BT - 72" spruce, S.72 3/4°E., 74.3 ft. scribed "T20S R10W S31 BT".

RE-RENEWED CORNER NO. # 207

184

1/4 Corner for Section 25; and Sec. 30 of T.20-10
Set - 2 3/8" x 30" alum. pipe with 3" alum. cap marked T20S R11W R10W
1/4 S25 S30 PLS 1978 1986"
New BTs - 8" Fir, N.28°E., 11.0 ft. scribed "1/4 S30 BT"
9" Fir, S.43 1/2° W., 16.9 ft. scribed "1/4 S25 BT".

185

SECTION CORNER 3,4, and 33,34 T19-11.
Set - 1-3/4" x 46-1/2" Iron pipe with brass cap.
1/2" x 60" Rebar bears N 72°26'40"E, 4.38 ft.
Rebar replaces 1981 section corner monument.
BT's - 1981 bearing tree changes:
A 13" Fir bears N 42 1/2°E, 256.6 ft. See Ren #159
21" Alder, bears N 47°W, 70.0 ft.

186

1/4 CORNER SECTIONS 34 and 3 of T19-11.
Set - 2" x 43" Iron pipe with brass cap buried 9" below ground.
BT's - 1981 bearing tree changes:
A 18" Alder bears N 6°W, 124.3 ft. See Ren #160
39" Hemlock bears S 17-1/2°W, 299.9 ft.

187

1/4 CORNER SECTION 3, 4.
Set - 1-3/4" x 40" Iron pipe with brass cap.
1/2" x 30" Rebar bears N 72°26'31"E, 1.96 ft.
Rebar replaces 1981 1/4 Corner Monument.
BT's - 1981 bearing tree changes:
A 22" Fir bears S 58 1/4°E, 66.1 ft. See Ren.#156
33" Fir bears S 2 1/2°W, 29.7 ft.

188

CENTER 1/4 CORNER SECTION 3.
Set - 1-3/4 x 40" Iron pipe with brass cap.
1/2" x 30" Rebar bears N 73°49'41"E, 1.04 ft.
Rebar replaces 1981 Center 1/4 Corner Monument.
BT's - 1981 bearing tree changes:
A 26" Fir bears N 24°E, 40.9 ft. See Ren#157
19" Fir bears S 88 1/2°W, 22.7 ft.

FD OK BY Daniel Baker 5/93 M118-6

189

Donald Peel L.S. #752
For Davidson Industries Inc.
April 9, 1987 M 103 - 78
Correction of Survey M 89 - 66

Clyde Mulkins
L.S. #2008
For: Sparrow-Pacific
and Richard Holmes
Oct. 30, 1987
M 101 - 31

1/4 Corner for Section 13 only of T.20-12
Found - 1" iron pipe. Ren. #24
Orig. BT, spruce stump with visible scribe marked "BT" bear
S.8°W., 27.1 ft.
Schoolmarm Spruce bears N.50°W., 63.9 ft. (Rec. N.52°W.,
63.1 ft.)
32" Hemlock stump bears S.61°W., 37.0 ft.
Set - 3/4" x 30" rebar and 2" alum. cap
New BTs - 9" fir scribed "1/4 BT" bears N.75°E., 21.8 ft.
6" D. fir scribed "1/4 BT" bears S.23 1/2°W., 4.9 ft.

190

CORNER REPORT ONLY
Section corner for Secs, 5 and 4. Also Secs., 32 and 33 of T 19-11
Found - A 2 1/4" iron pipe with Lane Co. brass cap "1975"
A 53" fir, bears N 73°W, 9.6 ft. - Closed face.
34" fir, bears S 37° E, 10.1 ft. - Opened, scribe visible
(this BT does not fit the calls however, there are 87 yrs.
of undergrowth, thus fixing the time of scribing at the time
of the original survey.

10/30/87

191

Donald Peel
For: Davidson Ind.
Dec. 11, 1981
M 89 - 66