

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T. 20 T. S. R. 11 W. R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 97401

Les Roberts  
For: Int. Paper &  
Champion Int.  
Nov. 1991  
M 114-29, C.S. 63/138

Center 1/4 for Section 22. 211  
Set - 3/4" x 12" aluminum rod with a 3 1/4" aluminum cap. Buried purple  
magnetic marker under 12" aluminum rod.  
BTs - 9" alder, S.04°W., 30.4 ft. Bark scribed "C1/4 S22 BT" Painted red.  
11" alder, N.08°W., 48.2 ft. Bark scribed "C1/4 S22 BT" Painted red.  
18" alder, N.45°E., 66.8 ft. Bark scribed "C1/4 S22 BT" Painted red.  
18" alder, S.66°E., 64.9 ft. Bark scribed "C1/4 S22 BT" Painted red.  
Set a 72" aluminum post, with a land survey monument sign  
attached beside aluminum rod.  
Note - Corner lies on east slope and westerly of two small creeks.  
1/92

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
Feb. 5, 1992  
C.S. File 64/23

Section Corner for Secs. 8, 9, 16 and 17 212  
Found - 2 1/2" dia. 1969 DCSO brass cap on a 1 1/4" O.D. Iron pipe, pro-  
truding 1 ft. above ground. witness corner lies in creek  
bank, leaning west of plumb. Ren. No. 65  
(bearings & distances taken from a point determined as sec. cor)  
30" now 84" dia. Cedar, no blazes visible bears S.41°W., 143.2 ft.  
(agrees with record) Orig. BT.  
23" now 15" dia. 12 ft. high maple snag possible rotted blaze,  
bears S.56°E., 213.8 ft. (agrees with record) Ren. No. 12  
DCSO BC/IP Wit. corner bears South 90.0 ft. (agrees w/rec.) No.65  
Set - At a point determined from bTs and BC/IP W.Cor., Set a 2 1/2"  
dia. DCSO brass cap on a 1 3/8" O.D. x 32" long Iron pipe 12"  
below ground. (Corner lies in open pasture. Cap marked:  
DOUGLAS COUNTY SURVEYORS

T 20 S  
S8 | S9 R  
S17 | S16 11  
1992 W  
OFFICE

Witness Cor. BC/IP returned to plumb position.  
New BTs - 32" dia. Hemlock double blazed and scribed "T20S R11W S8  
CS BT. bears N.20 3/4° W., 401.2 ft.  
18" dia. Alder double blazed and scribed "T20S R11W S9 CS BT"  
bears N.60p°E., 363.6 ft.  
9" dia. Red Cedar double blazed and scribed "T20S R11W S16 CSBT"  
bears S.74°E., 521.1 ft.  
Corner position is in open pasture. A wooden hub & tack was found North  
0.35 ft. from position of corner as we determined,  
2/5/92

Douglas County  
Surveyors Office  
Randall Smith  
Terrie Frannsen  
May 15, 1992  
C.S. 64/26

1/4 Corner for Secs. 10 and 15 213  
Found - 2 1/2" dia. 1969 DCSO brass cap on 1 1/2" O.D. Iron pipe protruding  
2" above ground. Ren. No. 69  
30" now 72" dia. 6 ft. high D.Fir stump, no bark scribing  
visible, bears N.58°W., 29.7 ft. (Orig. BT)(agrees w/rec.)  
48" now 43" dia. D.Fir with a fully healed single blaze, bears  
N.88°E., 178.8 ft. (agrees w/rec.) Ren. No. 69  
48" now 46" dia. D.Fir with a fully healed single blaze, bear  
S.64°E., 184.0 ft. (agrees w/rec) Ren. No. 69  
84" dia. 4 ft. high D.Fir stump with BT tag, with faced  
bark, no scribing visible, tag says "N.84°W., 15.1 ft.  
Stump bears S.80°E., 19.7 ft. (Unrecorded BT)  
New BTs - 18" dia. Hemlock double blazed and scribed "1/4 S10 CS BT"  
bears N.78°W., 5.4 ft.  
18" dia. D.Fir double blazed and scribed "1/4 S15 CS BT"  
bears S.41°E., 16.8 ft.

5/15/92