

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 20 T. S. R. 11 W. R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 91881

John Minor
For: Menasha Corp.
Feb. 1993
M 116 - 56

	1/4 Corner for Sections 19 and 30 Found - 2" Alum. pipe 2" above ground. (CS 51/311). <u>Ren. No. 41</u> . 47" Doug. fir stump N49°W 45.0' (Durham)	219
	New BTs- 17" Doug. fir N70°W 31.1' scribed S1/4 BT 21" Alder S80°E 19.7' bark scribed S 1/4 BT	2/93
	— — — — — Closing Corner for Sections 18 and 19 only. West side. Found - 1½" iron pipe 5.5' above ground. <u>Ren. No. 75</u> . 30" Doug. fir N20°E 52.8' (Org. Unknow) 24" Doug. fir N36°W 55.0' (Org. Unknow) 1½" iron pipe N9°W 36.4' (Org. Unknow)	220 2/93
	— — — — — Section Corner for Sections 13 and 24 T20S R12W only. East side. Found - Two 3/4" Iron pipes side by side. Org. unknow. A 1½" iron pipe is called for in M 22-36. <u>Ren. No. 74</u> . 15" Holly S23°W 44.6' side center. 14" Apple N23°W 34.7', side center. 48" spruce S15°E 48.5' , side center (rec. S17°10'W 48.10')	221 2/93
	— — — — — Closing Township Corner Amended (SW Cor. Sec. 31) Set - 2" Brass cap on 2" iron pipe for amended closing corner. Cap is stamped "T20S R11W S31 CC S6 T21S, T21S S1 R12W 1995 LS 2656" New BTs-12" Alder, N.71°E., 27.7 ft. bark scribed "T20S R11W S31CC BT" 18" Hemlock, S.39°W., 45.3 ft. scribed "S1 BT" 8" Spruce, N.84°W., 28.3 ft. chopped "X" County Surveyor's Brass Cap per C.S. file 54/1 bears N.89°29'E., 4.97 ft.	222
	1/4 Corner for Section 31 and Section 6 T.21-11 Found - 2½" dia. County Surveyor's Office brass cap on a 1½" iron pipe, 8" above ground. (C.S. 59/40) <u>See ren. # 113</u> . 24" D.Fir, S.19°W., 29.4 ft. Healed face. (rec. S.18°W., 29.8 ft.) 19" D.Fir, N.31°W., 18.6 ft. Healed face. (rec. 18.3 ft.)	223
	New BTs- 25" D.Fir, N.52°E., 26.2 ft. scribed "¼ S31 BT" 19" D.Fir, S.78°E., 67.9 ft. scribed "¼ S6 BT"	
	Original closing Township Corner (SW Cor. Sec. 31) Found - 2½" Douglas County Surveyor's Office brass cap on a 1½" iron pipe. (C.S. 54/1) <u>See renewal # 45</u> . 20" Fir stump, N.6°E., 20.4 ft. (rec. 21.1 ft.) 32" Fir stump, S.19°E., 6.7 ft. (rec. S.20°E., 6.3 ft.) Uprooted Fir stump, N.43°W., 18.0 ft. to root hole. (rec. 20.5 ft.)	224
	New BTs - 14" Spruce, S.20°E., 34.5 ft. scribed "T21S R11W S6 CC BT" 13" Alder, N.44°W., 2.5 ft. bark scribed "S1 BT"	
	Original Township Corner (SE Corner Sec. 36, T.20-12) Found - 2½" aluminum pipe (set by Durham in 1964) Menasha records. BTs per C.S. 54/1 - <u>See renewal # 46</u> . 30" Fir snag, S.88°W., 41.6 ft. (rec. S85°W., 40.9 ft.) 22" Hemlock stump, N.15°E. 29.8 ft. (rec. N.15°½'E. 30.1') 38" Fir stump, N.48°W., 42.2 ft. very rotten (rec. 40.1 ft.) Rotten Fir stump, N.5°E., 30.7 ft. scribing visible (rec. N.5½°E., 28.4 ft.)	225
	New BTs - 9" D.Fir, N.39°E., 16.5 ft. scribed "S31 BT" 11" Alder, S.19°E., 20.9 ft. bark scribed "S31 BT" 8" Alder, S.61°W., 21.0 ft. bark scribed "T21S R12W S1 BT" 14" Alder, N.14°W., 10.1 ft. bark scribed "T20S R12W S36 BT"	